[비전인식기반 모듈형 인공지능 로봇 콘텐츠 개발]

6주차

우송대학교 IT센터 응용로봇SW 전임교수 : 황동하 010-2512-6818 mrt2020@daum.net

1. 목표

- 대부분의 인공지능 활용 교육 프로그램이 SW 개발에 치중되어 있어 교육생들의 흥미가 떨어짐
- 로봇과 IoT를 접목한 AI 교육은 실생활 문제를 해결하는데 보다 더 적합하고 교육생들의 만족도도높은 편임
- 그러나, 로봇 구매비용이 수백~수천만원에 이르고 설치 환경도 까다로워 도입 이 쉽지 않은 상황
- 따라서, 한 종류의 모터로 다양한 형태의 로봇 조립이 (바퀴형과 관절형) 가능하고 오픈소스 기반의 아두이노, Pixy 카메라 등을 활용하여 프로그램 확장성이 있는 인공지능로봇 컨텐츠 개발이 필요함

2. 개발내용 및 결과

- 개발 내용
- Pixy2 카메라 접속 모듈 장치
- pixy2의 인식 결과를 SPI통신을 이용하여 전송 받아 콘텐츠를 구현하는 제어 보드 ICM-PA01하드웨어의 제작
- 제어보드는 콘텐츠의 처리 결과를 로봇으로 전달하도록 함
- Pixy2와 ICM-PA01간의 결속을 담당하는 브라켓 구조물 제작
- 개발 결과
 - ICM-PA01을 이용한 로봇 3종 대회(달리기, 장애물 회피, 마라톤) 용 샘플 코드 1종 작성 및 설명서 배포
- ICM-PA01 모듈을 이용한 로봇 제어 강좌 무료 개설 시험 운영
- 강좌를 통해 로봇 3종 대회에 참가 유도



[그림] 개발 결과 로봇 3종 경기 대회 개최

3. 과제결과물

- ICM 모듈 6개
- ICM 모듈기반 로봇 3종 대회 대비용 소스 코드 3종

4. 사업성과

- 기술적 성과
- 로봇의 베이스 제작의 어려움으로 응용 로봇 S/W와 콘텐츠 개발이 뒤처지게 되는 문젯점을 해결 할 수 있는 Secondary Development 모듈을 개발함.
- 향후 다기능 시각용 카메라 모듈과 음성 인식, 출력 모듈을 활용하여 AI의 품 질을 높일 수 있는 방법을 제시 함.
- 경제적 성과
- 고가의 AI 비젼 모델을 대체 할 수 있어 교육 및 취미 활동을 통한 인공지능 로봇 관련 인력의 폭을 넓히는 계기가 됨.
- 교육 현장의 인공지능 로봇 수요에 대처 할 수 있음.

1. 목표 및 추진배경

가. 목표

- 1) 기존의 휴머노이드 로봇 또는 바퀴구동형 로봇 등에 부착하여 활용 가능한 인공지능 기반의 모듈을 개발 하고자 함.
- 2) 아두이노 기반의 마이크로 프로세서를 이용하여 제어 할 수 있도록 함.

나. 추진 배경

1) 기존 휴머노이드 로봇 또는 바퀴구동형 로봇은 단순 리모콘형 이거나 센서에 의존하는 형태가 많음. 리모콘으로 조종하는 형태나 센서에만 의존 하는 로봇 학습 및 활용에 제한이 있음. 이에 AI기반의 시각 인공지능을 탑재한 디바이스의 개발 및 활용을 통해 다양한 방식의 자율형 서비스 로봇으로 활용 할 수 있는 콘텐츠 제작 및 교육이 가능이 가능하게 하도록 함.

다. 산업체와 대학의 산학 공동 진행 필요성

- 1) 개발하는 디바이스 보드로 아두이노 코딩 실습이 가능한 Arduino Nano를 채용하여 교육용으로 활용이 가능하도록 하고자 함.
- 2) 실제 사용하게 될 학생들을 프로젝트에 참여시켜 적응 정도를 파악 하고자 함.
- 3) 실제 학생들이 제작한 응용 SW를 통해 개발 결과물의 확장 가능성을 가늠해 볼 수 있음.

2. 개발 내용 및 결과


가. ICM-PA01의 주요 기능

1) 보드 및 프로세서 정의

- 보드 : 아두이노 호환 ATMEGA NANO

- 프로세서 : ATmega328P(Pld Bootloader)

- 프로그래머 : AVTISP mkII



2) 기능

- 아두이노 IDE를 사용 할 수 있음.
- PIXY2 카메라 모듈의 기능을 모두 사용 할 수 있음.



- PIXY2 카메라 모듈의 Detection 내용을 SPI 통신을 통해 아두이노에 전송 할수 있음.

3) Spec

MCU	ATMEGA328P
Operating Voltage	3.3V, 5V
Input Voltage	3.3V, 5V
Digital I/O pin	6+SPI+UART
DC Current per I/O pin	40mA
Flash Memory	32K of which 0.5KB used by bootloader
SRAM	2KB
EEPROM	1KB
Clock Speed	16MHz

4) ICM-PA01 하드웨어 구성

- 카메라 모듈(앞)과 아두이노호환 제어보드(뒤) 두 보드로 구성 되어 있음.








나. 제작 과정

1) 팀 셋업 및 설계를 위한 외부 전문가 미팅 및 개발 회의




[그림] 팀 구성 및 제작 회의

2) ICM-PA01 컨트롤러 제작을 위한 PCB 회로도 작성 및 회로구성 테스트



[그림] ICM-PA01용 컨트롤러 회로도면



[그림] 동작 시험을 위한 회로 구성과 테스트

ICM-PA01 제품 용도와 특성에 관한 관련 회의를 통해 SPEC을 결정하였음.
ICM-PA01 컨트롤러를 제작 하기 위한 PCB 제작 회로도를 작성 함.
ICM-PA01 컨트롤러의 모든 기능을 구현 가능한지 사전 점검을 위해 회로를 구성하고 기능을 구현 함.

다. 3D디자인(모형 제작)

1) 3D 프린터를 이용한 휴머노이드 제작








[그림] 3D 프린팅한 휴머노이드 모형(움직이지 않음)

로봇에 장착하기 위해 움직이지 않는 3D모형을 제작 휴머노이드 로봇과의

결착성 등을 검증.

- 라. 참여 학생들을 위한 멘토링과 콘텐츠 제작을 위한 교육 내용
 - 1) 실제 동작중인 휴머노이드 로봇에 적용 하기 위하여 로봇의 프로토콜과 동작 번호를 알려주고 로봇에 명령어를 전달하여 동작 할 수 있도록 지도함.



[그림] 실제 동작중인 로봇에의 응용 예시도

- 2) 프로토콜
 - 1. 공통 조건
 - 통신 조건에 다른 지연 시간을 고려하여 전송 속도를 정함.

CONTRO	LLER -	LSM	HOST to	CTRL (Sta	atement)	Packet Total		
Baudrate	bps	115200	PacketSize	byte	12	PacketSize	byte	24
1ByteT	us	86.81	1PacketT	us	1041.67	1PacketT	us	2083.33
			HOST from	m CTRL (F	Response)			
			PacketSize	byte	12			
			1PacketT	us	1041.67			
CONTRO	LLER -	LSM	CTRL to	LSM (Inst	ruction)	Packet Total		
Baudrate	bps	1000000	PacketSize	byte	8	PacketSize	byte	16
1ByteT	us	10.00	1PacketT	us	80.00	1PacketT	us	160.00
			CTRL fro	m LSM (R	esponse)	NumOfLSM	EA	18
			PacketSize	byte	8	1FrameT	ms	2.88
			1PacketT	us	80.00	1FramFeq	Hz	347.2222

- 각 명령을 전달 하기 위한 최소의 시간을 고려한 전송 속도를 확정함.

command	4						EA	18	
CTRL Protocol	:	8	X	EA			=	144	FIXED
Host Protocol	:	command	x	EA	+	12	=	84	ADJ

- 2. 데이지 체인 방식 서보 모터 전송 규약
- LS868 데이지체인 방식 서보 모터 제어를 위한 프로토콜을 이해하고 실제 명령어를 전달하여 개별적으로 또는 그룹으로 동작 하는 방법을 습득하도록 함.
- 프로토콜을 8Byte 구조로 이루어져 있으며 아래와 같음.

Header	Pruduct ID	Module ID	Instruction	Parameter1	Parameter2	Parameter3	CheckSum
Header	0xFF						
	Controller		0x10				
	Display		0x30	+ Model Versi	x1F)		
Pruduct ID	Comm		0x50				
	Sensor		0×70	+ Model Versi			
	Actuator		0XB0	+ Moder versi			
Module ID	Each ID		0~253	0x00 ~ 0xFD			
	BroadCast ID		254	0xFE			
	DATA GET		0x00				
to an order	DATA SET		0x40	+ Instruction	Code (0x00	~ 0x3F)	
Instruction	ACTION		0x80	Control of the contro			
	MSB 2bit : Op	Code		LSB 6bit : Inst	ructionCode		
arameter1~3	Depends on I	nstruction					
CheckSum	(ModuleID +	Instruction +	Prameter1 +	Parameter2 + F	Parameter3)		

- Product ID중 Actuator는 다양한 서보모터를 지원하고 있습니다.

	LSM-micro	0xB0
Pruduct ID	LSM-mini	0xC0
Pruduct ID	LSM-middle	0xD0
	LSM-mega	0xE0

사용예정인 모터는 LSM-micro 버전입니다.

- Module ID 는 0x00부터 0xFD까지 총 253개의 모터를 제어 할 수 있습니다. 전체 모터에 대한 브로드케스트 명령어 전달은 0xFE를 사용할수 있습니다. - 컨트롤러와 각 서보 모터간의 명령어(Instruction Code)에 대한 상세 내용을 이해합니다.

DATAGET	0x00						
DATASET	0x40	+ Instruction Code (0x00 ~ 0x3F)					
ACTION	0x80						
MSB2bit :	OpCode	LSB6bit : InstCode (0~63)					

명령어는 상위(MSB) 2Bit를 이용하여 GET / SET / ACTION을 정함. 다름 하위(LSB) 6Bit를 이용하여 실제 명령어를 전달 합니다.

DATA CET Instruction	OpCode	InstCode		Pac	ket		TXD Direction
DATA GET_Instruction	Opcode	instcode	Instruction	Parameter1	Parameter2	Parameter3	TAD Direction
C-t M-dul- ID		4.	0x01	0	0	0	CTRL → LSM
Get Module ID		1	0x01	0	Module	ID (Note.1)	LSM → CTR
Get Now Position		2	0x02	0	0	0	CTRL → LSM
Get Now Position		2	0x02	0	Now Posi	tion (Note.2)	LSM → CTF
Cat Town I Berlin		3	0x03	0	0	0	CTRL → LSM
Get Target Position		3	0x03	0	Target Pos	ition (Note.2)	LSM → CTF
Get Now Current		4	0x04	0	0	0	CTRL → LSM
Get Now Current		4	0x04	0	Now Current	[mA] (Note.3)	LSM → CTF
Get Limit Current		5	0x05	0	0	0	CTRL → LSM
Get Limit Current		5	0x05	0	Limit Current	[mA] (Note,3)	LSM → CTF
C d No. Townstown		-	0x06	0	0	0	CTRL → LSM
Get NowTemperature		6	0x06	0	Now Temperat	ure [°C] (Note.4)	LSM → CTF
Cat Limit		7	0x07	0	0	0	CTRL → LSM
Get LimitTemperature		,	0x07	0	Limit Temperat	ure [°C] (Note.4)	LSM → CTF
Cat Calla B			0x08	0	0	0	CTRL → LSM
Get Gain P		8	0x08	0	Gain F	(Note.5)	LSM → CTF
CA CALL		9	0x09	0	0	0	CTRL → LSM
Get Gain I		9	0x09	0	Gain I	(Note.5)	LSM → CTF
	1	40	0x0A	0	0	0	CTRL → LSM
Get Gain D	0.00	10	0x0A	0	Gain D	(Note.5)	LSM → CTF
C. C. C. Marrie	UXUU	0x00	0x0B	0	0	0	CTRL → LSM
Get Control Margin		SEL	0x0B	0	Control M	argin (Note.6)	LSM → CTF
Get ForwardControl Value		12	0x0C	0	0	0	CTRL → LSM
Get ForwardControl Value		12	0x0C	0	Forward Contr	ol Value (Note.7)	LSM → CTF
C-1 1/-11		24.50	0x0D	0	0	0	CTRL → LSM
Get Voltage		13	0x0D	0	Voltage [i	mV] (Note.8)	LSM → CTF
Cat Barredon Marri		14	0x0E	0	0	0	CTRL → LSM
Get Boundary Max		14	0x0E	0	Boundary	Max (Note.9)	LSM → CTR
Cat Barradan Min		45	0x0F	0	0	0	CTRL → LSM
Get Boundary Min		15	0x0F	0	Boundary	Min (Note.9)	LSM → CTR
CHIED WILL		46	0x10	0	0	0	CTRL → LSM
Get LED Value		16	0x10	Value R (Note.10)	Value G (Note.10)	Value B (Note.10)	LSM → CTR
Get Model Version		47	0x11	0	0	0	CTRL → LSM
Get Model Version		17	0x11	0	Model Ver	sion (Note.11)	LSM → CTF
C-t DWV		40	0x12	0	0	0	CTRL → LSM
Get FW Version		18	0x12	0	FW Versi	Off (Note, 12)	LSM → CTF
			0x13	0	0	0	CTRL → LSM
Get Comm Baudrate		19	0x13	Comm	Baudrate [BPS]	(Note.13)	LSM → CTR
			0x14	0	0	0	CTRL → LSM
Get ZeroCompValue		20	0x14	0	ZeroComp\	/alue (Note.14)	LSM → CTR

[그림] 데이터 읽기 명령어 전송과 응답과정 - 양방향 통신

DATA CET	Opcode	InstCode	No. of the second	Pac	ket		TXD Direction
DATA SET_Instruction	Opcode	ilistcode	Instruction	Parameter1	Parameter2	Parameter3	TAD DIRECTION
Set Factory Reset		0	0x40	0x53	0x46	0x52	
Set Module ID		1	0x41	x	New II) (Note.1)	
Set Sync Target Position		2	0x42	Sync Tq/Spd	SyncTarget P	osition (Note.2)	
Set Sync LED Control Value		3	0x43	Value R (Note.10)	Value G (Note. 10)	Value B (Note.10)	
Set Limit Current		4	0x44	х	Limit Current	[mA] (Note.3)	
Set Limit Temperature		5	0x45	x	Temperature [°C] (Note.4)		
Set Gain P		6	0x46	x	Gain F	(Note.5)	
Set Gain I	0x40	7	0x47	×	Gain I (Note.5)		CTRL → LSM
Set Gain D		8	0x48	x	Gain D (Note.5)		
Set Control Margin		9	0x49	x	Control M.	argin (Note.6)	
Set ForwardControl Value		10	0x4A	x	Forward Contr	ol Value (Note.7)	
Set Boundary Max		11	0x4B	x	Boundary	Max (Note.9)	
Set Boundary Min		12	0x4C	x	Boundary	Min (Note.9)	
Set Comm Baudrate		13	0x4D	Comm	Baudrate [BPS]	(Note.13)	
Set ZeroCompValue		14	0x4E	х	ZeroComp\	alue (Note.14)	

[그림] 단방향 데이터 셋팅 명령어

ACTION	Opcode	InstCode		Pac	ket		TXD Direction
ACTION_Instruction	Opcode	mstcode	Instruction	Parameter1	Parameter2	Parameter3	TAD DIRECTION
EEP PROG Config Data	8 8 8 8 8 8	1	0x81	1	2	3	7
Action Move T_Position		2	0x82	Torque	Target Pos	ition (Note.2)	
Action Move S_Position		3	0x83	Speed	Target Pos	ition (Note.2)	
Action LED Control		4	0x84	Value R (Note.10)	Value G (Note.10)	Value B (Note.10)	
Action Sync Move Position	0x80	5	0x85	1:Torq/2:Spd	1	1	CTDI LIENA
Action Sync LED Control	UXOU	6	0x86	1	1	1	CTRL → LSM
Action Wheel Mode		7	0x87	1:CW/2:CCW	Wheel Speed	[96] (Note.15)	
Action Active Stop		8	0x88	×	×	×	
Action Passive Stop		9	0x89	×	×	×	
en de vide komen et et kindelijk en een vide van en een		nichasendislevas ali		Marian and the second	en e		

[그림] 단방향 Action Instruction

No	Item	Unit	Range	Code	Product Default	Factory Reset Value
1	ID	34	0~253	2byte U_Int		0
2	Position	12	-500 ~ 500	2byte Int	Center Positin 0	
3	Current	[mA]	0~1000	2byte U_Int	Limit Current 1000	Limit Current 1000
4	Temperature	[°C]	0~80	2byte U_Int	Limit Temperature 60	Limit Temperature 60
5	Gain PID	-	Each 0~254	2byte U_Int	P:40 / I:0 / D:30	P:40 / I:0 / D:30
6	Control Margin	2	0 ~ 1000	2byte U_Int	0	0
7	Forward Control Value	12	0 ~ 1000	2byte U_Int	40	40
8	Voltage	[mV]		2byte U_Int	-	
9	Boundary Min/Max	-	-500 ~ 500	2byte Int	Min:-S00 / Max:500	Min:-500 / Max:500
10	LED RG8	- 1	0~250	2byte U_Int		
11	Model Version	- 2	2	2byte U_Int	0x80	0xB0
12	FW Version	72	20	2byte U_Int		
13	Baudrate	[BPS]	2400~1000000	3byte U_Int	1000000	1000000
14	ZeroCompValue	- 1	-12 ~ 12	2byte Int		0
15	Wheel Speed	[96]	0 ~ 100	2byte U Int	26	4

[그림] 각 파라메타의 값 범위

3. 아두이노와 통신을 위한 UART 통신 규약

acket Size :	12 Byte ~ (12	2+[N]) Byte	Header 4 byte		n Address yte		Address byte		ement byte	Para Length 1 byte	Parameters Length [N] byte	CheckSum 1 byte
	Header1	0xFF		Destination	CtN	Addr H	Each Addr	BroadCast	i e			
Header	Header2	0xFF		Address	dress Controller	Addr L	1~65535	0				
neader	Header3	0x4C		Source	Host	Addr H						
	Header4	0x53		Address	nost	Addr L						
Statement	Statement1	Туре		Length	Para Length	Length [N]	w n1-					
Statement	Statement2	Code		Para	Parameters	[N] byte # Depends on Si		on Statement				
CheckSum	= Src/	Addr H + SrcAdd	r L + Statemen	t1 + Statement2 -	Length (+ Para	11 + Para + Pa	raN)					

[그림] 통신 규약 UART

- 통신 규약은 115200bpx의 속도를 갖는 12Byte ~ (12 + n) Byte의 길이로 정의 되었음.
- Header는 반드시 지켜야 함.
- Destination Address와 Source Address는 0x00으로 채워도 무방함.
- Statement는 두가지로 구성됨

Statement	Statement1	Type
Statement	Statement2	Code

- Para Length는 실제 파라메타의 개수를 기록함.

Length	Para Length	Length [N]	· ≫Depends on Statement
Para	Parameters	[N] byte	»Depends on statement

- Checksum은 아래 표에 기술된 각 필드의 값을 모두 Or 연산한 값.

CheckSum = SrcAddr H + SrcAddr L + Statement1 + Statement2 + Length (+ Para1 + Para... + ParaN)

- State의 구성 요소는 **Type**와 Instruction **Code**로 2Byte로 구성 되어 있음.

	DATA GET	0x10
Tymo	DATA SET	0x20
Туре	EXECUTION	0x30
	Files Management	0x40

[그림] UART통신 프로토콜 Type 유형

- Data Get Code의 명령어 처리 순서

DATA CET	Direction \ Packet	Header	Dest Addr	Src Addr	Statement	Length	Parameter N	CheckSum
< DATA GET > Process	HOST LSC (Command)	Header	LSC Addr	HOST Addr	Statement	Parakength	Para	PHAREINY .
Frocess	LSC » HOST (Response)	Header	HOST Addr	LSC Addr	Statement	RespParaLength	RespRara	CheckSum

[그림] Data Get Code의 명령어 처리 Process

- Data get Code 의 상세 명령어

DATA GET	Type	Code	Para Length	Para1	Para2	Para3	Para4	Para5	Para6	Para7	Para8	Para9	-111
Get LSC Version		1	0										
Get LSC version			3	HW Version	FW Major	PW Minor							
Get BAT Voltage		2	0										
Get BAT Voltage		2	2	BAT VoltageH	BAT VoltageL								
Get Module ID		3	0	E. I									
(only 1EA Connected)		3	[A]	LSM ID									
C. M		4	117	Last ID									
Set Nbr of LSM(Connected)			1	NumberOfLSM									
Colection and account of the colection		4	INJLSMs	LSM ID_1st		LSM ID (N-1)th	LSM ID Nith						
Get LSMs NowPosition		5	INDLSMs x 3	ID_fist	ID_Tst PosH	ID_hit Post.	W	iD_fN[th	ID Jivjin Positi	ID (Nith Post.			
200220300000000000000000000000000000000		1 8	INILSMs	LSM (D. fat		LSM ID (N-1)th	LSM ID (N)th						
Get LSMs NowVoltage		6	INJLSMs x 3	ID 1st	ID_Tst Votte	ID_Tot Volts.		ID (N)th	ID PARTS VOICE:	ID_INIT Vols.			
		7	INILSMs	LSM ID 1st		LSM ID IN-11th	LSM ID INIth	1		1071020			
Get LSMs NowCurrent		7	BNJLSMs x 3	ID 1st	ID_1st NowCurri	ID_1st NowCurt.		iD_(N)th	ID_INITH NOWCUTH	ID (NIT) NowCurt.			
20022002000 0		2	(N)LSMs	LSM ID 1st	- 22	LSM ID (N-1)th	LSM ID (Nith						
Get LSMs LimitCurrent		8	INJLSMs x 3	ID 1st	ID: 1st LimCurti	IO Tet invited.		ID (Mith	ID INITA LINCUITH	ID PART LINGUIS			
		6	INILSMs	LSM ID 1st	- In the section pro-	LSM ID IN-11th	LSM ID INIth	1000000	THE RESERVE OF THE PARTY OF THE	To Wast Man			
Get LSMs NowTemperature		9	BNILSMs x 2	ID 1st	ID 1st NowTemp	- 14	ID INith	ID that NowTemp					
Annaba (Congly 1982 AV		1098	INILSMs	LSM ID 1st		LSM ID IN-11th	LSM ID (N)th						
Get LSMs LimtTemperature		10	INILSMs x 2	ID 1st	iO Tel LintTemp		ID INIth	ID_INIT IntTemp					
		8	INILSMs	LSM ID 1st	27-210-00-00-0	LSM ID IN-13th	LSM ID INJuh	THE REAL PROPERTY.					
Get LSMs GainP		11	BVILSMs x 2	ID 1st	ID 1st GainP	77.2	ID INjth	ID_Pilm GainP					
435100F8223080533	0x10	7 2558	(N)LSMs	LSM ID 1st		LSM ID (N-1)th	LSM ID (N)th						
Get LSMs Gainl		12	INJLSMs x 2	ID 1st	ID 1st Gaini		ID INIth	ID_Mth Garni					
		***	INILSMs	LSM ID 1st		LSM ID IN-11th	LSM ID INIth	TT-6 260 2700					
Get LSMs GainD		13	BVILSMs x 2	ID 1st	ID_1st GainD		ID INith	ID_PIJIT GaIND					
SANDERALAN LIANCE PINES NO			INILSMs	LSM ID 1st		LSM ID IN-17th	LSM ID (N)th	a grant and					
Get LSMs ControlMargin		14	INILSMs x 3	ID 1st	ID Tet CM H	ID 1st CM L	2207 22 (19)011	ID (Mith	ID_PAID CM H	ID INTO CMS			
		£	INILSMs	LSM ID 1st	Section Control	LSM ID IN-11th	LSM ID INIth	10,19901	SEATON CONTRACTOR	and the same			
Get LSMs FwdControl Value		15	INILSMs x 3	iD 1st	ID 1st RCVH	ID 1st FCV L	Law ID, Jrejin	iD INith	ID_Mgb RVH	ID INTO FCV L			
contraction of the contraction		T Seesa	INILSMs	LSM ID 1st	D BIRLY H	LSM ID (N-1)th	LSM ID-(N)th	: to steps	ID SHIP CONT.	and independent			
Get LSMs BoundaryMax		16	INILSMs x 3	ID 1st	ID_TIST BNDMX H	ID_1d BNDM(L	case of halle	ID fNith	IO_DVIDE BNIDMENH	ID INTO SNOWL			
		de la companya della companya della companya de la companya della	INILSMs	LSM ID 1st		LSM ID IN-11th	LSM ID INIth	LD, popul	SOLDERY GREAT	in Judiu account a			
Get LSMs BoundaryMin		17	PVILSMs x 3	iD 1st	ID Tet BNDMN H	ID 1st BNDMN L	Law to jirijan	iD INith	ID JINDS SNOWN H	ID INITI BNOWN L			
		7 0-40	[N]LSMs	LSM ID 1st		LSM ID IN-17th	LSM ID (N)th	: ID-Stellin	10_grape and set in	ID SHIP GALLANIA C			
Get LSMs LED Value		18	INJLSMs x 4	LSM ID Titl	ID TISTLED R	ID THIEDG	ID Tet (ED 8		LSM IO PVIIIN	ID INITIALED R	ID DVID LED G	ID INTO LED 8	
			INILSMs	LSM ID 1st	THE COURT OF THE C	LSM ID IN-13th	LSM ID Nith		DW30 PAPA	IU_MIN EUX	SO THE PERSON	in lulu mas	
Get LSMs ModelVersion		19	PULSMS X 3	iD 1st	ID 1st MV H	ID_1st MV L		iD (N)th	ID_INgts MV H	ID INJE MV L			
ACT OF STATE		7	INILSMs	LSM ID 1st			LSM ID (N)th	: IU- (IV)tin	IN AM URBITAL	ED_DRIPS MV C.			
Get LSMs FW Version		20			in vanio	LSM ID (N-1)th	110.001	ID (Nith					
		72	INILSMs x 3	ID_1st	IO_TGFVH	ID_1st FV L	1010 201	ID JIVIT	ID_N(h FVH	ID_IN(th PV L			
Get LSMs ZeroCompValue		21	[N]LSMs	LSM iD_1st	a var dibenos	LSM ID N-1)th	LSM ID, Mith		100000000000000000000000000000000000000				
		F 853	INJLSMs x 3	iD_fat	ID_1st ZCPMH	ID_1st ZCMP L		iD_[N]th	ID Shifts 20MP H	ID_DIJIN ZCMF L			
Get Sync Info		22	, 1/	넘어칠때요선변호									
		Succession Company of	2	모선병호	포즈벤트								

- Data set Code의 상세 명령어

DATA SET	Type	Code	Para Length	Para1	Para2	Para3	Para4	Para5	Para6	Para7	Para8	Para9	#
Set LSC Version		1	3	HW Version	FW Major	TW Minor							
Set LSC Address		2	2	Address H	Address L								
Set LSM Module ID		3	2	ESM ID	new LSM (D)								
Set Sync Target Position		4	N0.5M: x 4	LSM/SynctD_Sst	10,1st3ysc1/5	ID, 1st Synchose	10, 1st Synchosi.	5=	LSM Syncia (New	ID_INITE SYNCT/S	ID, Mith Synchosel	ID_(Nth Synchos).	
Set Sync LED Control Value		5	NILSMx 4	USM SynctD_14th	ID_1612DpaR	10,14130peG	ID, for GED pink		LSM Syscial India	ID, PRIN LED JOHN.	ID.JN(th SEDpwG	ID, MITH SEEpard	
Set LSM Limit Current		6	NILSMs s 3	10,1st	ID_fat (mCure)	10, he incurs	-	ID (Not)	10 JMIN LINCUM	ID_INITE LHOUSE			
Set LSM Limit Temperature		7	1NJLSWs x 2	ID_Ns	ID terunetemp		ID 349th	IQ_P(th LntTemp					
Set LSM GainP		8	INSLSML x 2	ID,1st	ID_1st Gain?	125	ID_N8th	ID_POh Garie					
Set LSM Gainl		9	NILSVh x 2	D,1st	ID,1d Sans		(D_74)th	ID SIRTS GOIN!					
Set LSM GainD	0x20	10	NJLSMs x 2	© 1st	(b) tet San D	-	(D,7N(th	ID_INth Gand					
Set LSM Control Margin	All States of the	- 11	INILSMs x 3	ID, 1st	ID_3etCMH	IQ 3st CML	21	ID (NBh	ID_N(th CM H	ID_3N(m CM L			
et LSM ForwardControl Value		12	INILSMs x 3	ID, tst	(D)3d KVH	10,7459071	23	(D) Night	ID JRID KVH	ID, JUJO-HOVA			
Set LSM Boundary Max		13	INILSMx x 3	©,1st	10,1st8NDN8XH	ID THE BROWN IS		ID N/h	HAMONE WOLCO.	D, JNJIN SNOW; L			
Set LSM Boundary Min		14	NILSMs x 3	(D) fst	ID, NY BROWN H	IO, NEBROWN),		© Nith	C'UNER BYDNINE	OUNT INDMIL			
Set LSM Comm Baudrate		15	MLSMx x 4	ID;1st	ID, fat 8F5 H	ID,168P5.M	0.16851	-	ID Men	10 (Figh 875.H	ID INSH BTS M	(0,00m 875 L	
Set LSM ZeroComp Value		16	INILSMs x 3	ID; fet	ID,1st2096H	10,1425MF1		(D_3N)th	ID_IN(th ZEMP H	ID_(N(th.2XMP.L			
Set LSM Factory Reset		17	4	LSM ID	0:53	0x46	0x52						
Set LSS Module ID		18	- 3	Product ©	L55 (D	new LSS ID							


- Data Execution Code의 상세 명령어

EXECUTION	Туре	Code	Para Length	Paral	Para2	Para3	Pare4	Para5	Para6	Para7	Para8	Para9	***
Exe LSM PWR ON/OFF		1	1 1	QOFF / HON									
Exe LSM Configure Save		2	INLSMs	LSM ID 1st		LSM ID 3N(sh							
Exe LSM PosMove Torq		3	INILSMs x 4	USM ID, Tel	ID, 1st Torque	10,1st Foot	10,1st Foxi.	14	LSM ID (NIII)	ID Stem Torque	(C) (N(8) FOSH	ID (N)th Post.	
Exe LSM PosMove Speed		4	IN/L9Vn x 4	USM 10-3 of	IQ:TistSpeed	10,3st PoH	10,14766	- H	HIM D INTO	IQ_P(m Speed	ID, JNJth PosH	ID, JNJth Fox.	
Exe LSM LED Control		5	IVILSMs x 4	13M10_1st	ID, for LED R	10,14:004	0,14408	-	LSM ID JMIN	(0,)N(m (40 %	DIMINUDE	ID_PMM LED B	
Exe LSM Sync PosMove		6	NILSMs x 2	LSM ID 1st	10_1stSyncMade	_	LSM ID DOW	ID Jildh Syndhole					
Exe LSM Sync LED Control		7	(N)LSMs	LSM ID, 1st		LSM ID (Non)							
Exe LSM Integration Control	0x30	8	(N)L5Ms x 7	USMID, Set	(Q,1st forque	ID, Tilt Poort	10,517,016	10,7erus0 ft	10,141406	10,1440.6	946		
Exe LSM Wheel Mode		9	IVILSMs x 3	ISM10,1st	ID, NI DOCKROCKS	ID, ht WSpd(%)		SMIO, Nm	0 metaconicos	(O_Pkth Whipd(%)			
Exe LSM ActiveStop		10	INILSMs	LSM ID 1st		LSM ID: Noh							
Exe LSM PassiveStop		11	INILSMy	LSM ID_fst	_	LSM ID North							
Exe Motion		12	3	MotionNumber	Start delay [mi]	Speed(-50-50(%)							
Exe Process		13	1	OOFF / NON									
Exe Remocon		14	4	mode	GOFF / 10N	L data	R data						
Exe Motion info		15	2	MotionNumber	PosNumber								

- 사용 예시

A STATE OF THE PARTY OF THE PAR		-	ATTACAS .	01001	100000	30077-71	III SUCCESSIVE	100000	19780781	10000	id 2	torg 80		on -100	2-711-72-71
DxFF	0xFE	0x4C	0x53	0x00	0x00	0x00	0x00	0x30	0x03	0x04	0x02	0x50	Oxff	0.9c	CheckSum
osition contro	di .	: ID[2] LSM P	osition '-100'	with torge 809	6										
											id 3	250	0	0	
0xFF	OxFF	0x4C	0x53	0x00	0x00	0x00	0x00	0x30	0x05	0x04	0x03	Onfo	0x00	0x00	CheckSum
LED control		: ID[3] LSM R	led LED On												
								type	code	para length					
0×FF	0xFF	0x4C	0x53	0x00	0x00	0x00	0x00	0x30	0x0C	0x03	MotionNumber	0×00	0x00	CheckSum	
Exe Motion															

- 컨트롤러에 저장된 3번 모션을 실행 하는 명령어 완성본



[그림] 통신 내용을 캡춰

- 리모콘 앱에서 수신되는 신호에 따른 동작 Process 예신



[그림] 리모콘 앱에서 수신되는 신호에 따른 명령어 처리


- Data File Management Code의 상세 명령어는 모션 데이터 파일을 전송할 때사용함.

Files Management	Type	Code	Para Length	Para1	Para2	Para3	Para4	Para5	Para6	Para7	Para8	Para9	
Write PROCESS		1	6	PlatformH	PlatformL	FileSize 1	FileSize 2	FileSize3	FileSize4				
	0.40												
	UX40												

1.	HOST > LSO	(Comm	and)															
		Н	eader		Dest	Addr	Source	e Addr	State	ment	ParaLength			CheckSum				
	OxFF	OxFF	0x4C	0x53	LSC AddrH	LSC AddrL	Host AddrH	Host AddrL	0x40	1	6	PlatformH	PlatformL	FileSize 1	FileSize 2	FileSize3	FileSize4	CheckSum
														(MSB)			(LSB)	
2.	LSC » HOS	(Respo	nse)															
		Н	eader		Source	e Addr	Dest	Addr	State	ment	ParaLength			Pa	ara			CheckSum
	OxFF	OxFF	0x4C	0x53	Host AddrH	Host AddrL	LSC AddrH	LSC AddrL	0x40	1	6	STATUS 1	STATUS 2	FileSize 1	FileSize 2	FileSize3	FileSize4	CheckSum
														(MSB)			(LSB)	
3.	HOST > LSO	(File Tr	ansfer : Max 64	byte)														
	Filedata[1]	220.5	Filedata[64]															
4.	LSC » HOS	(Respoi	nse : Received I	byte Countl	Nbr)													
	64 (0x40)																	
5.	HOST » LSC	(File Tr	ansfer : Max 64	1 byte)														
	Filedata[65]	220	Filedata[129]															
6.	LSC » HOS	(Respon	nse : Received I	byte Countl	Nbr)													
	64 (0x40)				7,000													
7.	HOST » LSC	(File Tr	ansfer : Max 64	1 byte)														
	Filedata[130]	25.5	Filedata[140]															
8.	LSC » HOS	(Respoi	nse : Received I	byte Countl	Nbr)													
	10 (0x0A)																	

[그림] 모션 데이터 파일 전송 규약의 프로세스

4. 종합 서비스 설계



[그림] 콘텐츠 제작을 위한 종합 서비스 개념도

- 로봇의 모션 테이블

기존에 판매 중인 휴머노이드 로봇은 컨트롤러에 기본적으로 저장된 모션 테이블을 갖고 있다.

앞서 살펴본 프로토콜에 의해서 전송된 모션 번호에 따라 로봇은 정해진 모션을 순차적으로 실행 하도록 되어 있다.

			M	otio	n Table					
MRT R&D	Cent	er				(ver. 2019.04.30)				
Motion	1	Mode	М	otion	Voice Command	Remark				
Index No.	No	Name	Des1	Des2	Voice Command	Remark				
	1		Ready		Ready					
2	2			ST						
3	3		F	Loop	Go Forward					
4	4			End						
	5		Left		Go Left					
(5		Right		Go Right					
	7		Turn	L	Turn Left					
8	3		Turn	R	Turn Right					
9	9				ST					
10	0		В	End	Go Backward					
11	MO	Basic		Loop						
12	2		L	Forward	Left Forward					
13	3	*					R	Forward	Right Forward	
14	4								Getup	F
15	5		Getup	В	Getup backward					
16	5		Losw1		lose					
17	7		Win1		champion					
18	3		Hi		Hi					
19	9		Bow1		bow					
20)		Tumble	F	Tumbling forward					
	-									

[그림] 로봇 제조사의 컨트롤러에 기본 내장된 모션 21개

Tumble B Tumbling backward

- ICM-PA01의 기본 예제 제작

아래 코드는 PIXY2 카메라에서 지정한 Sig1번 색상을 가진 물체를 감지하였을 때 아두이노에서 어떻게 반응하는가를 알아 보는 기본적인 소스 코드이다.

```
#include <Pixy2.h>
// This is the main Pixy object
Pixy2 pixy;
void setup()
 Serial.begin(115200);
 Serial.print("Starting...\n");
 pixy.init();
void loop()
 int i;
 // grab blocks!
 pixy.ccc.getBlocks();
 // If there are detect blocks, print them!
 if (pixy.ccc.numBlocks)
   Serial.print("Detected ");
   Serial.println(pixy.ccc.numBlocks);
   for (i=0; i<1; i++) // 여러개의 Bolock 정보 가운데 1번째에 해당하는 내용만 사용함.
     Serial.print(" block ");
     Serial.print(i);
     Serial.print(": ");
     pixy.ccc.blocks[i].print();
   pixy.setLamp(255,0); // 어떠한 물체라도 찾아 냈을 경우 위쪽 좌우의 2개의 램프를 점등
 }
 else
   pixy.setLamp(0,0); // 위쪽 좌우의 2개의 램프를 소등
 }
 delay(100); // 수시로 점등/소등이 되지 않도록 하기 위해서 약간의 딜레이를 준다.
```

- ICM-PA01의 방향 감지와 방향 전환용 코드

```
#include <Pixy2.h>
Pixy2 pixy;
void setup()
 Serial.begin(115200);
 Serial.print("Starting...\n");
 pixy.init();
void loop()
 pixy.ccc.getBlocks();
 if (pixy.ccc.numBlocks)
   Serial.print("Detected ");
   Serial.println(pixy.ccc.numBlocks);
   for (int i=0; i<1; i++) // 여러개의 Bolock 정보 가운데 1번째에 해당하는 내용만 사용함.
     Serial.print(" block ");
     Serial.print(i);
    Serial.print(": ");
    pixy.ccc.blocks[i].print();
   pixy.setLamp(255,0); // 어떠한 물체라도 찾아 냈을 경우 위쪽 좌우의 2개의 램프를 점등
   // 카메라의 전체 화소는 320 x 240 임
   // 카메라의 중심은 160임
   // 물체의 중심이 100 보다 작으면 왼쪽
   // 물체의 중심이 100 ~ 220에 있으면 중앙에 있다고 봄
   // 물체의 중심이 220보다 크면 오른쪽에 위치 하고 있다고 봄
   if (pixy.ccc.blocks[0].m_x < 100) // 감지 물체의 중심이 카메라의 중앙 보다 왼쪽에 위치
   {
      // 왼쪽으로 턴
   else if (pixy.ccc.blocks[0].m_x > 220) // 감지 물체의 중심이 카메라의 중앙 보다 왼쪽에 위치
      // 오른쪽으로 턴
  }
   else
      // 앞으로 전진
   }
 }
 else
  pixy.setLamp(0,0); // 위쪽 좌우의 2개의 램프를 소등
 delay(100); // 수시로 점등/소등이 되지 않도록 하기 위해서 약간의 딜레이를 준다.
```

```
#include <Pixy2.h>
Pixy2 pixy;
// 로봇 모션을 정의한 테이블 번호와 동일함.
enum {
 STOP
               = 0,
 M0_Ready
               = 1,
 M0_F_ST
               = 2,
             = 3.
 M0_F_Loop
 M0_F_End
               = 4,
 M0_Left
              = 5,
 M0_Right
              = 6,
 M0_Trun_L
               = 7,
  MO_Turn_R
  M0_B_ST
               = 9,
 M0_B_End = 10,
             = 11,
  M0_B_Loop
  M0_L-Forward = 12,
  M0_R-Forward = 13,
  M0_Getup_F = 14,
 M0_Getup_B = 15,
 M0_Losw1 = 16,
 M0_Win1
             = 17,
 M0_Hi
              = 18,
 M0_Bow1
               = 19.
 M0_Tumble_F = 20,
 M0_Tumble_B = 21,
void initialize(void)
 //Serial.begin(115200);
 //LED pin setting
 pinMode(3, OUTPUT);
 pinMode(5, OUTPUT);
 pinMode(6, OUTPUT);
 pinMode(7, OUTPUT);
 //RGB LED initialize
  digitalWrite(3, HIGH);
                         //Blue(Active low)
  digitalWrite(5, HIGH);
                         //Green(Active low)
 digitalWrite(6, HIGH);
                         //Red(Active low)
 //LED initialize
 digitalWrite(7, HIGH);
                          //Active high
 delay(1000);
                          //Waiting for init Line Core M
void setup()
 Serial.begin(115200);
 Serial.print("Starting...\n");
 initialize(); // ICM-PA01 보드의 램프를 사용하기 위하여 초기화 함.
  pixy.init();
```

```
// 로봇 제어와 ICM-PA01의 RGB LED를 제어 하기 위한 함수
void sendData(unsigned char data, unsigned int r, unsigned int g, unsigned int b)
 if (data >= M0_Ready && data <= M6_Getup_B) Serial.write(data);
 analogWrite(3, 255-b);
                             //Blue(Active low)
 analogWrite(5, 255-g);
                            //Green(Active low)
 analogWrite(6, 255-r);
                           //Red(Active low)
void loop()
{
 int i;
  pixy.ccc.getBlocks();
 if (pixy.ccc.numBlocks)
   for (i=0; i<1; i++)
     // Block's x is left
     if(pixy.ccc.blocks[i].m_x < 80){
       if (beforeCenter){
         beforeCenter = 0;
         sendData(M0_F_End); delay(500);
        sendData(M0_Trun_L);
       atFirst = 1;
     // Block's x is right
     else if(236 < pixy.ccc.blocks[i].m_x){
       if (beforeCenter){
         beforeCenter = 0;
         sendData(M0_F_End); delay(500);
        sendData(M0_Turn_R);
        atFirst = 1;
      // Block's x is centre
     else if(80 <= pixy.ccc.blocks[i].m_x <= 236){
        beforeCenter = 1;
        if (atFirst){
          sendData(M0_F_ST); delay(300);
         atFirst = 0;
        sendData(M0_F_Loop); delay(300);
     }
   }
 }
```

마. 소결

학습한 Protocol을 교육하고 만들어진 ICM-PA01모듈을 이용하여 실제 로봇을 움직이도록 하는 체험을 통해 참여 학생들을 대상으로 과제의 결과물을 활용한 다양한 실험을할 수 있도록 하여 콘텐츠 개발과 대회 참가등의 성과를 낼 수 있도록 함.

3. 과제 결과물


가. 시제품

- 제작 기획을 하면서 기존의 휴머노이드 로봇과 바퀴 굴림형 로봇등에서 활용 할 수 있는 독립적인 컨트롤러기능을 하는 인공지능 시각 처리 모듈을 제작함.



[그림] ICM-PA01 최종 결과물 상세

- 결과물은 제작의도와 도면에 맞게 제작 되었으며 실제 휴머노이드 로봇에 장착하여 테스트를 하였음.



[그림] 왼쪽 최종 결과물과 휴머노이드와 결합 사용 예

2) 제품의 용도와 특성

。 용도 :

- 단순 리모콘형 이거나 센서에 의존하는 휴머노이드 로봇 또는 바퀴 굴림 로봇에 AI기반의 시각 인공지능을 탑재한 디바이스 ICM을 만들어 추가함으로서 자율형 서비스 로봇으로 활용 할 수 있는 콘텐츠 제작이 가능.
- 아두이노 코딩 실습이 가능한 Arduino Nano를 채용하여 교육용으로 활용 할 수 있음.
- 국제 로봇 3종대회(달리기, 장애물 회피, 마라톤)와 같은 로봇 첼린지에 출전 할수 있는 샘플 코드를 제공하여 참가의 기회를 제공.

• 특성 :

- 2개의 PCB를 연결하는 브라켓 구조물을 추가 하여 완성도를 높였음.
- 로봇의 머리 부분과 ICM-PA01의 접결은 4pin 커넥터로 처리하여 완성도 높임











