Install keil and kit drivers:

http://edx-org-utaustinx.s3.amazonaws.com/UT601x/download.html?fbclid=lwAR1gYYGRg3iz3uXoDXmVXHrz106Jf8dgGKQ-v4YiZ-d7MXhZQWGFKacbO1q

Download and install TivaWare for C Series Software (Complete) http://www.ti.com/tool/SW-TM4C

Download The LaunchPadDLL and Place this in \Keil\ARM\BIN folder (To be able to run simulation mode)

How to make a new project in Keil:

https://www.youtube.com/watch?v=X-4RVXqmqks

To use Keil Tiva C Simulator add "-dLaunchPadDLL" in Options for Target -> Debug:

