

Baker Hughes

H0J1364100

Work Order# : 109359307

WO Qty.: 4

Criticality :

Material# : H0J1364100CEOW

QRD UPR CRG BMS-N235

Type : PP01

BMS : BMS-N235 -

Batch# :

Q2/Q3 : BAKER Q2 QUAL LVL

WO: Í*} [> È 7 Î

MN: JÇ-`*È0CEO\

Batch:

Op No.	Work Center	Plant	Control Key	StdText	Operation short text	Long text	GOOD QTY	REJ QTY	COMPLETE	Comments (QN, etc.)
10	WRAW	0003	PP01	GWH07	PULL RAW MATERIAL					
15	SAWI	0003	PP01	GS002	SAW	Yes				
20	QCHVM	0003	PP01	GT007	CHECK HARDNESS AND VERIFY MTR	Yes				
30	NX4A	0003	PP01	GL062	MACHINE,ROUGH PART OUT-INCONEL	Yes				
40	NX4A	0003	PP01	GSR02	SPECIAL STRESS RELIEVE INCONEL	Yes				
50	NX4A	0003	PP01	GL113	MACHINE COMPLETE AND PART OFF					
60	QCMM	0003	PP01	GQ027	CRITICAL COMPONENT INSPECTION	Yes				
70	WEDM	0003	PP01	GX163	EDM LUGS	Yes				
80	QCMM	0003	PP01	GQ027	CRITICAL COMPONENT INSPECTION	Yes				
90	HEAT	0003	PP01	GX115	STRESS RELIEVE PER PRINT	Yes				
100	WEDM	0003	PP01	GE002	WIRE EDM	Yes				
110	QCMM	0003	PP01	GQ027	CRITICAL COMPONENT INSPECTION	Yes				
120	NDETP	0003	PP01	GN008	NDT- PT PER QP100-003 / WITNESS	Yes				
130	XPRES	0003	PP01	GWH09	PREPARE FOR OUTSIDE PROCESS					
140	XPOR	0003	PI01	GWH11	READY FOR PO CREATION					
150	XOUT	0003	PP01	GWH04	LOADED ON TRUCK					
160	OUTP	0003	ZP02	GX701	COAT PER BCS A701	Yes				
170	QCMM	0003	PP01	GQ032	INSPECT COATING	Yes				
180	FINL	0003	PP01	GQ012	FINAL RELEASE OF PRODUCT PER DQRM-I104					
189	QCEWO	0003	PP01	GQ002	VERIFY ALL DOCUMENTATION	Yes				
190	CHRG	0003	ZP06	GWH01	CHARGE IN	Yes				

Baker Hughes

SAP Serial Numbers

Work Order# : 109359307

WO Qty. 4

Criticality : 0

Material# : H0J1364100CEOW

QRD UPR CRG BMS-N235

Type : PP01

BMS : BMS-N235 -

Batch# : 0

Q2/Q3 : BAKER Q2 QUAL LVL

WO: Í*} [> È 7 Î

MN: JÇ-`*È0CEO\

Batch: Ì01Î

Serial Number	Barcode	Serial Number	Barcode
16949923	Í0~Ç7pÎ		
16949924	Í0~Ç8tÎ		
16949925	Í0~Ç9xÎ		
16949926	Í0~Ç: Î		

