Taylors Legal 17/12/2022



Applicant's Copy

		Valuation for mortgage p	urposes	5	
	Section A - General details	331	-		
A1	Applicant name(s)	Miss T T Duong	A10	Mortgage reference	
				number M539692376-)1
A2	Building/Flat number		A11	Inspection date 02/09/2022	2
A3	Building name	Flat 23 Gannet Apartments	A12	Report date 02/09/2022	2
A4	Street	42 Shearwater Drive			
A5	District		A13	Is this a transcription	Y N X
A6	Town	Landan	A14	Is the security address the same	e as that on the
A7	County			instruction?	Y X N
A8	Postcode	NW9 7GF		If No, amend address and provi	de details
A9	Plot number (New build only)	282		-	
			A15	Estimated value	£ 385,000
			A16	Purchase price	£ 385,000
	Section B - Tenure				
R1	Freehold	Flying freehold		% flying freehold	
D1	Leasehold	X If Yes, provide details		70 Hyling neeriota	
	Commonhold	in res, provide details	B5	Ground rent (p/a)	£ 0
	Ownership Scotland (Feudal)	Years remaining 989	B6	Service charge (p/a)	£ 1,735
	Shared ownership %	%	В7	Does the property require a righ	<u> </u>
B2	Tenancy in place Y		Б7	shared access?	Y X N
52	If Yes to B2 provide details/rent	\rightarrow \leftarrow		If Yes, provide details	· 🖭 · · 🗀
	Tes to B2 provide details/rent	provided	Legal advisor to ensure		rre appropriate
			B8 Year built		2022
G1	Section C - Property details		G2	N. A. G	
C1	Property type:		C2	Number of:	
	Terraced house			Kitchens	1
	Semi-detached house			Bathrooms	1
	Detached house			Bedrooms	1
	Terraced bungalow			Habitable rooms	2
	Semi-detached bungalow			(bedrooms and reception rooms	
	Detached bungalow			Outbuildings/annexes	0
	Converted flat/maisonette			Provide description of outbuilding	igs/annex
	Purpose Built flat/maisonette	X			37
	Self Contained flat/maisonette		C3	Local authority built	Y N X
	Studio flat	(only acceptable in central London)		Flats:	
	Studio flat Other	(only acceptable in central London)	C4	Floors in block	8
		(only acceptable in central London)	C5	Floors in block Units in block	324
		(only acceptable in central London)	C5 C6	Floors in block Units in block Lift	324 Y X N
		(only acceptable in central London)	C5	Floors in block Units in block	324
		(only acceptable in central London)	C5 C6	Floors in block Units in block Lift	324 Y X N
D1	Other	(only acceptable in central London) Unknown	C5 C6	Floors in block Units in block Lift	324 Y X N
D1 D2	Other Section D - Property services	Unknown	C5 C6	Floors in block Units in block Lift	324 Y X N
	Section D - Property services Current EPC rating Are solar panels fitted to the property	Unknown	C5 C6 C7	Floors in block Units in block Lift	324 Y X N
D2	Section D - Property services Current EPC rating Are solar panels fitted to the property	Unknown perty? No	C5 C6 C7	Floors in block Units in block Lift Accessible via open balcony	324 Y X N
D2 D3	Section D - Property services Current EPC rating Are solar panels fitted to the proposes the property have access to	Unknown perty? No	C5 C6 C7	Floors in block Units in block Lift Accessible via open balcony	324 Y X N



	Section E - Property construction	n			
E1	Garage/parking space	Onsite Private Parking S	pace		
E2	Is the plot size over 10 acres/ 40,000s	sqm? Y N X			
E3	Is the internal floor space less than	30sqm? Y N X			
E4	Is the property a single dwelling?	y Ϊ N 🗍			
	Provide details if not a single dwell	ing			
E5	Is the property of standard construc	ction? Y N X	E6 Is the roof thatched?	Y	N X
	Provide further details below if not	standard construction.	Provide further details regarding co	ndition	
	Walls are of modern rei		if roof is thatched		
	concrete framed constru				
	clad externally, beneat	II a IIac			
	Section F - New build				
F1	Is the property a new build or has it	t been newly converted or refurbished?		YX	N
	Type of new build property	New Build			
F2	Is the property complete?			Y	n X
	If "No" provide details - stage of con	nstruction Roof wall plate.			
F3	Is the property a self build or barn of	conversion?		Y	N X
	If Yes selected, provide details				
F4	Has the UK Finance Disclosure of inco	entives form been seen and taken into account?		YX	N
	If No, assume incentives do not exc	ceed 5%			
F5	Date of UK Finance disclosure of in	ncentives form		20/08/202	2
F6	Are there any financial incentives in	ncluded?		YX	N _
F7	Value of financial incentives?			£ 6,250	
F8	Building guarantee/warranty scheme	NHBC			
	If Other or No warranty selected, plea				
F9	Name of Development	Hendon Waterside			
	Name of Builder/Developer	Barratt Homes			
F11	Number of Units in the Development	2,000			
	Section G - Insurance details				
G1	Estimated current re-instatement co	ost including site clearance		- [120, 000	
	and professional fees excluding VA	AT, except on fees?		£ 130,000	
G2	Floor area main building (sqm)?			59	
G3	Has the property ever been affected	d by structural movement			
	caused by subsidence, settlement,	landslip or heave?		Υ	N X
G4	Is this movement considered to be	long-standing in nature		v 🗀	,
	and the risk of further movement ta	king place acceptable?		Y	N
	If the answer to G4 is 'No' please p	provide further details below			
C5	Is there evidence of coastal erosion	2		ү П	n X
G3	If the answer to G5 is 'Yes' please			1	N X
	n the answer to 05 is 1es please	provide further details below			



	Section H - Specialist reports			
H1	Are there any specialist reports required for mortgage purposes?	YX	N	
H2	f yes to H1 please specify below			
	Structural report Arboriculturalist report Drains	s report		
	Dry rot report Timber and damp report Prefal	bricated reinforced	l	
	Concr	rete (PRC) report	Ш	
	Mundic report Contaminated land report Electr	ical report		
	Gas report Wall ties report Other	report	X	
	Please provide further details of specialist reports required including qualifications required.			
	The building incorporates a cladding system/balconies that may contain combustil The Building Owner and/or its agent, as the 'responsible person' under the Regui			
	Is there any indication/factors that the property has:			
НЗ	Previously been underpinned	Y	n X	
	If "Yes" - Provide details		Ī	
H4	A significant risk of future structural movement	Y	n X	
	If "Yes" - Provide details			
H5	Any Presence of Japanese Knotweed within the curtilage and/or within potential influencing distance of the property?	Y	N X	
	If "Yes" - Provide details	, ,		
Н6	Walls showing signs of damage due to floors suffering from sulphate/ chemical attack or settlement?	Y	N X	
	If "Yes" - Provide details			
H7	Are you aware if the property (including gardens and outbuildings) has flooded in the past?	Y	N X	
	If "Yes" - Provide details			
Н8	Is there any evidence of an insurance claim in progress relating to the subject property	Υ	N X	
	If "Yes" - Provide details			
Н9	Does any part of the property (including any outbuildings) need to be excluded for insurance?	Υ	N X	
	Please detail what part(s) of the property need to be excluded and the reason for the exclusion			
	Is there a commercial element to the property?	Υ	N X	
	Is the commercial element of the property greater than 40%?	Y	N	
H12	Is the property situated over/ next to commercial premises?	Y	N X	
	Please provide further details and any additional guideline related comments regarding commercial use.			
	Section I - Marketability factors			
I1	Are you aware of any factors that affect desirability / demand now or in the near future?	Υ 🗌	n X	
	If "Yes" to I1 - Provide details			
I2	Is the property readily saleable at or about the valuation figure?	ΥX	N	
	If "No" to I2 - Provide details			
I3	In the case of flats, is proper management / maintenance apparent?	YX	N	
	If "No" to I3 - Provide details			
I4	Are there any restrictions on the property (e.g. resale or agricultural restrictions)?	Y	N X	
	If "Yes" to I4 - Provide details	· —		
I5	Is the location of the property likely to significantly impact saleability?	Y	n X	
	If "Yes" to I5 - Provide details			
I6	Is the property and its value comparable to similar properties in the surrounding area?	ΥX	N	
	If "No" to I6 - Provide details			
I7	Is there satisfactory demand for property type in location?	Y X	N	
	If "No" to I7 - Provide details			



	Section J - Works required / retention		
J1	Is there a recommended retention for this mortgage?	Y	n X
J2	Amount of recommended retention £		
Ј3	Please provide further details		
	Section K - Valuation		
K1	Is the property suitable security for the lender?	YX	N \square
	If No, provide details if the property is not considered to be suitable		
		h =	
K2	Valuation in present condition \mathfrak{E}	0	
K3	Valuation upon completion of any works required £	385,000	
K4	For shared ownership, value of share owned by the borrower following completion of this transaction $\mathfrak E$		
K5	Market valuation after any essential/works subject to retention. \mathfrak{E}		
K6	Please provide further details		
	Section L - Buy to Let		
L1	Section L - Buy to Let Is this a Buy to Let Application?	Y	n X
L1 L2	·	Y	N X N
	Is this a Buy to Let Application?	Y	N X N
L2	Is this a Buy to Let Application? Is this property in an acceptable condition to be immediately let? If not in a condition to be immediately let provide details	Y	N X N
	Is this a Buy to Let Application? Is this property in an acceptable condition to be immediately let? If not in a condition to be immediately let provide details Is Buy to Let licensing required?	Y	N X N N N N N N N N N N N N N N N N N N
L2	Is this a Buy to Let Application? Is this property in an acceptable condition to be immediately let? If not in a condition to be immediately let provide details	Y	N X N N N N N N N N N N N N N N N N N N
L2	Is this a Buy to Let Application? Is this property in an acceptable condition to be immediately let? If not in a condition to be immediately let provide details Is Buy to Let licensing required?	Y	N X N N N N N N N N N N N N N N N N N N
L2 L3	Is this a Buy to Let Application? Is this property in an acceptable condition to be immediately let? If not in a condition to be immediately let provide details Is Buy to Let licensing required? If Yes, provide details		
L2 L3	Is this a Buy to Let Application? Is this property in an acceptable condition to be immediately let? If not in a condition to be immediately let provide details Is Buy to Let licensing required? If Yes, provide details Does owner occupier and investor demand exist in this location?		
L2 L3	Is this a Buy to Let Application? Is this property in an acceptable condition to be immediately let? If not in a condition to be immediately let provide details Is Buy to Let licensing required? If Yes, provide details Does owner occupier and investor demand exist in this location? If No, provide rationale for No		
L2 L3 L4 L5	Is this a Buy to Let Application? Is this property in an acceptable condition to be immediately let? If not in a condition to be immediately let provide details Is Buy to Let licensing required? If Yes, provide details Does owner occupier and investor demand exist in this location? If No, provide rationale for No What is the Market Rent (per calendar month) in Present Condition or assumed completion of works mentioned above. £		

Note to Applicants

This is not a building survey but it is a valuation solely for mortgage purposes. You must not assume that if defects are not mentioned in the report, all parts of the structure are free from defect, nor if some defects are mentioned, that there are no others. Moreover services have not been fully tested. It is highly recommended that you obtain your own full report from an independent surveyor to protect your own interests.



Valuation for mortgage purposes - Continuation Page

Applicant name(s)	Miss T T Duang	Mortgage reference		
		number	M539692376-01	
Building/Flat number				
Building name	Flat 23 Gannet Apartments			
Street	42 Shearwater Drive			
District				
Town	Landon			
County				
Postcode	NW9 7GF			

B7 If property requires a right of way or shared access, provide details (continued)

rights of way and management arrangements for the shared vehicular and pedestrian access.

E5 Provide further details below if not standard construction. (continued) proprietary covered roof.

H2 Please provide further details of specialist reports required (continued) (Fire Safety) Order 2005, must produce a completed form EWS1.

M1 Additional valuer comments: (continued)

in the document entitled 'Advice for Building Owners of Multi-storey, Multi-occupied Residential Buildings' dated 20 January 2020, and as specifically agreed with the Bank, the Bank will ascertain this for itself; the valuer has been instructed not to carry out any form of due diligence; has not received a copy of the EWS1 form; and, has not made any form of assessment as to the suitability of it.

It was not possible to inspect the property as no access was available on site. The valuation is therefore based on information provided by the developer. The lenders legal adviser should refer any discrepancies to the valuer.

It should be appreciated that the valuation provided is for the property as new. It may not be possible to obtain the valuation figure if the property is resold as second-hand, especially if comparable new property is on offer at the same time.

Sales incentives including: the payment £4,250 for stamp duty relating to the property and £2,000 for other unspecified discounts have been disclosed. Legal adviser to confirm in accordance with UK Finance Handbook. This has been reflected in the valuation.

The property is being purchased through the Help to Buy scheme.

The unexpired term of the lease is 989 years and has been reflected in the valuation.

*End of Report *