
ECU2 Operation State Machine



Transition notation	Transition condition
T1	(DRState == OPN && SPDState == MOV)
T2	(DRState == OPN && SPDState == STP)
Т3	(DRState == CLS)
T4	(SWState == PRESS && SPDState == MOV)
Т5	(SWState == PRESS && SPDState == STP)