

Project 2 EDF Scheduler

:≣ Week	
YouTube Link	https://classroom.udacity.com/nanodegrees/nd0900-fwd-t3/parts/c5e0f9f6-c4a0-462e-b4ca-619dfd99477a/modules/75f64c76-198c-405e-b1dd-0a5509fd2ca8/lessons/69b5bcfa-71a8-45c3-8973-2fc710f0f92e/concepts/0b3e4ee6-b7b0-4acd-b48b-f8e711144708 https://www.youtube.com/watch?v=d0AF1wZ2_yQ&t=9s
@ FileLink	
Status	
■ Notes	
Other Sources Reference	
# Rem Esti Hrs	
≡ Property	

Project Analysis






Project Requirements:

• The general idea is to:

- create a new Ready List (Figure 3.3), able to manage a dynamic task priority behavior:
- it will contain tasks ordered by increasing deadline time, where positions in the list represent the tasks priorities.
- The head of the list contains the task with the closest deadline



- The head of the list containing the running task.
- The rest of FreeRTOS architecture and structures, as the Waiting List and the clock mechanism are maintained with marginal changes.
- Implementation assumptions :
 - Periodic tasks only;
 - task deadline equal to task period;
 - only schedulable tasks set;
 - independent tasks only (no shared resources and no sync issues).

- When Task is moved from Delayed (Waiting List) to Ready List. DeadLine
 evaluation shall be calculated and insertion and insertion in ReadList shall be in
 the correct order based on deadline.
- Ex: Tick mechanism wakes tskZ removing it from Waiting List and adding it to Ready List, in the right position according to its new deadline
 - Zdeadline = tick + Zperiod
- All changes that will be illustrated refer to tasks:c file
- Required configuration variables:
 - configUSE_EDF_SCHEDULER, is added to the FreeRTOS:h config file.
- Implement, the prvInitialiseTaskLists() method, that initialize all the task lists at the creation of the first task, is modified adding the initialization of xReadyTasksListEDF
- prvAddTaskToReadyList() method that adds a task to the Ready List → Very important as it's the one responsible about scheduling
- vListInsert() method is called to insert in xReadyTasksListEDF the task TCB pointer.
 The

item will be inserted into the list in a position determined by its item value xGenericListItem

(descending item value order). So it is assumed that xGenericListItem contains the next task


deadline.

 when a task moves to the Ready List, the knowledge of its next deadline is needed in

order to insert it in the correct position.

 The deadline is calculated as: TASKdeadline = tickcur + TASKperiod, so every task needs to store its period value. A new variable is added in the tskTaskControlBlock structure (TCB):

The deadline is calculated as: TASKdeadline = tickcur + TASKperiod,



- xTaskPeriodicCreate() is a modified version of the standard method xTaskGenericCreate() shown in Cap.2, that receives the task period as additional input parameter and set the xTaskPeriod variable in the task TCB structure. Before adding the new task to the Ready List by calling prvAddTaskToReadyList(), the task's xGenericListItem is initialized to the value of the next task deadline.
- The IDLE task management is modified as well.
 - The initialization of the IDLE task happens in the vTaskStartScheduler() method, that:
 - starts the real time kernel tick processing
 - initialize all the scheduler structures.

Since FreeRTOS specifications want a task in execution at every instant, a correct management of the IDLE task is fundamental.

With the standard FreeRTOS scheduler, the IDLE task is a simple task initialized at the lowest priority.

- In this way it would be scheduled only when no other tasks are in the ready state. With the
- EDF scheduler, the lowest priority behavior can be simulated by a task having the farest deadline.
- Shall increment it in runtime as well Every time IDLE task executes (i.e. no other tasks are in the Ready List), it calls a method that increments its deadline in order to guarantee that IDLE task will remain in the last position of the Ready List (implemented)
- vTaskStartScheduler() method initializes the IDLE task and inserts it into the Ready List.
 - This MACRO listSET_LIST_ITEM_VALUE(&((pxNewTCB)->xGenericListItem), (pxNewTCB)->xTaskPeriod + currentTick); shall calculate deadline.
- taskSELECT HIGHEST PRIORITY TASK() method is replaced in order to assign to pxCurrentTCB the task at the first place of the new Ready List
- When the tick interrupt occurs, the ISR vPortYeldFromTick() is called. (not implmented)
 - Saves the running task context → portSAVECONTEXT()
 - xTaskIncrementTick()
 - if same tasks are wake up from the Waiting List (Not implmented)
 - performs a context switch → vTaskSwitchContext()
 - tskA's(new Task) GenericListIteam is set to tskA's(new Task) new deadline (currentTick + tskA period);
 - restores the context of the (tskA's) new running task.
 - *pxCurrentTCB pointer points to tskA;
 - portRESTORECONTEXT() restores the context
 - tskA is insered in <u>xReadyTasksListEDF</u> by calling the <u>addTaskToReadyList()</u> method

Missing Implementation for the project:

- 1- Increment IDLE Task Deadline to be the max_align_t value ever → (implementation in Function static portTASK_FUNCTION(prvIdleTask, pvParameters)) → DONE
- 2- **Evaluate Delayed List** by checking Current Tick. Then will decide if context Switch required if **YES:** → (implementation in Function BaseType_t xTaskIncrementTick(void))
 - Task will be removed from Delayed List → Remove MACRO implementation shall be adjusted for EDF
 - Remove from Event List → check also if this requires implementation adjustment
 - Task will be added to ReadyList by new DL Calculated.
 - Execute Context Switch based on DL information in ready list:
 - by setting xSwitchRequired

3-Check Condition for Context Switch shall not be Priority → shall be changed to deadline 1st → (implementation in Function BaseType_t xTaskIncrementTick(void)) or on return from it —> May be implemented to get from the ReadyTask next one

Notes:

- xGenericListItem → xStateListItem name changed
- xItemValue → new calculated deadline
- xItemValue will be used by insert macro to decide location of Task in ReadyList

Project Completion Requirements:

- Implement 4 tasks using EDF scheduler
 - o TickHook → PIN1
 - Task1: (Periodicity: 10, Priority: , ExecutionTime: 1 ms) → PIN2
 - Task2: (Periodicity: 50, Priority: , ExecutionTime: 8 ms) → PIN3

- Task3: (Periodicity: 20, Priority: , ExecutionTime: 2 ms) → PIN4
- Task4: (Periodicity: 40, Priority: , ExecutionTime: 5 ms) → PIN5
- 1. Verifying the system implementation with the following parameters:
 - Deadline
 - Periodicity
 - Priority
 - Execution Time → Add overload & Calculate by hooks
- Verify Schedulability with:
 - o offline Simulator
 - Analytical analysis
 - ∘ Runtime → implement deadline Detector, & GetTime Counters and execution
 - Simple report of work and Comments
- Bonus → RTOS Runtime implementation update to consider Runtime analysis for EDF ReadyList

Simulator Data

