
E14: the same missions without (faint) and with (solid) the load-carrying motion limits
goal reached (%)
0
20
40
60
80
100
VFH
DWA
MPC
pVFH
P-VFH
mover-contact steps / run
0
5
10
15
20
25
VFH
DWA
MPC
pVFH
P-VFH
mean mission time (s)
0
10
20
30
40
50
VFH
DWA
MPC
pVFH
P-VFH
peak robot speed needed (m/s)
0.0
0.5
1.0
1.5
2.0
2.5
3.0
limits OFF (E1 rows)
limits ON
VFH
DWA
MPC
pVFH
P-VFH