



NOTE
* With JUMPER JP1 bridged, output current is variable causing "breathing LED" effect.
* C1 and R5 values affect breathing effect

* With JUMPER JP1 open, and resistors R4/R6 populated, the 555 works as a classic astable multivibrator
* Output voltage switches between 2/3rd and 1/3rd of input voltage (6V)
* C1/R4/R6 values affect astable frequency

Mounting Hole
placeholder

G2
Pin

LEGS
solder stiff brass or copper wire pieces to form six legs

G3 LEG G4 LEG G5 LEG G6 LEG G7 LEG G8 LEG

STING
solder short brass or copper wire for sting

G9
STING

MAP6 @ git.io/J0GPd
Learn to Solder Maker's Asylum Badge
**Maker's Asylum**

G1
Logo_MA

G10
OPEN_HARDWARE_1

Sheet: /
File: MAP6.kicad_sch

***Title: MAP6***

| Size: A4 | Date: 2026-08-24 | **Rev: v2** |
|---|---|---|
| KiCad E.D.A. 10.0.5 | | Id: 1/1 |