1. Description


1.1. Project

Project Name	led
Board Name	custom
Generated with:	STM32CubeMX 5.3.0
Date	05/31/2020

1.2. MCU

MCU Series	STM32F1
MCU Line	STM32F103
MCU name	STM32F103T6Ux
MCU Package	VFQFPN36
MCU Pin number	36

2. Pinout Configuration




3. Pins Configuration

Pin Number VFQFPN36	Pin Name (function after reset)	Pin Type	Alternate Function(s)	Label
1	VDD	Power		
2	PD0-OSC_IN	I/O	RCC_OSC_IN	
3	PD1-OSC_OUT	I/O	RCC_OSC_OUT	
4	NRST	Reset		
5	VSSA	Power		
6	VDDA	Power		
15	PB0 *	I/O	GPIO_Output	LED
18	VSS	Power		
19	VDD	Power		
26	VSS	Power		
27	VDD	Power		
35	воото	Boot		
36	VSS	Power		

^{*} The pin is affected with an I/O function

4. Clock Tree Configuration



5. Software Project

5.1. Project Settings

Name	Value		
Project Name	led		
Project Folder	C:\Users\cloud\Documents\LIS3DH\led		
Toolchain / IDE	MDK-ARM V5		
Firmware Package Name and Version	STM32Cube FW_F1 V1.8.0		

5.2. Code Generation Settings

Name	Value
STM32Cube MCU packages and embedded software	Copy all used libraries into the project folder
Generate peripheral initialization as a pair of '.c/.h' files	No
Backup previously generated files when re-generating	No
Delete previously generated files when not re-generated	Yes
Set all free pins as analog (to optimize the power	No
consumption)	

6. Power Consumption Calculator report

6.1. Microcontroller Selection

Series	STM32F1
Line	STM32F103
MCU	STM32F103T6Ux
Datasheet	15060_Rev7

6.2. Parameter Selection

Temperature	25
Vdd	3.3

7. IPs and Middleware Configuration 7.1. RCC

High Speed Clock (HSE): Crystal/Ceramic Resonator

7.1.1. Parameter Settings:

System Parameters:

VDD voltage (V) 3.3
Prefetch Buffer Enabled

Flash Latency(WS) 0 WS (1 CPU cycle)

RCC Parameters:

HSI Calibration Value 16
HSE Startup Timout Value (ms) 100
LSE Startup Timout Value (ms) 5000

7.2. SYS

Debug: No Debug

Timebase Source: SysTick

^{*} User modified value

8. System Configuration

8.1. GPIO configuration

IP	Pin	Signal	GPIO mode	GPIO pull/up pull down	Max Speed	User Label
RCC	PD0- OSC_IN	RCC_OSC_IN	n/a	n/a	n/a	
	PD1- OSC_OUT	RCC_OSC_OUT	n/a	n/a	n/a	
GPIO	PB0	GPIO_Output	Output Push Pull	No pull-up and no pull-down	Low	LED

8.2. DMA configuration

nothing configured in DMA service

8.3. NVIC configuration

Interrupt Table	Enable	Preenmption Priority	SubPriority	
Non maskable interrupt	true	0	0	
Hard fault interrupt	true	0	0	
Memory management fault	true	0	0	
Prefetch fault, memory access fault	true	0	0	
Undefined instruction or illegal state	true	0	0	
System service call via SWI instruction	true	0	0	
Debug monitor	true	0	0	
Pendable request for system service	true	0	0	
System tick timer	true	0	0	
PVD interrupt through EXTI line 16	unused			
Flash global interrupt	unused			
RCC global interrupt	unused			

^{*} User modified value

9. Software Pack Report