














I mean, this should be fine. The diode's forward voltage is about .32 V at the currents I am expecting. Therefore, if the G0 pulls to 0.1V LOW and the diode adds .32V, .42V must be less than .3Vdd for the NRST to register VL. If Vdd is 3.3V, this shouldn't be an issue I hope.




Got the Switch Pinout from a random site online, could be wrong. Check with multimeter the connections








Keep the two clocks far away from each other on the layout



We use the Port F Block (Block 1)





 H11 MountingHole H10
Mounting Hole