


XCOM V2.6 Interface Map



1. Main Log Window - COM

2. Port Selection - COM

3. Baud Rate - (9600 115200)

4. Stop Bits - - (1 2)

5. Data Bits - (8)

6. Parity Bit - : None / Even / Odd ..

7. Hex Send - HEX-

8. Open Port - COM-

9. Optional Flags (RTS/DTR etc) - : RTS, DTR, DIR

10. Send Button - ,

11. Open File -

12. Timed Send -

13. Save - /

14. HEX Mode - HEX- (NewLine)

15. Input Field -

16. Status Panel - (S: R:)

17. System Time -