

CD30/35 MANUAL & START GUIDE

FOR USE ON
PPM ELECTROMAGNETIC EQUIPMENT

VF Advance
VF Premier
Mini VF
VFX
Magnatron

PPM Contact information:

AMERICAS

PPM TECHNOLOGIES
500 E. Illinois St.
Newberg, OR 97132 | USA
(503) 538-3141
(800) 523-8123 toll free in the US
(503) 538-8575 fax

EUROPE | MIDDLE EAST | AFRICA

PPM TECHNOLOGIES EMEA Ltd.
Axis 40 Oxford Road
Stokenchurch
Buckinghamshire HP14 3SX
+44 1494 682800
+44 1494 682801 fax

Webpage: www.ppmtech.com
Email: Parts.na@ppmtech.com

Printed in the USA

Manual Revision Log

REV #	DATE	CHANGE DESCRIPTION	SECTIONS MODIFIED	BY
0	1/29/09	Original creation of quick start supplement for using the CD30 on PPM EM equipment (VF, Magnatron, etc.)	ALL	NJD
1	3/1/09	Updated setup values, added –En note	4, 4.2	NJD
2	4/17/09	Clarified numerous sections, added QS addendum	ALL	NJD
3	7/28/09	Updated wiring diagram, added sections 1.3, 2.4 & 7x	2, 1.3, 2.4, 7x	NJD
4	12/13/10	Added PPM Contact information	Intro	DER
5	8/8/12	Change section on how to hide service menus (C127)	3.2 (C127)	CWJ
6	12/08/17	Revised sections for accelerometer use	2.2; 4.2; 4.3; QSA	TNT

PPM Technologies reserves the right to alter at any time, without notice and without liability or other obligations on its part, materials, equipment specifications, and models. PPM Technologies also reserves the right to discontinue the manufacture of models, parts, and components thereof.

Table of Contents

- 1. Summary**
 - 1.1. Controller Specifications
 - 1.2. Application
 - 1.3. Safety Instructions
- 2. Wiring**
 - 2.1. Power (incoming to controller/outing to coil)
 - 2.2. Feedback Sensor
 - 2.3. System control wiring
 - 2.3.1. Enable Unit
 - 2.3.2. External Set Point (C038~ESP)
 - 2.3.3. Status Relay (C040~r.b.)
 - 2.3.4. 2nd Set Point (C038~2.)
 - 2.4. Recommended Method for Installing a Frequency Controller
- 3. CD30/35 Important Menu Settings**
 - 3.1. Basic Display Navigation
 - 3.2. C210, C143, C117, C127 (Save & Hide Settings)
 - 3.3. C038 (Function Settings)
 - 3.4. C040 (Service Settings)
- 4. Step by Step Setup Procedure**
 - 4.1. Wire CD30/35
 - 4.2. Set CD30/35 Menu Settings for PPM equipment
 - 4.3. Set Sensor Position using C051
 - 4.4. Run Automatic Frequency Search (AFS)
 - 4.5. Set Operating Characteristics (A, P)
 - 4.6. Save User Settings & Hide Menus
- 5. Main Fault Messages**
- 6. Troubleshooting**
- 7. Special Applications**
 - 7.1. Master/Slave Control
 - 7.2. Single Controller for Multiple Magnet Coils

CD30/35 Quick Start Addendum