


SB-2 HD

Side Belt Heavy Duty Industrial Case Taping System

User Guide



EASTEY®

SB-2 HD

Side Belt Heavy Duty Industrial Case Taping System

User Guide

Revised 07/18/2019

PN# 5000711 Rev. E

Copyright and Trademarks

Copyright ©2013-2019 Engage Technologies Corporation
All rights reserved. All trademarks and brand names
are the property of their respective owners.

Eastey
7041 Boone Ave N.
Brooklyn Park, MN. 55428

Phone: (763) 428-4846; Fax: (763) 795-8867; Toll Free: 1-800-835-9344
www.eastey.com

Contents

Safety	7
Introduction	8
SB-2 HD Overview.....	8
Specifications	9
Installation and Setup	11
Removing the Shipping Pallet.....	11
Repositioning Width Adjustment Handle.....	12
Installing the Optional Locking Casters.....	13
Set Machine Height	14
Location Requirements.....	14
Loading the Tape Cartridges	15
Operation	21
Adjustments	22
Package Width	22
Package Height	22
Maintenance	23
Rollers	23
Cutting Knives	23
Changing the Drive Belts	24
Parts List.....	26
SB-2 HD Main Assembly	26
Base Frame Assembly, Top	28
Base Frame Assembly, Bottom	29
Case Support Assembly	30
Width Adjustment Assembly	31
Vertical Column With Height Adjustment	32
Electrical Switch, Strain Relief & Column Attachment	33
Upper Tape Head Seat Plunger Pin, CF Spring & Spacer.....	34
Upper Tape Head Seat to Column Assembly	35
Side Belt Frame, Idler Pulley, and Tension Brackets.....	36
Side Belt Motor, Motor Pulley, and Attaching Hardware	37
Side Belt Guide Strips and Attaching Hardware	38
Side Belt Belts, Tensioning & Frame Attaching Screws.....	39
Side Belt Cover & Cover Attaching Screws	40
Warranty Statement	41
Customer Support.....	43
Eastey Technical Service	43

Safety

Before installing, operating or servicing this equipment, please read the following precautions carefully:

- This machine is equipped with moving belts. Do not place hands near the belts when they are moving as fingers may be pinched where belts enter the frame. We suggest the use of a roller-type exit conveyor or pack table for your cases. Always remove boxes after they clear the exit end of the machine.
- Observe caution when near the tape heads or when threading tape. The tape cutting knife is very sharp, automatically operated, and is linked to the wipe down rollers.
- Always disconnect electrical power before attempting maintenance for any electrical or moving parts. Do not attempt to open or work on the electrical box, junction boxes or other electrical components of the unit without first disconnecting power to the machine. Electrical shock hazard exists if power is not disconnected.
- Use only the specified power-supply cable. Do not use the power cable to pull or position the machine, as this will damage or break the cable.
- Do not bypass any factory-designed safety features such as knife guards, interlocks, switches, etc. Do not operate a machine if such modifications have been made.
- Do not attempt to operate the machine with loads that exceed the limits of use and operation in regards to weight and sizes, or with unstable loads that present a hazard of tipping or falling.
- This equipment is designed for indoor operation in a typical clean, dry factory environment. Do not operate the machine in any extremely wet or oily environment that may exceed operating specifications.
- Do not place hands, head, or any part of the body inside the confines of the machine unless the tape head mechanisms are securely fastened, and the electrical supply is shut off. Do not stand or climb on any part of the taper.
- To minimize the potential for personal injury, always be sure that the machine operators and others working on the machinery are properly trained in the correct usage of this equipment and properly instructed regarding safe operation.
- Never provide service or clear a box jam when machine is running. Always stop the machine and shut off power before servicing.
- When feeding a box into the unit, always hold down the box top and present the box to unit. Release hands as soon as the belts begin to take the box.
- Do not wear loose clothing such as ties, scarves, jewelry etc. Long hair should be pulled back and/or covered while operating this machine.