

Cleaning

! WARNING !

STOP the equipment (Push Red STOP button) before attempting to clean. Do not attempt to clean the equipment with the belts in motion.

This Machine is Not designed for Wash-Down.

Suggested Cleaning Agents

Poly Carbonate Guarding - lukewarm water containing a neutral (safe for plastics) detergent.

Servo slider shaft - disposable paper and methylated spirit or alcohol.

Other - food grade sanitizing spray.

Poly Carbonate Guarding - Cleaning

Wash with lukewarm water containing a neutral (**safe for plastics**) detergent using a soft sponge, a wool cloth or a chamois.

Rinse with water.

Never use razor blades, scrapers, squeegees, brushes, etc.

Every Shift

The equipment should be cleaned and wiped down as follows at least once at the end of every shift. Depending on the type of product being processed, more frequent cleaning may be required.

Push the **EMERGENCY STOP** button down.

DO NOT Attempt To Wipe Down the Machine While it is Running.

Remove all scraps from stacking towers and conveyors.

Vacuum or blow refuse out of the units.

Wipe all food contact surfaces with a damp cloth. Mist with a sanitizing spray, if desired.

Belts

Do NOT Attempt to clean the belts while they are in motion.

Push the **EMERGENCY STOP** button down to stop the belts.

Wipe the accessible portion of each belt with a damp cloth.

Release the **EMERGENCY STOP** button by turning it clockwise.

Push the **SAFETY RESET** button.

Push the **CYCLE START** button to advance the belts.

Repeat until the belts are clean.

Maintenance Procedures should be performed by Trained Personnel Only.
Maintenance PPE - Safety Shoes, Bump Caps, Safety Glasses

Cleaning

! WARNING !

STOP the equipment (Push Red STOP button) before attempting to clean. Do not attempt to clean the equipment with the belts in motion.

This Machine is Not designed for Wash-Down.

Wipe all photo sensor lenses.

Clean servo sliders and shafts.

Monthly

Blow out all hoses and air lines.

Wipe down the entire machine.

DO NOT Attempt To Wipe Down the Machine While it is Running.

Maintenance Procedures should be performed by Trained Personnel Only.
Maintenance PPE - Safety Shoes, Bump Caps, Safety Glasses