
(a) PWM frequency
Mean pose failure (%)
PWM frequency (Hz)
0
200
400
600
800
1000
(b) Exposure time
Exposure time (ms)
2
4
6
8
10
(c) Duty cycle
PWM duty cycle (%)
10
20
30
40
50
60
70
80
90
(d) Modulation depth
PWM modulation depth (%)