```
void setup() {
Serial.begin(9600);//initializing serial monitor
}
void loop() {
float c=35;
float f=c*9/5+32;
//relationship between Celsius, Fahrenheit scale
Serial.println(f,3);delay(1000);
}
```