

Task Risk Assessment

With COSHH Compliance

sevron

Before Controls	MEDIUM 8 RISK	LOW 4 RISK	After Controls

Task Title	Pushing Nasonia		
Process Title	Pushing Nasonia		
Location	519 (E.Mallon)		
Assessed On	06/05/2026	Assessed By	Christian Thomas
Review Date	06/05/2027	Reference	Pushing Nasonia
Signed By	Christian Thomas	Revision	1
People Affected	Employees, Lab Users, Service Users, Students		

Hazards



PPE

Task/Procedure/Method Statement

Anaesthetise Nasonia and transfer them to a new tube

Substance Information

Product Name	Manufacturer	Hazard Symbols
CARBON DIOXIDE (CO2) - Filled Gas		
Cylinder (5060351, 5060375, 5060416, 5066413, 5066427)		

Task Related Hazards & Controls



Before Controls: **Low Risk (3/25)**



After Controls: **Low Risk (3/25)**



Hazard Description

Warning; Pressurized cylinder

Ensure only experienced members of staff touch the cylinders

Emergency Controls In Place



First aid



Before Controls: **Medium Risk (8/25)**



After Controls: **Low Risk (4/25)**



Hazard Description

CO2 leak can cause asphyxiation.

Controls In Place



Sound Alarm

Emergency Controls In Place



Evacuation assembly point



Before Controls: **Low Risk (4/25)**



After Controls: **Low Risk (2/25)**



Hazard Description

Nasonia handling

Controls In Place



Wash your hands

Emergency Controls In Place



First aid

General Controls & Emergency Controls

Controls In Place



Wash your hands



Cleaning



Sound Alarm

Emergency Controls In Place



Wash your hands



First aid



Evacuation assembly point

Health Surveillance

Make sure all valves are turned off to avoid leaking of CO₂.

If you hear the alarm sound, turn off the gas at your station.

If the alarm persists, evacuate the station.

Wash your hands after Nasonia handling to reduce risk of irritation.