Practice Exam B Multiple Choice Questions

B6.	A server administrator has four identical drives to install into a database server. Which of these RAID types would provide both redundancy and the most available storage space?	
	O A. RAID 5 O B. RAID 10	Quick Answer: 161
	○ C. RAID 0○ D. RAID 1	The Details: 171
B7.	A user is attempting to charge their iPhone, but the charging icon does not appear when connecting the charging cable. A working cable from another iPhone exhibits the same symptoms. Which of the following is the MOST likely reason for this issue?	
	O A. The screen is lockedO B. An iOS update is pending	Quick Answer: 161
	O C. The iPhone has low signalO D. The Lightning port is damaged	The Details: 172
B8.	A user in the marketing department needs an LCD with the best possible color representation. Which of the following would be the BEST choice for this requirement?	
	O A. TN O B. CCFL	Quick Answer: 161
	O C. IPS O D. VA	The Details: 173
В9.	A company is receiving an increase in malware delivered to random employees through email attachments. Which of the following would be the BEST way to protect users against this malicious software?	
	O A. Spam gateway O B. DHCP services	Quick Answer: 161
	O C. Syslog O D. VLANs	The Details: 174

B10. A user has reported their tablet is not able to retrieve or send mail, browse the Internet, or connect to video conferences. Apps on the device which do not require connectivity are working as expected. Which of these would be the MOST likely cause of this issue?

O A. Battery is very low

Quick Answer: **161**

O B. The Wi-Fi network is out of range

The Details: 175

- O C. The touch screen needs calibration
- O **D.** The tablet is overheated
- **B11.** A PC technician has been asked to replace the LCD on a touch-screen laptop computer. Which of the following would be the MOST important component to test after this replacement?

O A. Digitizer

Quick Answer: **161**

O B. Keyboard

The Details: 176

- O C. Audio controls
- O D. System memory
- **B12.** The computers in the shipping department are receiving the message "No connectivity" on their computers. The ipconfig output on one of the computers provides this information:

IPv4 Address: 192.168.1.22 Subnet Mask: 255.255.255.0 Default Gateway: 192.168.1.1

From this device, a technician is able to successfully ping 127.0.0.1 and 192.168.1.22. The technician can also ping other devices in the shipping department, but cannot receive a ping response from servers in the data center or from the 192.168.1.1 address.

Which of these would be the MOST likely cause of this issue?

Quick Answer: **161**

The Details: 177

- O A. The DHCP server is down
- O B. The wireless network is experiencing interference
- O C. The local router is down
- O D. The Internet provider is experiencing an outage

B13.	Which of the following would be the BEST way to activate the screen of a smartphone without physically touching the display?	
	O A. Trackpad	Quick Answer: 161
	O B. Port replicatorO C. Smart card readerO D. Touch pen	The Details: 178
B14.	A graphics designer is working on a computer that powers itself off after about an hour of work. The computer tends to power down when working on complex designs that require extensive CPU utilization. Which of the following would be the MOST likely reason for this issue?	
	A. The case fans are blockedB. The hard drive is failing	Quick Answer: 161
	O C. The graphics software is corruptedO D. A device driver is outdated	The Details: 179
B15.	Which of these services would be associated with a Windows file transfer?	
	O A. LDAP O B. SMB	Quick Answer: 161
	O C. IMAP O D. SSH	The Details: 180
B16.	A server administrator is configuring a new system for virtualization. Which of the following configurations would provide virtualization support on an Intel CPU?	
	A. Install a 64-bit operating systemB. Turn on HTT	Quick Answer: 161
	O C. Allocate a larger amount of storage space to the virtualization partition	The Details: 181
	O D. Enable VT in the firmware	

B17.	A user in the shipping department is printing a single page to your laser printer, but the output includes the printed page with three or four pages stuck together underneath it. Which of these would be the most likely cause of this issue?	
	O A. Duplexer	Quick
	O B. Transfer belt	Answer: 161
	O C. Fuser assembly	The Details: 182
	O D. Separation pad	
	O E. Imaging drum	
B18.	A company is using a cloud-based service that provides a hardware platform and no additional software. Which of these would BEST describe this purchase?	
	O A. SaaS	Quick
	O B. Hybrid	Answer: 161
	O C. Metered	The Details: 183
	O D. IaaS	
B19.	While working at their desk, a laptop user would like to use a full-size keyboard and external mouse. They would also like to connect to a monitor and wired network without connecting and disconnecting cables each time they leave the desk. Which of these would be the BEST way to provide this functionality?	Quick
	O A. Use separate desktop and laptop computers	Answer: 161

O B. Install a docking station at the user's deskO C. Use a wireless access point at the user's desk

O D. Install a USB hub for the laptop

The Details: 184

B20.	A server administrator needs to store gigabytes of server performance statistics for future analysis. The data needs to be always be available, even if a storage drive fails. Which of the following would be the BEST choice for this data?	
	O A. Optical drive O B. SD	Quick Answer: 161
	O C. RAID	The Details: 185
	O D. CompactFlash	
B21.	In which of the following would a cable with a DB-9 connector be used?	
	O A. Attaching a mouse or keyboard to a desktop computerO B. Configuring a router	Quick Answer: 161
	O C. Connecting an external storage device	The Details: 186
	O D. Attaching a video camera to a computer	
B22.	A workstation administrator is configuring a new system for graphics designers, and the users have requested the fastest possible storage speed for reading and writing data. Which of the following would be the BEST choice for this requirement? O A. 10 TB NAS	Quick
	O B. 8TB HDD	Answer: 161
	O C. 5 TB SANO D. 2 TB SSD	The Details: 187
B23.	A user has connected a new laptop to an LCD projector in a conference room. About thirty minutes into the presentation, the projector light turns off but the projector fans continue to run. Which of the following would be the MOST likely reason for this issue?	
	O A. Incorrect laptop cable O B. Poor projector airflow	Quick Answer: 161
	O B. Poor projector airflowO C. Dead pixelsO D. Incorrect resolution setting	The Details: 188

B24.	A marketing manager is printing a document on the company letterhead stored in one of the printer trays. However, the output is instead printed from a tray containing plain paper. Which of the following would be the BEST way to resolve this issue?	
	A. Select the duplex print optionB. Enable collated output	Quick Answer: 161
	O C. Modify the output tray in the print dialog	The Details: 189
	O D. Change the output orientation	
B25.	A system administrator has noticed that their cloud implementation supports multiple application instances during the busy workday, but only one application instance is available during the slower evening shifts. Which of the following would BEST describe this functionality?	
	O A. Metered utilization	Quick Answer: 161
	O B. Rapid elasticity	Alliswei. 101
	O C. High availability	The Details: 190
	O D. Shared resources	
	O E. File synchronization	
B26.	A security administrator would like to ensure that each login attempt from a smartphone is from someone physically located inside the corporate office. Which of the following would provide this functionality?	
	A. Serial interfaceB. GPS	Quick Answer: 161
	O C. iCloud	The Details: 191
	O D. Hotspot	
B27.	A technician is connecting USB interfaces on a computer case to the motherboard. Which of the following would be commonly used for this connectivity?	r
	O A. PCIe	Quick
	O B. eSATA	Answer: 161
	O C. TPM	The Details: 192
	O D. Headers	

B28.	A company is building an ARM-based IoT device for the consumer market. Which of the following would be an advantage of using the ARM architecture for this product? (Choose TWO)	
	 A. Redundancy B. High speed networking	Quick Answer: 161
	O C. Low power use	The Details: 193
	O D. NAS	
	O E. Load balancing	
	O F. Minimal heat	
B29.	A manufacturing company uses a specialized printer which connects to a Windows computer over a USB connection. Which of the following would be the BEST way to allow all Windows devices in the company to send print jobs to this printer?	
	 A. Connect using AirPrint B. Configure Windows Printer Sharing C. Use Print to File and copy the file to the printer D. Copy the print jobs to a USB drive 	Quick Answer: 161 The Details: 194
B30.	Which of these would commonly be used to connect to an external storage device?	
	O A. F-connector O B. ST	Quick Answer: 161
	O C. eSATA O D. Molex	The Details: 195

B31.	A company has acquired computers that were previously part of a third-party lease. All of the computers prompt for a password when powering on the system before the operating system will load, but the password was not included with the computers. Which of the following would be the BEST way to resolve this issue? O A. Replace the primary storage drive	Quick
	O B. Boot from the Windows installation media	Answer: 161
	O C. Reset the BIOS using jumpers on the motherboard	The Details: 196
	O D. Disconnect the power cable for ten minutes	
B32.	A user has complained that a laptop will not charge the battery past 25% percent, and the laptop only operates for fifteen minutes when on battery power. The battery and the AC adapter have already been replaced. Which of the following components would be the MOST likely cause of this issue?	
	O A. MotherboardO B. Backlight inverter	Quick Answer: 161
	C. 802.11 adapterD. CPU	The Details: 197
B33.	A field engineer is working at a remote site that is under construction, but the site does not have an Ethernet or Wi-Fi Internet connection. Which of the following would be the BEST way to get access to the Internet at this location?	
	O A. Bluetooth	Quick Answer: 161
	O B. Hotspot	
	O C. MAN	The Details: 198
	O D. NFC	

B34.	Which of the following would be the MOST likely reason the finishing function of a printer would punch two holes in a page instead of three?	
	O A. The incorrect paper tray is selectedO B. The print driver is not configured properly	Quick Answer: 161
	O C. The printer is low on toner	The Details: 199
	O D. The connection between the computer and the printer is faulty	
B35.	A technician is upgrading the RAM on a laptop computer. Which of the following would BEST describe the memory required for this upgrade?	
	O A. SSD	Quick
	O B. SO-DIMM	Answer: 161
	O C. CMOS	The Details: 200
	O D. ECC	
B36.	A hospital would like to use a hands-free authentication system based on the user's proximity to the computer. Which of the following technologies would be the BEST choice for this system?	
	O A. NFC	Quick
	O B. 5G	Answer: 161
	O C. MDM	The Details: 201
	O D. SSD	
B37.	Daniel is building out a new floor of office space for his company. Which of the following cables would be the BEST choice to install in the active airspace above the drop ceiling?	
	O A. Plenum-rated	Quick
	O B. Shielded twisted-pair	Answer: 161
	O C. Coaxial	The Details: 202
	O D. PVC jacketed twisted-pair	111c 15 ctairs. 202
	2.1 v o jackotou twisted pair	

B38.	A developer is connecting a laptop to an LCD projector, but the projected image is flickering and occasionally part of the output will appear blocky and difficult to read Which of the following should resolve this issue? O A. Replace the projector's video cable O B. Turn the projector off and back on again O C. Update the laptop's video driver	Quick Answer: 161
	O D. Connect the laptop to a power source	The Details: 203
B39.	A graphics designer needs to connect their macOS computer to a second monitor and an external storage drive. Which of the following interface types would provide this connectivity?	
	O A. LightningO B. DisplayPort	Quick Answer: 161
	O C. DVI-D O D. Thunderbolt	The Details: 204
B40.	What cloud-based service provides hardware, but still requires the user to setup, configure, and manage the operating system and applications?	
	A. SaaSB. PaaS	Quick Answer: 161
	O C. IaaS O D. DaaS	The Details: 205
B41.	Which of the following would be MOST associated with a SAN?	
	O A. Bluetooth O B. RAID	Quick Answer: 161
	O C. APIPA O D. Cellular	The Details: 206

B42.	A network administrator is using a laptop computer to configure a switch over a direct cable connection. Which of the following would BEST describe this connectivity?	
	O A. Bluetooth	Quick
	O B. Thunderbolt	Answer: 161
	O C. Serial	The Details: 207
	O D. Lightning	The Details. 207
B43.	A manager in the accounting department is complaining of slow performance on her computer. Initial troubleshooting shows low utilization of CPU and memory. A network speed test reports normal throughput to the local network devices. Which of the following would be the BEST next step for troubleshooting this issue?	
	O A. Boot to Safe Mode	Quick
	O B. Upgrade the BIOS	Answer: 161
	O C. Replace the memory modules	The Details: 208
	O D. Perform a hard drive diagnostic	
B44.	A server administrator has moved a database server from a lab to a data center. After installing the server in a data center rack, the system does not power on. None of the system lights are on, and the power supply and cooling fans do not spin up. Which of the following should be the FIRST troubleshooting step for this issue?	
	O A. Replace the power supply	Quick
	O B. Reseat all of the internal components	Answer: 161
	O C. Check the power cable	The Details: 209
	O D. Replace the motherboard	
B45.	A user is traveling and has enabled airplane mode on their laptop, but they would still like to use their wireless headset. Which of these settings should be enabled to allow this functionality?	
	O A. Wi-Fi	Quick
	O B. USB	Answer: 161
	O C. Bluetooth	The Details: 210
	O D. Cellular	

	printer will not begin to print until the user has typed their PIN on the printer console. Which of the following would BEST describe this scenario?	;
	O A. Badging	Quick
	O B. Secured prints	Answer: 161
	O C. Active Directory	The Details: 211
	O D. ADF	
B47.	A system administrator has been asked to troubleshoot a non-operational print server. The printer displays an error code on the front panel and does not respond to any user input. The system administrator has created a list of four theories that might cause this particular error. Which of the following would be the best NEXT troubleshooting step?	
	O A. Test each theory on a lab system	Quick
	O B. Document the theories in the company	Answer: 161
	knowledgebase	The Details: 212
	O C. Try different theories on the print server until the problem is resolved	
	O D. Replace the print server device	
B48.	Which of these devices sends incoming traffic to every other port on the device?	
	O A. Router	Quick
	O B. Unmanaged switch	Answer: 161
	O C. Cable modem	The Details: 213
	O D. Hub	
B49.	Which of these wireless standards was the first to introduce 54 Mbit/sec throughput on the 2.4 GHz band?	
	O A. 802.11g	Quick
	O B. 802.11ac	Answer: 161
	O C. 802.11n	The Details: 214
	O D. 802.11b	

 $\boldsymbol{B46.}\ \boldsymbol{A}$ user has submitted a job to a network printer, but the

B50.	An organization has implemented a cloud solution using a third-party data center. Access to the cloud service is available to anyone on the Internet. Which of the following describes this deployment model?	
	O A. Hybrid O B. Public	Quick Answer: 161
	O C. CommunityO D. Private	The Details: 215
B51.	What voltages would be commonly found on a motherboard's power supply connector? O A. 120 V AC O B. 12 V AC, 5 V AC, 3.3 V AC O C. 12 V DC, 5 V DC, 3.3 V DC O D. 120 V DC	Quick Answer: 161 The Details: 216
B52.	A user is reporting this message on their Windows computer taskbar icon: "Limited or No connectivity." Which of the following would be the best NEXT troubleshooting step? O A. Check the local IP address configuration O B. Restart the computer O C. Ping the default gateway O D. Check the switch VLAN configuration O E. Check for a duplicate IP address	Quick Answer: 161 The Details: 217
B53.	What kind of device is installed into a computer and directly connects the computer to an Ethernet network? O A. NIC O B. Switch O C. Repeater O D. Bridge	Quick Answer: 161 The Details: 218

B54.	A network administrator is planning to connect the
	network of two buildings together with a Category 6A
	cable. Ten Ethernet cables have been run from a wiring
	closet, through a conduit, and into a wiring closet on the
	other side. The network administrator needs to identify
	the ends of the cables so they can be properly terminated
	on each side. Which of the following should be used to
	complete this task?

O A. Cable stripper
O B. Loopback plug

Quick
Answer: 161

O C. Tone generator The Details: 219

O D. Crimper

B55. A server administrator has configured a database server with a RAID 0 array containing four hard drives. An error notification from the RAID controller states that disk 3 has failed. Which of the following would be the BEST way to address this disk failure?

A. Replace the drive and re-mirror the array
 B. Replace the drive and resynchronize the array

Answer: 161

O C. Replace the drive and restore from backup

The Details: 220

O **D.** Replace all drives and restore from backup

O E. Replace all drives and resynchronize the array

B56. A company is installing a new communications link using SC interfaces. Which of the following would BEST describe this connection?

O A. Fiber optic
O B. USB-C
Quick
Answer: 161

O C. 10GBASE-T The Details: 221

O D. M.2

B57.	A server administrator has replaced a bad hard drive in a RAID array and has verified the array is operating with full functionality. Which of the following would be the best NEXT troubleshooting step?	
	 A. Run diagnostics on the bad hard drive B. Replace the RAID controller C. Create a list of optional troubleshooting steps D. Document the drive replacement 	Quick Answer: 161 The Details: 222
B58.	An application developer is designing an app which uses three servers running simultaneously as VMs on her desktop. An upgrade to the application will add three additional servers to the list of running VMs. Which of these hardware resources will be the MOST important for this upgrade? O A. Video adapter O B. Network connection O C. RAM O D. CPU	Quick Answer: 161 The Details: 223
B59.	A company has experienced a significant increase in printing costs over the last few months. Which of the following would provide the best way to track and manage these costs? O A. Audit logs O B. Print spooler uptime O C. Power usage monitor O D. Packet captures	Quick Answer: 161 The Details: 224

B60. A network engineer is troubleshooting an issue communicating to the Internet over a newly installed DSL connection. A laptop is connected to a DSL router over twisted pair copper. The IP configuration of the laptop is:

IP address: 169.254.228.109 Subnet mask: 255.255.0.0

DNS: 9.9.9.9

Which of the following should be the NEXT troubleshooting step?

O A. Reset the DSL modem

Quick
Answer: 161

O **B.** Modify the subnet mask

O C. Change the DNS server address

The Details: 225

O D. Check the status of the DHCP server

B61. A user in the accounting department has configured their mobile phone as a hotspot. Which of these would BEST describe this configuration?

O **A.** Use the phone as a method of payment Quick
O **B.** Fast-charge the phone

Quick
Answer: 161

O C. Access the Internet through the phone The Details: 226

O D. Connect to external speakers

B62. A user has logged into their laptop using a fingerprint reader on the laptop's keyboard tray. Which of the following would BEST describe this technology?

O A. NFC
O B. GPS

Quick
Answer: 161

O C. Screen digitizer The Details: 227

O D. Biometrics

B63.	An organization has recently implemented a browser-based email system that requires no additional software on the user devices. Which of the following would describe this type of application?	
	O A. SaaS O B. IaaS O C. HaaS O D. PaaS	Quick Answer: 161 The Details: 228
B64.	What type of power supply can operate across countries using different voltages? O A. High-voltage O B. Primary O C. Modular O D. Auto switching	Quick Answer: 161 The Details: 229
B65.	A user is reporting after starting their desktop, they receive the message "Windows has detected an IP address conflict." Which of the following would be the BEST way to resolve this issue? O A. Replace the Ethernet patch cable O B. Enable DHCP on the workstation O C. Bounce the switch port O D. Reboot the default gateway	Quick Answer: 161 The Details: 230
B66.	Each time a user logs in, they must type their password and a random number from a smartphone app. Which of the following would BEST describe this process? O A. PRL update O B. Bluetooth pairing O C. NFC data transfer O D. Two-factor authentication	Quick Answer: 161 The Details: 231

B67.	Which of the following would be used to terminate a copper Ethernet patch cable?	
	O A. BNC O B. RS-232	Quick Answer: 161
	○ C. RJ45○ D. DB-9	The Details: 232
B68.	A technician has replaced a laser printer toner cartridge, but now the output does not appear as dark as the original toner cartridge. Which of the following would be the best way to address this issue?	
	A. Run a printer calibrationB. Replace the fuser	Quick Answer: 161
	O C. Use a laser printer maintenance kitO D. Clean the OPC drum	The Details: 233
B69.	A system administrator has just received a laptop previously sent out for repair. However, after powering on the computer, the laptop no longer responds to the stylus. Which of the following is the MOST likely reason for this issue?	
	A. The GPU requires an updated device driverB. The display needs a new inverter	Quick Answer: 161
	O C. The display needs to be paired to the laptop motherboard	The Details: 234
	O D. The digitizer is faulty	
B70.	A graphics designer has noticed that small dots on their screen remain a solid black color, even when the image should display a different color. Which of the following would describe this issue?	
	O A. Burn-in	Quick Answer: 161
	O B. Non-native resolutionO C. Incorrect data sourceO D. Dead pixel	The Details: 235

В/1.	A gaming enthusiast has upgraded his home computer from integrated graphics to a separate video adapter card. The computer operates as expected for web browsing and word processing applications. However, playing a game results in the system shutting down after a few minutes of operation. Which of the following would be the MOST likely component causing this issue?	
	O A. CPU	Quick
	O B. Power supply	Answer: 161
	O C. RAM	The Details: 236
	O D. SSD	
B72.	A network administrator has just installed a new access point in a downtown office building, but now users are reporting intermittent connectivity to the Internet. Which of the following would be the FIRST thing to check?	
	O A. SSID broadcast option	Quick
	O B. Firmware version	Answer: 161
	O C. MAC filter	The Details: 237
	O D. Channel interference levels	
B73.	A company would like to advertise a list of email servers authorized to send messages on their behalf. Which of the following would be the BEST way to provide this information?	
	O A. APIPA	Quick
	O B. Proxy server	Answer: 161
	O C. UTM	The Details: 238
	O D. SPF record	
B74.	A company assigns IP addresses automatically to each device, and those addresses will remain on the device for a minimum of 8 hours. Which of the following BEST describes this configuration?	
	O A. Subnet mask	Quick
	O B. Lease	Answer: 161
	O C. SDN	The Details: 239
	O D. Reservation	

B75.	Users in the marketing department are reporting that one network printer is not working. There are many print jobs in the queue, but none of the jobs are printing. A test print from the printer's front panel does not print any pages. What is the MOST likely reason for this printing issue?	
	O A. Printer drivers need to be updated	Quick
	O B. Network is disconnected	Answer: 161
	O C. Printer hardware has failed	The Details: 240
	O D. Print spooler needs to be restarted	
B76.	A member of the accounting department would like to work remotely while attending a conference in another city. Which of these technologies would BEST provide this functionality?	
	O A. VLAN	Quick
	O B. 802.11	Answer: 161
	O C. VPN	The Details: 241
	O D. PAN	
B77.	In which of the following situations would you be MOST likely to use a network tap?	
	O A. Attach an RJ45 connector to the end of an Ethernet cable	Quick Answer: 161
	O B. Capture packets from a network link	The Details: 242
	O C. Test packet loss on a router interface	
	O D. Locate a specific workstation connection on a punch-down block	
B78.	A digital graphics department has been using a SAN to store their image files. The team now reports that all of the files on the SAN are no longer accessible. Which of the following should be the FIRST thing to check on the SAN?	÷
	O A. RAID array status	Quick
	O B. CPU utilization	Answer: 161
	O C. Input voltage	The Details: 243
	O D. Cache hits	

- **B79.** A network administrator is installing a new access point between buildings. Which of the following would determine the usable frequencies and maximum signal strength for this connection?
 - O A. End User License Agreement Quick
 Answer: 161
 - O **B.** Type of data transferred
 - O C. Acceptable Use Policy The Details: 244
 - O D. Government regulations
- **B80.** A network administrator is pinging a site on the Internet and receives these results:

C:\Users\professor>ping 9.9.9.9

```
Pinging 9.9.9.9 with 32 bytes of data:

Reply from 9.9.9.9: bytes=32 time=618ms TTL=128

Reply from 9.9.9.9: bytes=32 time=816ms TTL=128

Reply from 9.9.9.9: bytes=32 time=627ms TTL=128

Reply from 9.9.9.9: bytes=32 time=727ms TTL=128

Ping statistics for 9.9.9:

Packets: Sent = 4, Received = 4, Lost = 0 (0% loss),

Approximate round trip times in milli-seconds:

Minimum = 618ms, Maximum = 816ms, Average = 697ms
```

Which of the following would BEST describe these state of this network connection?

- O A. Dropped packets
- O **B.** Excessive latency
- O C. Port flapping
- O **D.** Network loop

Quick Answer: **161**

The Details: 245

B81.	A system administrator needs to upgrade the hard drives in a RAID array. Which of the following would be the BEST measurement of read and write times on the new hard drives?	
	O A. S. M. A. R. T.	Quick Answer: 161
	O B. Jitter	
	O C. IOPS	The Details: 247
	O D. RPM	
B82.	A user in the marketing department is printing to a color printer, but the colors on the output don't match the colors on the screen. Which of the following would be the BEST next step?	
	O A. Replace the ink or toner	Quick Answer: 161
	O B. Calibrate the monitor and printer	Allswel. 101
	O C. Restart the print spooler	The Details: 248
	O D. Configure the printer for PostScript	
B83.	A user's desktop computer does not start in the morning when the power button is pressed. A technician notices that the screen remains dark, but fans are spinning inside of the computer case. No messages are displayed and no beeps are heard. Which of the following would be the MOST likely reason for this issue?	
	O A. Faulty RAM	Quick
	O B. No boot drive found	Answer: 161
	O C. The CPU is overheating	The Details: 249
	O D. Bad power supply	
B84.	A user in the shipping department needs a charging cable for their Android phone. Which of the following connectors would be the MOST likely to work on this phone?	
	O A. USB-C	Quick
	O B. Lightning	Answer: 161
	O C. RJ45	The Details: 250
	O D. Thunderbolt	

B85.	A company has installed a page scanner that outputs the scanned files to SMB. Which of the following would be the MOST likely destination for these scanned images?	
	O A. Cloud storageO B. Windows share	Quick Answer: 161
	C. eSATA driveD. Network printer	The Details: 251
	O E. Email inbox	
B86.	A workstation administrator has been asked to troubleshoot an issue with Internet connectivity on a laptop computer. The network status in the taskbar shows a yellow exclamation mark with the message "No Internet access." When examining the Ethernet connection on the laptop, the cable sheath is an inch short and individual copper wires are visibly disconnected from the RJ45 connector. Which of the following should be used to correct this issue?	
	O A. Crimper O B. Punch-down tool	Quick Answer: 161
	O C. Loopback plugO D. Cable tester	The Details: 252
B87.	A network administrator needs to connect two sites located on opposite sides of the city. Which of these network connections would be the MOST appropriate?	
	O A. MAN	Quick
	O B. PAN	Answer: 161
	O C. LAN	The Details: 253
	O D. WAN	

B88.	Which of the following would be the BEST way to remove toner and paper dust from the inside of a laser printer?	
	O A. Use a chemical cleaner that removes toner particles	Quick Answer: 161
	O B. Run a cleaning page through the printer	The Details: 254
	O C. Wipe the inside with a damp cloth	
	O D. Use compressed air to blow out the particles	
B89.	A system administrator is connecting a remote site to the Internet over a single pair of copper wires. Which of the following is the administrator using for this installation? O A. PoE switch O B. Hub O C. DSL modem O D. ONT	Quick Answer: 161 The Details: 255
B90.	Which of the following would most commonly be associated with a thermal pad?	
	O A. Connect a heat sink to a processorO B. Install a fan in a desktop computer case	Quick Answer: 161
	 C. Mount a radiator for liquid cooling D. Manage CPU speed based on the current temperature 	The Details: 256

Practice Exam B Multiple Choice Quick Answers

B6. A	B36. A
B7. D	B37. A
B8. C	B38. A
B9. A	B39. D
B10. B	B40. C
B11. A	B41. B
B12. C	B42. C
B13. D	B43. D
B14. A	B44. C
B15. B	B45. C
B16. D	B46. B
B17. D	B47. A
B18. D	B48. D
B19. B	B49. A
B20. C	B50. B
B21. B	B51. C
B22. D	B52. A
B23. B	B53. A
B24. C	B54. C
B25. B	B55. C
B26. B	B56. A
B27. D	B57. D
B28. C and F	B58. C
B29. B	B59. A
B30. C	B60. D
B31. C	B61. C
B32. A	B62. D
В33. В	B63. A

B34. B

B35. B

B36. A	B66. D
B37. A	B67. C
B38. A	B68. A
B39. D	B69. D
B40. C	B70. D
B41. B	B71. B
B42. C	B72. D
B43. D	B73. D
B44. C	B74. B
B45. C	B75. C
B46. B	B76. C
B47. A	B77. B
B48. D	B78. A
B49. A	B79. D
B50. B	B80. B
B51. C	B81. C
B52. A	B82. B
B53. A	B83. D
B54. C	B84. A
B55. C	B85. B
B56. A	B86. A
B57. D	B87. A
B58. C	B88. C
B59. A	B89. C
B60. D	B90. A
B61. C	
D (a D	

B64. D

B65. B