

SENSOR INPUT




CELL MEASUREMENT / BALANCING INPUT




https://uk.rs-online.com/web/p/non-resettable-fuses/5413552?gb=s


ADC + DIGITAL OUT INPUT




MUX SWITCHES



5V TO 3V3 CONVERSION




3V3 REGULATOR



H1 MountingHole_Pad H3 MountingHole_Pad H4 MountingHole_Pad

12V ISOLATED POWER OUTPUT REGULATOR



Sheet: /		
File: BMS-Mu	x-PCB.kicad_sch	
Title:		
Size: A3	Date:	Rev:
KiCad E.D.A.	3.0.9	ld: 1/1
·	7	8