


SENSOR INPUT




CELL MEASUREMENT / BALANCING INPUT




ADC + DIGITAL OUT INPUT




MUX SWITCHES



5V TO 3V3 CONVERSION



3V3 REGULATOR



H1 MountingHole_Pad H3 MountingHole_Pad H4 MountingHole_Pad

12V ISOLATED POWER OUTPUT REGULATOR

