

Sprint_9_8_1_For_11423_API_Retour_Prog

Execution time
2024-04-25 9:15:25 AM
Operating system
Windows 11 64bit
Bun configuration name

Run configuration name TestRun

Computer name
DELPHI11
Screen dimension
1920x1080
Username

Language en-US Duration 3.5m

080 3.5i

Total warnings

Total errors

1

0

User

Table of Contents

[SETUP]	 2
■ InitCworkWlthPrgs3 (CworkTestLib)	 2
■ InitNewWorkingInWindows (CworkTestLib)	2
NewWorkingDirServerAndAccess (CworkTestLib)	2
■ CreateFilesToImport2 (CworkTestLib)	 5
StartCwork (CworkTestLib)	 5
■ LogUser (CworkTestLib)	 5
LogUser (CworkTestLib)CreateNewCnc (CworkTestLib)	 6
■ ImportPrgFromFaoFolder (CworkTestLib)	6
QuitCworkWithMenu (CworkTestLib)	 7
■ StartCwork (CworkTestLib)	 7
StartCwork (CworkTestLib)LogUser (CworkTestLib)	 7
■ StopStartCworkService (CworkTestLib)	7
■ ConfigCncAsFanucRs232 (CworkTestLib)	 8

Global Parameters:

Cwork: C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe

CworkUsr: Administrateur

CworkPsw:

QuitPos: 11

CworkDir: C:\Program Files (x86)\Smcom Software\Cwork\bin

CworkTravail: C:\CworkTestAuto

CworkNbPrg: 1

CworkProcessId:

ComPC: ComPC

CApi: CApi

Time

SETUP

3.5m

+

InitCworkWlthPrgs3 (CworkTestLib)

Level

1.8m

+

■ InitNewWorkingInWindows (CworkTestLib)

794ms

+

Category Message 00:00.224 Info UserCode Run RunProgramAndWait C:\Users\User\Documents\cwork\Cwork80\tst\TestCwork\Sprint-9 $\verb|_8_1\bin\Debug\\|.....\TestPrep\CleanCworkWorkingDir.bat|$

NewWorkingDirServerAndAccess (CworkTestLib)

43.91s

Time	Level	Category	Message
00:01.015	Info	Data	Current variable values:
			\$AppToRun = 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe', \$AppWorkingDir = 'C:\Program Files (x86)\Smcom Software\Cwork\bin', \$CworkWorkingDir = 'C:\CworkTestAuto'
00:01.067	Info	Application	Run application 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe' with arguments '/WIZARD' in normal mode.
00:01.319	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptDataDir' at Center.
00:03.558	Info	Keyboard	Key 'Ctrl+A' Press with focus on 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptDataDir'.
00:03.832	Info	Keyboard	Key sequence from variable '\$CworkWorkingDir' with focus on 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptDataDir'.

Delay Waiting for 5s.				
October Content Con	00:04.594	Info	Delay	
Key sequence Smcorm' with focus on CworkAsstantConfig AssistantDeConfigurationDeCWork Panel3.O ptSociety*.				Waiting for 5s.
CworkAssitantConfig AssistantDeConfigurationDeCWork.Panel3.0 ptSociety.	00:09.631	Info	Keyboard	. 3 ,
CworkAssiantConfig AssistantDeConfigurationDeCWork.Panel3.0 ptPartnerID¹ at 36;14. CworkAssiantConfig AssistantDeConfigurationDeCWork.Panel3.0 ptSociety1*.				'Cwork Assistant Config. Assistant De Configuration De CWork. Panel 3. O
CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.0 ptSociety1*. Continued of the provided of th	00:10.074	Info	Mouse	'Cwork Assistant Config. Assistant De Configuration De CWork. Panel 3. O
Image: Contract of	00:10.866	Info	Validation	'Cwork Assistant Config. Assistant De Configuration De CWork. Panel 3.0
CovorkAssitantConfig AssistantDeConfigurationDeCWork.Panel3.B Next* at Center. 00:12.032 Info Validation Validating AttributeEqual (Text='Selectionner la fonction de votre ordinateur') on item 'CworkAssitantConfig StartWizardForm.SelectionnerLaFonctionDeV otreOrdina'. 00:12.473 Success Validation Attribute "Text" of element for item 'CworkTestLibRepository.CworkAssitantConfig.StartWizardForm.SelectionnerLaFonctionDeVotreOrdina' does match the specified value. 00:12.607 Info Mouse Select Server Mouse Left Click item 'CworkAssitantConfig AssistantDeConfigurationDeCWork.Panel3.Bt nServeur' at Center. Validating Exists on item 'CworkAssitantConfig AssistantDeConfigurationDeCWork.Panel3.B Next'. 00:13.400 Success Validation Element for item 'BNext' does exist. 00:13.501 Info Mouse Mouse Left Click item 'CworkAssitantConfig AssistantDeConfigurationDeCWork.Panel3.B Next' at Center. 00:14.091 Info Validation Information server displayed 'Validating Exists on item 'CworkAssitantConfig AssistantDeConfigurationDeCWork.Panel3.B Next'. 00:14.322 Success Validation Element for item 'BNext' does exist. 00:14.372 Info Mouse Mouse Left Click item 'CworkAssitantConfig AssistantDeConfigurationDeCWork.Panel3.B Next'.		Success	Validation	'CworkTestLibRepository.CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.OptSociety1' does match the specified
ordinateur') on item 'CworkAssitantConfig.StartWizardForm.SelectionnerLaFonctionDeV otreOrdina'. O:12.473 Success Validation Attribute 'Text' of element for item 'CworkAssitantConfig.StartWizardForm.Sel ectionnerLaFonctionDeVotreOrdina' does match the specified value. O:12.607 Info Mouse Select Server Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.Bt nServeur' at Center. O:13.242 Info Validation Server selected Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'. O:13.460 Success Validation Element for item 'BNext' does exist. O:13.501 Info Mouse Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center. O:14.091 Info Validation Information server displayed Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center. O:14.091 Validation Element for item 'BNext' does exist. Element for item 'BNext' does exist. O:14.322 Success Validation Element for item 'BNext' does exist. O:14.332 Info Mouse Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'. O:14.372 Info Mouse Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B	00:11.386	Info	Mouse	'Cwork Assistant Config. Assistant De Configuration De CWork. Panel 3.B
VeworkTestLibRepository.CworkAssitantConfig.StartWizardForm.Sel ectionnerLaFonctionDeVotreOrdina' does match the specified value. 00:12.607 Info Mouse Select Server Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.Bt nServeur' at Center. Oction 13.242 00:13.242 Info Validation Server selected Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'. Next'. 00:13.460 Success Validation Element for item 'BNext' does exist. 00:13.501 Info Mouse Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center. 00:14.091 Info Validation Information server displayed Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'. Next'. 00:14.322 Success Validation Element for item 'BNext' does exist. 00:14.372 Info Mouse Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B	00:12.032	Info	Validation	ordinateur') on item 'CworkAssitantConfig.StartWizardForm.SelectionnerLaFonctionDeV
Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.Bt nServeur' at Center. O0:13.242 Info Validation Server selected Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'. O0:13.460 Success Validation Element for item 'BNext' does exist. O0:13.501 Info Mouse Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center. O0:14.091 Info Validation Information server displayed Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'. O0:14.322 Success Validation Element for item 'BNext' does exist. O0:14.372 Info Mouse Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B	00:12.473	Success	Validation	'Cwork Test Lib Repository. Cwork Assitant Config. Start Wizard Form. Selection ner La Fonction De Votre Ordina' does match the specified
'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.Bt nServeur' at Center. 00:13.242 Info Validation Server selected Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'. Next'. 00:13.460 Success Validation Element for item 'BNext' does exist. 00:13.501 Info Mouse Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center. 00:14.091 Info Validation Information server displayed Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'. Next'. 00:14.322 Success Validation Element for item 'BNext' does exist. 00:14.372 Info Mouse Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B	00:12.607	Info	Mouse	Select Server
Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'. 00:13.460 Success Validation Element for item 'BNext' does exist. 00:13.501 Info Mouse Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center. 00:14.091 Info Validation Information server displayed Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'. Next'. 00:14.322 Success Validation Element for item 'BNext' does exist. 00:14.372 Info Mouse Mouse Left Click item 'CworkAssitantDeConfigurationDeCWork.Panel3.B				'Cwork Assistant Config. Assistant De Configuration De CWork. Panel 3. Bt
'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'. 00:13.460 Success Validation Element for item 'BNext' does exist. 00:13.501 Info Mouse Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center. 00:14.091 Info Validation Information server displayed Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'. 00:14.322 Success Validation Element for item 'BNext' does exist. 00:14.372 Info Mouse Mouse Left Click item 'CworkAssitantDeConfigurationDeCWork.Panel3.B	00:13.242	Info	Validation	Server selected
O0:13.501 Info Mouse Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center. 00:14.091 Info Validation Information server displayed Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'. 00:14.322 Success Validation Element for item 'BNext' does exist. 00:14.372 Info Mouse Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B				'Cwork Assistant Config. Assistant De Configuration De CWork. Panel 3.B
'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center. 00:14.091 Info Validation Information server displayed Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'. Next'. 00:14.322 Success Validation Element for item 'BNext' does exist. 00:14.372 Info Mouse Mouse Left Click item 'CworkAssitantDeConfigurationDeCWork.Panel3.B		Success	Validation	Element for item 'BNext' does exist.
Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'. 00:14.322 Success Validation Element for item 'BNext' does exist. ○ 00:14.372 Info Mouse Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B	00:13.501	Info	Mouse	'Cwork Assistant Config. Assistant De Configuration De CWork. Panel 3.B
'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'. 00:14.322 Success Validation Element for item 'BNext' does exist. ○ 00:14.372 Info Mouse Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B	00:14.091	Info	Validation	Information server displayed
00:14.372 Info Mouse Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B				'Cwork Assistant Config. Assistant De Configuration De CWork. Panel 3.B
'Cwork Assistant Config. Assistant De Configuration De CWork. Panel 3.B.	00:14.322	Success	Validation	Element for item 'BNext' does exist.
	00:14.372	Info	Mouse	'Cwork Assistant Config. Assistant De Configuration De CWork. Panel 3.B

00:14.992	Info	Validation	Choix base displayed
			Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:15.203	Success	Validation	Element for item 'BNext' does exist.
00:15.250	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.
00:15.870	Info	Mouse	Choix attelier
			Mouse Left Click item 'CworkAssitantConfig.StartWizardForm.BAddSupervision' at Center.
00:16.830	Info	Keyboard	Enter name of workshop
			Key sequence 'Atelier1' with focus on 'None.TEdit'.
00:17.408	Info	Mouse	Mouse Left Click item 'None.ButtonOK' at 32;13.
00:17.997	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:18.223	Success	Validation	Element for item 'BNext' does exist.
00:18.246	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 0;0.
00:18.864	Info	Mouse	Choix profil
			Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.Pr ogStatusBox' at 391;17.
00:19.769	Info	Mouse	Mouse Left Click item 'None.FrenchMecaniqueGenerale' at 88;6.
00:20.274	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:20.518	Success	Validation	Element for item 'BNext' does exist.
00:20.561	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 47;13.
00:21.209	Info	Mouse	Choix mode DNC PROD
			Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.C bProfil' at 389;13.
00:22.049	Info	Mouse	Mouse Left Click item 'None.DNCPlusSuiviDeProduction' at Center.
00:22.557	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:22.806	Success	Validation	Element for item 'BNext' does exist.
00:22.842	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 44;13.

00:23.462	Info	Mouse	Choix type de démargae Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.D emarrerAvecPageLogin' at 7;8.
00:24.368	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:24.600	Success	Validation	Element for item 'BNext' does exist.
00:24.624	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 49;12.
00:25.242	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Close'.
00:25.460	Success	Validation	Element for item 'BClose' does exist.
00:25.499	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Close' at Center.
00:26.117	Info	Wait	Waiting 30s to not exist. Associated repository item: 'CworkAssitantConfig.AssistantDeConfigurationDeCWork'
00:34.855	Info	Delay	Waiting for 10s.

○ CreateFilesToImport2 (CworkTestLib)

166ms

Time	Level	Category	Message
00:44.926	Info	UserCode	Run RunProgramAndWait C:\Users\User\Documents\cwork\Cwork80\tst\TestCwork\Sprint-9 _8_1\bin\Debug\\\\TestPrep\genfic2.bat

StartCwork (CworkTestLib)

72ms **T**

Time	Level	Category	Message
00:45.096	Info	Data	Current variable values:
			\$AppToRun = 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe'
00:45.131	Info	Application	Run application with file name from variable \$AppToRun with arguments '/TEST' in normal mode.

Q LogUser (CworkTestLib)

16.88s **▼**

Time	Level	Category	Message
00:45.171	Info	Data	Current variable values:
			\$User = 'Administrateur', \$UserPsw = ''

00:45.220	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ComboUser' at 281;7.
00:46.802	Info	Keyboard	Key sequence '{Down}' with focus on 'None'.
00:47.040	Info	Keyboard	Key sequence '{Return}' with focus on 'None'.
00:47.350	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.EdPassword' at Center.
00:47.799	Info	Keyboard	Key sequence from variable '\$UserPsw' with focus on 'CworkMainForm.OuvertureDeSessionCWork.EdPassword'.
00:48.110	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ElementBOk' at 17;20.
00:48.582	Info	Wait	Waiting 3m to exist. Associated repository item: 'CworkMainForm.Atelier1'
01:00.761	Info	Validation	Validating AttributeEqual (Text='Atelier1') on item 'CworkMainForm.Atelier1'.
01:01.910	Success	Validation	Attribute 'Text' of element for item 'CworkTestLibRepository.CworkMainForm.Atelier1' does match the specified value.

⊙ CreateNewCnc (CworkTestLib)

1.94s **↑**

Time	Level	Category	Message
01:02.057	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.BAdd' at 75;14.
01:03.302	Info	Mouse	Mouse Left Click item 'AjoutDeCNCS.BAdd' at 19;10.

○ ImportPrgFromFaoFolder (CworkTestLib)

44.72s

Time	Level	Category	Message
01:03.993	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.MenuItemFichier' at 29;11.
01:10.614	Info	Mouse	Mouse Left Click item 'CworkMainForm.Cwork.MenuItem1' at 64;16.
01:11.116	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.OptImportFolder' at 17;11.
01:12.083	Info	Keyboard	Key sequence 'C:\CworkTestAuto\ImportFAO' with focus on 'ImportationDunDocumentOuDunDossier.OptImportFolder'.
01:13.112	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.Button1' at 8;12.
01:13.894	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.Cnc1' at 15;8.
01:14.648	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.ButtonOK' at 44;13.
01:15.335	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.ElementBOk' at 92;14.
01:47.085	Info	Wait	Waiting 4m to not exist. Associated repository item: 'ImportationDunDocumentOuDunDossier'
01:47.136	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.StationsTiles' at 671;296.

• QuitCworkWithMenu (CworkTestLib)

2.03s **T**

Time	Level	Category	Message
01:48.714	Info	Data	Current variable values:
			\$QuitItemNum = '11'
01:48.766	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.MenultemFichier' at Center.
01:50.241	Info	Mouse	Mouse Left Click item 'CworkMainForm.Cwork.MenuItemQuit' at 58;14.

StartCwork (CworkTestLib)

158ms

Time	Level	Category	Message
01:50.755	Info	Data	Current variable values:
			\$AppToRun = 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe'
01:50.822	Info	Application	Run application with file name from variable \$AppToRun with arguments '/TEST' in normal mode.

Q LogUser (CworkTestLib)

14.1s **★**

Time	Level	Category	Message
01:50.913	Info	Data	Current variable values:
			\$User = 'Administrateur', \$UserPsw = ''
01:50.969	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ComboUser' at 281;7.
01:52.587	Info	Keyboard	Key sequence '{Down}' with focus on 'None'.
01:52.835	Info	Keyboard	Key sequence '{Return}' with focus on 'None'.
01:53.084	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.EdPassword' at Center.
01:53.550	Info	Keyboard	Key sequence from variable '\$UserPsw' with focus on 'CworkMainForm.OuvertureDeSessionCWork.EdPassword'.
01:53.850	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ElementBOk' at 17;20.
01:54.303	Info	Wait	Waiting 3m to exist. Associated repository item: 'CworkMainForm.Atelier1'
02:03.796	Info	Validation	Validating AttributeEqual (Text='Atelier1') on item 'CworkMainForm.Atelier1'.
02:04.861	Success	Validation	Attribute 'Text' of element for item 'CworkTestLibRepository.CworkMainForm.Atelier1' does match the specified value.

StopStartCworkService (CworkTestLib)

Redémarage de Compc afin de contourner un bug

Time	Level	Category	Message
02:05.050	Info	Data	Current variable values:
			\$CworkServiceName = 'ComPC'
02:05.095	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.MenuItemOutils' at 23;10.
02:06.552	Info	Mouse	Mouse Left Click item 'CworkMainForm.Cwork.MenuItem11' at 61;15.
02:07.019	Info	Mouse	Mouse Left Click item 'GestionDesServeursEtMoteurs.ActionsSurMoteurs' at 56;10.
02:08.239	Info	Mouse	Stop
			Mouse Left Click item 'GestionDesServeursEtMoteurs.BCStopCworkService' at 28;15.
02:09.300	Info	Wait	Waiting 30s for the attribute 'Enabled' to equal the specified value 'True'. Associated repository item: 'GestionDesServeursEtMoteurs.BStartCworkService'
02:10.504	Info	Mouse	Mouse Left Click item 'GestionDesServeursEtMoteurs.BStartCworkService' at 26;14.
02:11.488	Info	Validation	Validating AttributeEqual (Valid='True') on item 'GestionDesServeursEtMoteurs.BCStopCworkService'.
02:13.599	Success	Validation	Attribute 'Valid' of element for item 'CworkTestLibRepository.GestionDesServeursEtMoteurs.BCStopCworkService' does match the specified value.
02:13.735	Info	Delay	Waiting for 5s.
02:18.786	Info	Mouse	Mouse Left Click item 'GestionDesServeursEtMoteurs.Valider' at 53;15.
02:19.675	Info	Delay	Waiting for 3s.

○ ConfigCncAsFanucRs232 (CworkTestLib)

1.1m

Time	Level	Category	Message
02:22.740	Info	Mouse	Mouse Left Click item 'CworkMainForm1.Cnc1' at Center.
02:24.051	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.BProperty' at Center.
02:25.241	Info	Mouse	Choix du type deconfiguration à Fanuc RS232
			Mouse Left Click item 'ChoixDuneConfiguration.ListItemDefaultFanucRS232' at 54;6.
02:27.489	Info	Mouse	Mouse Left Click item 'ChoixDuneConfiguration.ElementBOk' at 54;16.
02:28.238	Info	Mouse	Config de la partie RS232
			Mouse Left Click item 'ProprietesPourCnc1.RS232' at 22;7.
02:29.426	Info	Mouse	Mouse Left Click item 'ProprietesPourCnc1.SomeButton' at 6;10.
02:30.960	Info	Mouse	Choix de Com2
			Mouse Left Click item 'List1000.COM2' at 24;4.

03:31.078	Error	Module	Failed to find item 'CworkTestLibRepository.List1000.COM2'. Please check that your whitelist allows Ranorex to access the process.
			No element found for path '/list[@controlid='1000']/listitem[@text='COM2']' at step 'list[@controlid='1000']' after 749 attempts within 1m.