

### Sprint\_9\_8\_4\_For\_12026\_CreateMultipleDocs\_SETUP\_ONLY

Execution time Computer name Language 23/10/2024 10:15:24 DELPHI11 en-US
Operating system Screen dimension Duration
Windows 11 64bit 1920x1080 2.3m
Run configuration name Username

User

0

Total warnings Total errors

0

#### **Table of Contents**

TestRun

[SETUP]	 2
■ InitCworkWIthPrgs3 (CworkTestLib)	 2
<ul><li>InitNewWorkingInWindows (CworkTestLib)</li></ul>	2
<ul><li>NewWorkingDirServerAndAccess (CworkTestLib)</li></ul>	2
<ul><li>CreateFilesToImport2 (CworkTestLib)</li></ul>	 5
StartCwork (CworkTestLib)	 5
<ul><li>LogUser (CworkTestLib)</li></ul>	6
■ CreateNewCnc (CworkTestLib)	 6
<ul><li>ImportPrgFromFaoFolder (CworkTestLib)</li></ul>	 6
<ul><li>QuitCworkWithMenu (CworkTestLib)</li></ul>	 7
■ StartCwork (CworkTestLib)	 7
■ LogUser (CworkTestLib)	 7
■ Create3AdditionalCNC	 8
■ AddManualPrograms	g

GI	obal Parame	eters:					
Cv	vork: C:\Program F	Files (x86)\Sm	ncom Software\Cwork	x\bin\Cwork.exe			
	vorkUsr: Administ						
	vorkPsw:						
	ıitPos: 11						
		ım Files (x86)	\Smcom Software\Cw	vork\bin			
	vorkTravail: C:\Cw						
	vorkNbPrg: 1						
	vorkProcessId:						
CA	<b>Api:</b> CApi						
	<b>c-2:</b> Cnc-2						
Pr	gName: Prg1_2						
	iasName: Prg1_2_	ALIAS					
	oduleGroupApp:						
	oduleGroupRepT	ravail:					
	oduleGroupCwor						
	oduleGroupnbFile						
	· oduleGroupApplo						
	oduleGrouppsw:						
	ModuleGroupUser:						
	pToRun:						
Ap	pWorkingDir:						
_	vorkWorkingDir:						
SET	UP						
5	•				2.3m	<del>-</del>	
					2.5	-	
[0	InitCworkW	IthPrgs3 (C	(workTestLib)				
					1.8m	<del>+</del>	
П							
	<b>⊙</b> InitNewWo	orkingInWi	ndows (CworkTes	stLib)			
					5.79s	<b>†</b>	
	Time	Level	Category	Message			
	00:00.252	Info	UserCode	Run RunProgramAndWait			
				C:\Users\User\Documents\cwo			
				_8_4\bin\Debug\\\\TestPre	.p \cieaticwotkwotkitigD	ıı.vat	
	NewWorki	ingDirServe	erAndAccess (Cwo	orkTestLib)			
		9= 30, **		/	41.77s	<del>+</del>	
					41.775	,	
	Time	Level	Category	Message			

00:06.031	Info	Data	Current variable values:
			\$AppToRun = 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe', \$AppWorkingDir = 'C:\Program Files (x86)\Smcom Software\Cwork\bin', \$CworkWorkingDir = 'C:\CworkTestAuto'
00:06.070	Info	Application	Run application 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe' with arguments '/WIZARD' in normal mode.
00:06.316	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptDataDir' at Center.
00:08.582	Info	Keyboard	Key 'Ctrl+A' Press with focus on 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptDataDir'.
00:08.927	Info	Keyboard	Key sequence from variable '\$CworkWorkingDir' with focus on 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptDataDir'.
00:09.754	Info	Delay	wait empty compagny name
			Waiting for 5s.
00:14.793	Info	Keyboard	Enter compagny name
			Key sequence 'Smcom' with focus on 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptSociety'.
00:15.248	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptPartnerID' at 36;14.
00:16.051	Info	Validation	Validating AttributeEqual (Text='Smcom') on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptSociety1'.
00:16.488	Success	Validation	Attribute 'Text' of element for item 'CworkTestLibRepository.CworkAssitantConfig.AssistantDeConfigu rationDeCWork.Panel3.OptSociety1' does match the specified value.
00:16.636	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.
00:17.300	Info	Validation	Validating AttributeEqual (Text='Selectionner la fonction de votre ordinateur') on item 'CworkAssitantConfig.StartWizardForm.SelectionnerLaFonctionDeV otreOrdina'.
00:17.858	Success	Validation	Attribute 'Text' of element for item 'CworkTestLibRepository.CworkAssitantConfig.StartWizardForm.Sel ectionnerLaFonctionDeVotreOrdina' does match the specified value.
00:18.011	Info	Mouse	Select Server
			Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.Bt nServeur' at Center.
00:18.676	Info	Validation	Server selected
			Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:18.915	Success	Validation	Element for item 'BNext' does exist.

00:18.970	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.
00:19.583	Info	Validation	Information server displayed  Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:19.816	Success	Validation	Element for item 'BNext' does exist.
00:19.842	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.
00:20.487	Info	Validation	Choix base displayed  Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:20.745	Success	Validation	Element for item 'BNext' does exist.
00:20.782	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.
00:21.393	Info	Mouse	Choix attelier  Mouse Left Click item 'CworkAssitantConfig.StartWizardForm.BAddSupervision' at Center.
00:22.394	Info	Keyboard	Enter name of workshop  Key sequence 'Atelier1' with focus on 'None.TEdit'.
00:23.010	Info	Mouse	Mouse Left Click item 'None.ButtonOK' at 32;13.
00:23.620	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:23.829	Success	Validation	Element for item 'BNext' does exist.
00:23.874	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 0;0.
00:24.518	Info	Mouse	Choix profil  Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.Pr ogStatusBox' at 391;17.
00:25.336	Info	Mouse	Mouse Left Click item 'None.FrenchMecaniqueGenerale' at 88;6.
00:25.834	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:26.098	Success	Validation	Element for item 'BNext' does exist.
00:26.124	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 47;13.

I			
00:26.803	Info	Mouse	Choix mode DNC PROD
			Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.C bProfil' at 389;13.
00:27.741	Info	Mouse	Mouse Left Click item 'None.DNCPlusSuiviDeProduction' at Center.
00:28.212	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:28.474	Success	Validation	Element for item 'BNext' does exist.
00:28.498	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 44;13.
00:29.150	Info	Mouse	Choix type de démargae
			Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.D emarrerAvecPageLogin' at 7;8.
00:30.051	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:30.335	Success	Validation	Element for item 'BNext' does exist.
00:30.376	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 49;12.
00:30.996	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Close'.
00:31.263	Success	Validation	Element for item 'BClose' does exist.
00:31.314	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Close' at Center.
00:31.924	Info	Wait	Waiting 30s to not exist. Associated repository item: 'CworkAssitantConfig.AssistantDeConfigurationDeCWork'
00:37.743	Info	Delay	Waiting for 10s.

## **○ CreateFilesToImport2 (CworkTestLib)**

172ms **→** 

Time Level Category Message

00:47.804 Info UserCode Run RunProgramAndWait
C:\Users\User\Documents\cwork\Cwork80\tst\TestCwork\Sprint-9
\_8\_4\bin\Debug\..\..\..\..\TestPrep\genfic2.bat

### StartCwork (CworkTestLib)

77ms **1** 

Time Level Category Message

00:47.975	Info	Data	Current variable values:
			\$AppToRun = 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe'
00:48.002	Info	Application	Run application with file name from variable \$AppToRun with arguments '/TEST' in normal mode.

### **O** LogUser (CworkTestLib)

Time	Level	Category	Message
00:48.054	Info	Data	Current variable values:
			\$User = 'Administrateur', \$UserPsw = "
00:48.092	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ComboUser' at 281;7.
00:49.740	Info	Keyboard	Key sequence '{Down}' with focus on 'None'.
00:49.987	Info	Keyboard	Key sequence '{Return}' with focus on 'None'.
00:50.243	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.EdPassword' at Center.
00:50.707	Info	Keyboard	Key sequence from variable '\$UserPsw' with focus on 'CworkMainForm.OuvertureDeSessionCWork.EdPassword'.
00:50.997	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ElementBOk' at 17;20.
00:51.463	Info	Wait	Waiting 3m to exist. Associated repository item: 'CworkMainForm.Atelier1'
01:01.900	Info	Validation	Validating AttributeEqual (Text='Atelier1') on item 'CworkMainForm.Atelier1'.
01:03.346	Success	Validation	Attribute 'Text' of element for item 'CworkTestLibRepository.CworkMainForm.Atelier1' does match the specified value.

### **○** CreateNewCnc (CworkTestLib)

2.19s

Time	Level	Category	Message
01:03.488	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.BAdd' at 75;14.
01:04.923	Info	Mouse	Mouse Left Click item 'AjoutDeCNCS.BAdd' at 19;10.

# **○** ImportPrgFromFaoFolder (CworkTestLib)

41.98s

Time	Level	Category	Message
01:36.716	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.MenuItemFichier' at 29;11.
01:38.489	Info	Mouse	Mouse Left Click item 'CworkMainForm.Cwork.MenuItem1' at 64;16.

01:38.990	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.OptStatus' at 157;15.
01:39.972	Info	Mouse	Mouse Left Click item 'List1000.VALIDE' at 19;2.
01:40.426	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.OptImportFolder' at 17;11.
01:41.238	Info	Keyboard	Key sequence 'C:\CworkTestAuto\ImportFAO' with focus on 'ImportationDunDocumentOuDunDossier.OptImportFolder'.
01:42.254	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.Button1' at 8;12.
01:43.020	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.Cnc1' at 15;8.
01:43.800	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.ButtonOK' at 44;13.
01:44.590	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.ElementBOk' at 92;14.
01:45.368	Info	Wait	Waiting 4m to not exist. Associated repository item: 'ImportationDunDocumentOuDunDossier'
01:45.769	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.StationsTiles' at 671;296.

### QuitCworkWithMenu (CworkTestLib)

2.3s **T** 

Time	Level	Category	Message
01:47.658	Info	Data	Current variable values:
			\$QuitItemNum = '11'
01:47.689	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.MenuItemFichier' at Center.
01:49.489	Info	Mouse	Mouse Left Click item 'CworkMainForm.Cwork.MenuItemQuit' at 58;14.

## StartCwork (CworkTestLib)

120ms **∓** 

Time	Level	Category	Message
01:49.961	Info	Data	Current variable values:
			\$AppToRun = 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe'
01:50.034	Info	Application	Run application with file name from variable \$AppToRun with arguments '/TEST' in normal mode.

## **Q** LogUser (CworkTestLib)

15.21s **∓** 

Time	Level	Category	Message
01:50.081	Info	Data	Current variable values:
			\$User = 'Administrateur', \$UserPsw = "
01:50.126	Info	Mouse	Mouse Left Click item

01:51.769	Info	Keyboard	Key sequence '{Down}' with focus on 'None'.
01:52.018	Info	Keyboard	Key sequence '{Return}' with focus on 'None'.
01:52.262	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.EdPassword' at Center.
01:52.740	Info	Keyboard	Key sequence from variable '\$UserPsw' with focus on 'CworkMainForm.OuvertureDeSessionCWork.EdPassword'.
01:53.023	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ElementBOk' at 17;20.
01:53.490	Info	Wait	Waiting 3m to exist. Associated repository item: 'CworkMainForm.Atelier1'
02:03.742	Info	Validation	Validating AttributeEqual (Text='Atelier1') on item 'CworkMainForm.Atelier1'.
02:05.149	Success	Validation	Attribute 'Text' of element for item 'CworkTestLibRepository.CworkMainForm.Atelier1' does match the specified value.

## **○** Create3AdditionalCNC

11.55s **★** 

Time	Level	Category	Message
02:05.310	Info	Mouse	Mouse Left Click item 'CWork2024983.BAdd' at 72;26.
02:06.489	Info	Mouse	Mouse Left Click item 'AjoutDeCNCS.CNCCount' at 11;10.
02:07.237	Info	Keyboard	Key sequence '{Back}3' with focus on 'AjoutDeCNCS.CNCCount'.
02:07.652	Info	Mouse	Mouse Left Click item 'AjoutDeCNCS.BAdd' at 39;13.
02:08.407	Info	Validation	Validating AttributeEqual (RawText='Cnc-2') on item 'CWork2024983.Atelier1.Cnc2'.
02:15.090	Success	Validation	Attribute 'RawText' of element for item 'Sprint_9_8_4Repository.CWork2024983.Atelier1.Cnc2' does match the specified value.
02:15.234	Info	Validation	Validating AttributeEqual (RawText='Cnc-3') on item 'CWork2024983.Atelier1.Cnc3'.
02:15.970	Success	Validation	Attribute 'RawText' of element for item 'Sprint_9_8_4Repository.CWork2024983.Atelier1.Cnc3' does match the specified value.
02:16.105	Info	Validation	Validating AttributeEqual (RawText='Cnc-4') on item 'CWork2024983.Atelier1.Cnc4'.
02:16.700	Success	Validation	Attribute 'RawText' of element for item 'Sprint_9_8_4Repository.CWork2024983.Atelier1.Cnc4' does match the specified value.

## • AddManualPrograms

0ms 1

Time	Level	Category