

Sprint_9_8_4 Execution time Computer name Language 23/10/2024 09:21:34 DELPHI11 en-US Operating system Screen dimension Duration Windows 11 64bit 1920x1080 5.1m Run configuration name Username TestRun User Total warnings

0

Total errors

1

Table of Contents

[SETUP]	2
■ InitCworkWIthPrgs3 (CworkTestLib)	2
■ InitNewWorkingInWindows (CworkTestLib)	2
■ NewWorkingDirServerAndAccess (CworkTestLib)	
■ CreateFilesToImport2 (CworkTestLib)	
StartCwork (CworkTestLib)	5
LogUser (CworkTestLib) County No. County County (County No. County No. Coun	5
CreateNewCnc (CworkTestLib)	6
■ ImportPrgFromFaoFolder (CworkTestLib)	6
QuitCworkWithMenu (CworkTestLib)	7
StartCwork (CworkTestLib)	7
LogUser (CworkTestLib)	7
LogUser (CworkTestLib)CreateThreeCNC	8
StopStartCworkService (CworkTestLib)	8
■ AddDocumentsOnThreeCNC	٩

Global Parameters:

Cwork: C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe

CworkUsr: Administrateur

CworkPsw:

QuitPos: 11

CworkDir: C:\Program Files (x86)\Smcom Software\Cwork\bin

CworkTravail: C:\CworkTestAuto

CworkNbPrg: 1

CworkProcessId:

CApi: CApi

Cnc-2: Cnc-2

PrgName: Prg1_2

AliasName: Prg1_2_ALIAS

SETUP

+ 5.1m

InitCworkWIthPrgs3 (CworkTestLib)

1.8m

+

InitNewWorkingInWindows (CworkTestLib)

5.91s +

Time Level Category Message 00:00.249 Info UserCode Run RunProgramAndWait C:\Users\User\Documents\cwork\Cwork80\tst\TestCwork\Sprint-9 $\verb|_8_4\bin\Debug\\......\TestPrep\CleanCworkWorkingDir.bat|$

▶ NewWorkingDirServerAndAccess (CworkTestLib)

41.73s **→**

Time	Level	Category	Message
00:06.155	Info	Data	Current variable values:
			\$AppToRun = 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe', \$AppWorkingDir = 'C:\Program Files (x86)\Smcom Software\Cwork\bin', \$CworkWorkingDir = 'C:\CworkTestAuto'
00:06.200	Info	Application	Run application 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe' with arguments '/WIZARD' in normal mode.
00:06.441	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptDataDir' at Center.
00:08.874	Info	Keyboard	Key 'Ctrl+A' Press with focus on 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptDataDir'.

00:09.173	Info	Keyboard	Key sequence from variable '\$CworkWorkingDir' with focus on 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptDataDir'.
00:09.941	Info	Delay	wait empty compagny name
			Waiting for 5s.
00:14.985	Info	Keyboard	Enter compagny name
			Key sequence 'Smcom' with focus on 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptSociety'.
00:15.405	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptPartnerID' at 36;14.
00:16.213	Info	Validation	Validating AttributeEqual (Text='Smcom') on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptSociety1'.
00:16.663	Success	Validation	Attribute 'Text' of element for item 'CworkTestLibRepository.CworkAssitantConfig.AssistantDeConfigu rationDeCWork.Panel3.OptSociety1' does match the specified value.
00:16.797	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.
00:17.405	Info	Validation	Validating AttributeEqual (Text='Selectionner la fonction de votre ordinateur') on item 'CworkAssitantConfig.StartWizardForm.SelectionnerLaFonctionDeV otreOrdina'.
00:17.922	Success	Validation	Attribute 'Text' of element for item 'CworkTestLibRepository.CworkAssitantConfig.StartWizardForm.Sel ectionnerLaFonctionDeVotreOrdina' does match the specified value.
00:18.079	Info	Mouse	Select Server
			Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.Bt nServeur' at Center.
00:18.745	Info	Validation	Server selected
			Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:19.003	Success	Validation	Element for item 'BNext' does exist.
00:19.045	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.
00:19.684	Info	Validation	Information server displayed
			Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:19.912	Success	Validation	Element for item 'BNext' does exist.
00:19.945	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.

00:20.592	Info	Validation	Choix base displayed
			Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:20.825	Success	Validation	Element for item 'BNext' does exist.
00:20.848	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.
00:21.497	Info	Mouse	Choix attelier
			Mouse Left Click item 'CworkAssitantConfig.StartWizardForm.BAddSupervision' at Center.
00:22.475	Info	Keyboard	Enter name of workshop
			Key sequence 'Atelier1' with focus on 'None.TEdit'.
00:23.056	Info	Mouse	Mouse Left Click item 'None.ButtonOK' at 32;13.
00:23.692	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:23.948	Success	Validation	Element for item 'BNext' does exist.
00:23.976	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 0;0.
00:24.624	Info	Mouse	Choix profil
			Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.Pr ogStatusBox' at 391;17.
00:25.496	Info	Mouse	Mouse Left Click item 'None.FrenchMecaniqueGenerale' at 88;6.
00:25.997	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:26.251	Success	Validation	Element for item 'BNext' does exist.
00:26.287	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 47;13.
00:26.963	Info	Mouse	Choix mode DNC PROD
			Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.C bProfil' at 389;13.
00:27.805	Info	Mouse	Mouse Left Click item 'None.DNCPlusSuiviDeProduction' at Center.
00:28.337	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:28.590	Success	Validation	Element for item 'BNext' does exist.
00:28.630	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 44;13.

00:29.280	Info	Mouse	Choix type de démargae
			Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.D emarrerAvecPageLogin' at 7;8.
00:30.158	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:30.396	Success	Validation	Element for item 'BNext' does exist.
00:30.443	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 49;12.
00:31.088	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Close'.
00:31.330	Success	Validation	Element for item 'BClose' does exist.
00:31.382	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Close' at Center.
00:32.031	Info	Wait	Waiting 30s to not exist. Associated repository item: 'CworkAssitantConfig.AssistantDeConfigurationDeCWork'
00:37.848	Info	Delay	Waiting for 10s.

• CreateFilesToImport2 (CworkTestLib)

145ms

Time	Level	Category	Message
00:47.889	Info	UserCode	Run RunProgramAndWait C:\Users\User\Documents\cwork\Cwork80\tst\TestCwork\Sprint-9 _8_4\bin\Debug\\\\TestPrep\genfic2.bat

StartCwork (CworkTestLib)

79ms **∓**

Time	Level	Category	Message
00:48.034	Info	Data	Current variable values:
			\$AppToRun = 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe'
00:48.072	Info	Application	Run application with file name from variable \$AppToRun with arguments '/TEST' in normal mode.

Q LogUser (CworkTestLib)

14.9s **★**

Time	Level	Category	Message
00:48.119	Info	Data	Current variable values:
			\$User = 'Administrateur', \$UserPsw = ''

00:48.162	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ComboUser' at 281;7.
00:49.747	Info	Keyboard	Key sequence '{Down}' with focus on 'None'.
00:49.988	Info	Keyboard	Key sequence '{Return}' with focus on 'None'.
00:50.239	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.EdPassword' at Center.
00:50.754	Info	Keyboard	Key sequence from variable '\$UserPsw' with focus on 'CworkMainForm.OuvertureDeSessionCWork.EdPassword'.
00:51.037	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ElementBOk' at 17;20.
00:51.494	Info	Wait	Waiting 3m to exist. Associated repository item: 'CworkMainForm.Atelier1'
01:01.559	Info	Validation	Validating AttributeEqual (Text='Atelier1') on item 'CworkMainForm.Atelier1'.
01:02.888	Success	Validation	Attribute 'Text' of element for item 'CworkTestLibRepository.CworkMainForm.Atelier1' does match the specified value.

⊙ CreateNewCnc (CworkTestLib)

2.07s **★**

Time	Level	Category	Message
01:03.028	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.BAdd' at 75;14.
01:04.401	Info	Mouse	Mouse Left Click item 'AjoutDeCNCS.BAdd' at 19;10.

○ ImportPrgFromFaoFolder (CworkTestLib)

41.75s

Time	Level	Category	Message
01:36.180	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.MenuItemFichier' at 29;11.
01:37.903	Info	Mouse	Mouse Left Click item 'CworkMainForm.Cwork.MenuItem1' at 64;16.
01:38.371	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.OptStatus' at 157;15.
01:39.312	Info	Mouse	Mouse Left Click item 'List1000.VALIDE' at 19;2.
01:39.782	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.OptImportFolder' at 17;11.
01:40.558	Info	Keyboard	Key sequence 'C:\CworkTestAuto\ImportFAO' with focus on 'ImportationDunDocumentOuDunDossier.OptImportFolder'.
01:41.572	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.Button1' at 8;12.
01:42.342	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.Cnc1' at 15;8.
01:43.089	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.ButtonOK' at 44;13.
01:43.869	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.ElementBOk' at 92;14.

01:44.619	Info	Wait	Waiting 4m to not exist. Associated repository item: 'ImportationDunDocumentOuDunDossier'
01:45.041	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.StationsTiles' at 671;296.

QuitCworkWithMenu (CworkTestLib)

2.19s

Time	Level	Category	Message
01:46.844	Info	Data	Current variable values:
			\$QuitItemNum = '11'
01:46.881	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.MenultemFichier' at Center.
01:48.558	Info	Mouse	Mouse Left Click item 'CworkMainForm.Cwork.MenuItemQuit' at 58;14.

StartCwork (CworkTestLib)

79ms

†

Time	Level	Category	Message
01:49.035	Info	Data	Current variable values:
			\$AppToRun = 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe'
01:49.070	Info	Application	Run application with file name from variable \$AppToRun with arguments '/TEST' in normal mode.

■ LogUser (CworkTestLib)

14.78s **→**

Time Level Category Message 01:49.113 Info Data Current variable values: \$User = 'Administrateur', \$UserPsw = " 01:49.160 Info Mouse Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ComboUser' at 281;7. 01:50.811 Info Keyboard Key sequence '{Down}' with focus on 'None'. 01:51.060 Info Keyboard Key sequence '{Return}' with focus on 'None'. 01:51.299 Info Mouse Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.EdPassword' at 01:51.777 Info Keyboard Key sequence from variable '\$UserPsw' with focus on 'Cwork Main Form. Ouverture De Session CWork. Ed Password'.01:52.068 Info Mouse Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ElementBOk' at 17;20. 01:52.528 Info Wait Waiting 3m to exist. Associated repository item: 'CworkMainForm.Atelier1' 02:02.397 Info Validation Validating AttributeEqual (Text='Atelier1') on item

'CworkMainForm.Atelier1'.

02:03.746	Success	Validation	Attribute 'Text' of element for item
•			$\label{lem:condition} 'Cwork Test Lib Repository. Cwork Main Form. At elier 1' does match the specified value.$

⊙ CreateThreeCNC

2.88s **T**

Time	Level	Category	Message
02:03.900	Info	Mouse	Mouse Left Click item 'CWork2024983.TAdvSmoothToggleButton1' at 28;32.
02:04.714	Info	Mouse	Mouse Left Click item 'CWork2024983.BAdd' at 69;22.
02:05.746	Info	Keyboard	Key sequence '{Back}3' with focus on 'AjoutDeCNCS.CNCCount'.
02:06.112	Info	Mouse	Mouse Left Click item 'AjoutDeCNCS.BAdd' at 48;15.

StopStartCworkService (CworkTestLib)

22.92s **T**

demarage CAPI			
Time	Level	Category	Message
02:06.788	Info	Data	Current variable values:
			\$CworkServiceName = 'CApi'
02:06.820	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.MenuItemOutils' at 23;10.
02:13.529	Info	Mouse	Mouse Left Click item 'CworkMainForm.Cwork.MenuItemGererMoteur' at Center.
02:13.995	Info	Mouse	Mouse Left Click item 'GestionDesServeursEtMoteurs.ActionsSurMoteurs' at 56;10.
02:15.216	Info	Mouse	Stop
			Mouse Left Click item 'GestionDesServeursEtMoteurs.BCStopCworkService' at 28;15.
02:16.278	Info	Wait	Waiting 30s for the attribute 'Enabled' to equal the specified value 'True'. Associated repository item: 'GestionDesServeursEtMoteurs.BStartCworkService'
02:16.974	Info	Mouse	Mouse Left Click item 'GestionDesServeursEtMoteurs.BStartCworkService' at 26;14.
02:18.118	Info	Validation	Validating AttributeEqual (Valid='True') on item 'GestionDesServeursEtMoteurs.BCStopCworkService'.
02:20.448	Success	Validation	Attribute 'Valid' of element for item 'CworkTestLibRepository.GestionDesServeursEtMoteurs.BCStopCw orkService' does match the specified value.
02:20.581	Info	Delay	Waiting for 5s.
02:25.644	Info	Mouse	Mouse Left Click item 'GestionDesServeursEtMoteurs.Valider' at 53;15.
02:26.653	Info	Delay	Waiting for 3s.

○ AddDocumentsOnThreeCNC

2.6m **★**

Time	Level	Category	Message
02:29.707	Info	Mouse	Mouse Left Click item 'CWork2024983.TAdvSmoothToggleButton' at 27;41.
02:31.461	Info	Mouse	Mouse Left Click item 'CWork2024983.BNew' at 61;41.
02:32.851	Info	Mouse	Mouse Left Click item 'NouveauDocument.AQXDHOYA' at 25;30.
02:33.560	Info	Mouse	Mouse Left Click item 'NouveauDocument.ElementBOk' at 16;25.
02:34.280	Info	Mouse	Mouse Left Click item 'ProprietesDunDocument.TEditBtn' at 23;17.
02:35.403	Info	Keyboard	Key sequence 'prog1' with focus on 'ProprietesDunDocument.TEditBtn'.
02:35.847	Info	Mouse	Mouse Left Click item 'ProprietesDunDocument.Button' at 1;8.
02:36.558	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.Cnc1' at 19;9.
02:37.321	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.ButtonOK' at 37;7.
02:38.068	Info	Mouse	Mouse Left Click item 'ProprietesDunDocument.ElementBOK' at 40;11.
02:38.900	Info	Mouse	Mouse Left Click item 'CWork2024983.Prog1CNCA0EDITECnc1.BClose' at 101;16.
02:41.219	Info	Mouse	Mouse Left Click item 'CWork2024983.BNew' at 65;22.
02:42.027	Info	Mouse	Mouse Left Click item 'NouveauDocument.ProgrammeDusinage' at 9;6.
02:42.657	Info	Mouse	Mouse Left Click item 'NouveauDocument.ElementBOk' at 10;17.
02:43.369	Info	Mouse	Mouse Left Click item 'ProprietesDunDocument.TEditBtn' at 64;19.
02:44.494	Info	Keyboard	Key sequence 'prog2' with focus on 'ProprietesDunDocument.TEditBtn'.
02:44.999	Info	Mouse	Mouse Left Click item 'ProprietesDunDocument.Button' at 3;11.
02:45.713	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.Cnc2' at 12;7.
02:46.498	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.ButtonOK' at 19;4.
02:47.247	Info	Mouse	Mouse Left Click item 'ProprietesDunDocument.ElementBOK' at 36;4.
02:47.995	Info	Mouse	Mouse Left Down item 'CWork2024983.Prog1CNCA0EDITECnc1.BClose' at 66;23.
02:50.648	Info	Mouse	Mouse Left Up item 'CWork2024983.Prog1CNCA0EDITECnc1.BClose' at 72;29.
02:51.822	Info	Mouse	Mouse Left Click item 'CWork2024983.BNew' at 63;32.
02:52.654	Info	Mouse	Mouse Left Click item 'NouveauDocument.ProgrammeDusinage' at 31;4.
02:53.277	Info	Mouse	Mouse Left Click item 'NouveauDocument.ElementBOk' at 11;18.
02:53.967	Info	Mouse	Mouse Left Click item 'ProprietesDunDocument.TEditBtn' at 68;17.
02:55.059	Info	Keyboard	Key sequence 'prog3' with focus on 'ProprietesDunDocument.TEditBtn'.
02:55.536	Info	Mouse	Mouse Left Click item 'ProprietesDunDocument.Button' at 10;7.
02:56.215	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.Cnc3' at 19;4.
02:56.964	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.ButtonOK' at 20;18.
02:57.715	Info	Mouse	Mouse Left Click item 'CWork2024983.PartsView' at 735;487.
02:58.527	Info	Mouse	Mouse Left Click item 'CWork2024983.Prog1CNCA0EDITECnc1.BClose' at 37;40.
05:02.871	Error	Module	The test run has been aborted by the user.