

# Sprint\_9\_8\_4\_For\_12026\_CreateMultipleDocs\_SETUP\_ONLY

Execution time

23/10/2024 10:11:59

Operating system

Windows 11 64bit

Run configuration name

Computer name

Language

en-US

Screen dimension

Duration

1920x1080

2.3m

Username

Run configuration name Username TestRun User

Total warnings Total errors

0

0

#### **Table of Contents**

■ [SETUP]	2
<ul><li>InitCworkWlthPrgs3 (CworkTestLib)</li></ul>	2
■ InitNewWorkingInWindows (CworkTestLib)	2
<ul><li>NewWorkingDirServerAndAccess (CworkTestLib)</li></ul>	
CreateFilesToImport2 (CworkTestLib)	5
<ul><li>CreateFilesToImport2 (CworkTestLib)</li><li>StartCwork (CworkTestLib)</li></ul>	5
<ul><li>LogUser (CworkTestLib)</li></ul>	6
CreateNewCnc (CworkTestLib)	6
<ul><li>ImportPrgFromFaoFolder (CworkTestLib)</li></ul>	6
QuitCworkWithMenu (CworkTestLib)	
StartCwork (CworkTestLib)	7
LogUser (CworkTestLib)	7
■ Create3AdditionalCNC	8
AddManualPrograms.	8

Global Param	eters:					
Cwork: C:\Program	Files (x86)\S	mcom Software\Cwork	<\bin\Cwork.exe			
CworkUsr: Adminis	trateur					
CworkPsw:						
QuitPos: 11						
CworkDir: C:\Progra	am Files (x86	5)\Smcom Software\Cw	vork\bin			
CworkTravail: C:\C\	workTestAut	0				
CworkNbPrg: 1						
CworkProcessId:						
<b>CApi:</b> CApi						
<b>Cnc-2:</b> Cnc-2						
<b>PrgName:</b> Prg1_2						
AliasName: Prg1_2_	_ALIAS					
ModuleGroupApp:						
ModuleGroupRep1						
ModuleGroupCwo	rkDir:					
ModuleGroupnbFil	le:					
ModuleGroupAppl						
ModuleGrouppsw:						
ModuleGroupUsers						
AppToRun:						
AppWorkingDir:	AppWorkingDir:					
CworkWorkingDir:						
SETUP				2.3m	<del>-</del>	
<u>™</u> InitCworkW	/IthPrgs3 (	(CworkTestLib)		1.8m	<del>-</del>	
<b>⊙</b> InitNewW	orkingInV	Vindows (CworkTes	stLib)			
				5.77s	<b>T</b>	
Time	Level	Category	Message			
00:00.252	Info	UserCode	Run RunProgramAndWait C:\Users\User\Documents\cwor _8_4\bin\Debug\\\\TestPre			
<b>⊙</b> NewWork	kingDirSer	verAndAccess (Cwo	orkTestLib)	41.92s	<u>_</u>	
				41.325		
Time	Level	Category	Message			

00:06.019	Info	Data	Current variable values:
			\$AppToRun = 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe', \$AppWorkingDir = 'C:\Program Files (x86)\Smcom Software\Cwork\bin', \$CworkWorkingDir = 'C:\CworkTestAuto'
00:06.058	Info	Application	Run application 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe' with arguments '/WIZARD' in normal mode.
00:06.300	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptDataDir' at Center.
00:08.726	Info	Keyboard	Key 'Ctrl+A' Press with focus on 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptDataDir'.
00:09.001	Info	Keyboard	Key sequence from variable '\$CworkWorkingDir' with focus on 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptDataDir'.
00:09.784	Info	Delay	wait empty compagny name
			Waiting for 5s.
00:14.840	Info	Keyboard	Enter compagny name
			Key sequence 'Smcom' with focus on 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptSociety'.
00:15.296	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptPartnerID' at 36;14.
00:16.072	Info	Validation	Validating AttributeEqual (Text='Smcom') on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptSociety1'.
00:16.452	Success	Validation	Attribute 'Text' of element for item 'CworkTestLibRepository.CworkAssitantConfig.AssistantDeConfigu rationDeCWork.Panel3.OptSociety1' does match the specified value.
00:16.591	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.
00:17.257	Info	Validation	Validating AttributeEqual (Text='Selectionner la fonction de votre ordinateur') on item 'CworkAssitantConfig.StartWizardForm.SelectionnerLaFonctionDeV otreOrdina'.
00:17.813	Success	Validation	Attribute 'Text' of element for item 'CworkTestLibRepository.CworkAssitantConfig.StartWizardForm.Sel ectionnerLaFonctionDeVotreOrdina' does match the specified value.
00:17.970	Info	Mouse	Select Server
			Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.Bt nServeur' at Center.
00:18.633	Info	Validation	Server selected
			Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:18.885	Success	Validation	Element for item 'BNext' does exist.

00:18.924	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.
00:19.573	Info	Validation	Information server displayed  Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:19.878	Success	Validation	Element for item 'BNext' does exist.
00:19.926	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.
00:20.568	Info	Validation	Choix base displayed  Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:20.793	Success	Validation	Element for item 'BNext' does exist.
00:20.829	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.
00:21.477	Info	Mouse	Choix attelier  Mouse Left Click item 'CworkAssitantConfig.StartWizardForm.BAddSupervision' at Center.
00:22.509	Info	Keyboard	Enter name of workshop  Key sequence 'Atelier1' with focus on 'None.TEdit'.
00:23.081	Info	Mouse	Mouse Left Click item 'None.ButtonOK' at 32;13.
00:23.663	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:23.873	Success	Validation	Element for item 'BNext' does exist.
00:23.925	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 0;0.
00:24.541	Info	Mouse	Choix profil  Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.Pr ogStatusBox' at 391;17.
00:25.447	Info	Mouse	Mouse Left Click item 'None.FrenchMecaniqueGenerale' at 88;6.
00:25.954	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:26.233	Success	Validation	Element for item 'BNext' does exist.
00:26.269	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 47;13.

00:26.974	Info	Mouse	Choix mode DNC PROD
			Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.C bProfil' at 389;13.
00:27.851	Info	Mouse	Mouse Left Click item 'None.DNCPlusSuiviDeProduction' at Center.
00:28.319	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:28.583	Success	Validation	Element for item 'BNext' does exist.
00:28.610	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 44;13.
00:29.256	Info	Mouse	Choix type de démargae
			Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.D emarrerAvecPageLogin' at 7;8.
00:30.162	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:30.424	Success	Validation	Element for item 'BNext' does exist.
00:30.457	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 49;12.
00:31.083	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Close'.
00:31.348	Success	Validation	Element for item 'BClose' does exist.
00:31.394	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Close' at Center.
00:32.039	Info	Wait	Waiting 30s to not exist. Associated repository item: 'CworkAssitantConfig.AssistantDeConfigurationDeCWork'
00:37.884	Info	Delay	Waiting for 10s.

### **⊙** CreateFilesToImport2 (CworkTestLib)

182ms **∓** 

Time	Level	Category	Message
00:47.938	Info	UserCode	Run RunProgramAndWait C:\Users\User\Documents\cwork\Cwork80\tst\TestCwork\Sprint-9 _8_4\bin\Debug\\\\TestPrep\genfic2.bat

### **⊙** StartCwork (CworkTestLib)

108ms

|--|--|

00:48.121	Info	Data	Current variable values:
			\$AppToRun = 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe'
00:48.179	Info	Application	Run application with file name from variable \$AppToRun with arguments '/TEST' in normal mode.

### **O** LogUser (CworkTestLib)

Time	Level	Category	Message
00:48.229	Info	Data	Current variable values:
			\$User = 'Administrateur', \$UserPsw = ''
00:48.268	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ComboUser' at 281;7.
00:49.884	Info	Keyboard	Key sequence '{Down}' with focus on 'None'.
00:50.137	Info	Keyboard	Key sequence '{Return}' with focus on 'None'.
00:50.372	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.EdPassword' at Center.
00:50.851	Info	Keyboard	Key sequence from variable '\$UserPsw' with focus on 'CworkMainForm.OuvertureDeSessionCWork.EdPassword'.
00:51.144	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ElementBOk' at 17;20.
00:51.632	Info	Wait	Waiting 3m to exist. Associated repository item: 'CworkMainForm.Atelier1'
01:01.600	Info	Validation	Validating AttributeEqual (Text='Atelier1') on item 'CworkMainForm.Atelier1'.
01:02.956	Success	Validation	Attribute 'Text' of element for item 'CworkTestLibRepository.CworkMainForm.Atelier1' does match the specified value.

### **○** CreateNewCnc (CworkTestLib)

2.06s

Time	Level	Category	Message
01:03.098	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.BAdd' at 75;14.
01:04.505	Info	Mouse	Mouse Left Click item 'AjoutDeCNCS.BAdd' at 19;10.

# **○** ImportPrgFromFaoFolder (CworkTestLib)

41.87s **★** 

Time	Level	Category	Message
01:36.239	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.MenuItemFichier' at 29;11.
01:37.948	Info	Mouse	Mouse Left Click item 'CworkMainForm.Cwork.MenuItem1' at 64;16.

01:38.417	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.OptStatus' at 157;15.
01:39.447	Info	Mouse	Mouse Left Click item 'List1000.VALIDE' at 19;2.
01:39.950	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.OptImportFolder' at 17;11.
01:40.726	Info	Keyboard	Key sequence 'C:\CworkTestAuto\ImportFAO' with focus on 'ImportationDunDocumentOuDunDossier.OptImportFolder'.
01:41.757	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.Button1' at 8;12.
01:42.572	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.Cnc1' at 15;8.
01:43.350	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.ButtonOK' at 44;13.
01:44.069	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.ElementBOk' at 92;14.
01:44.882	Info	Wait	Waiting 4m to not exist. Associated repository item: 'ImportationDunDocumentOuDunDossier'
01:45.267	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.StationsTiles' at 671;296.

### • QuitCworkWithMenu (CworkTestLib)

2.19s

Time	Level	Category	Message
01:47.039	Info	Data	Current variable values:
			\$QuitItemNum = '11'
01:47.083	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.MenultemFichier' at Center.
01:48.758	Info	Mouse	Mouse Left Click item 'CworkMainForm.Cwork.MenuItemQuit' at 58;14.

### StartCwork (CworkTestLib)

134ms **→** 

Time	Level	Category	Message
01:49.234	Info	Data	Current variable values:
			\$AppToRun = 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe'
01:49.276	Info	Application	Run application with file name from variable \$AppToRun with arguments '/TEST' in normal mode.

### **Q** LogUser (CworkTestLib)

14.94s **▼** 

Time	Level	Category	Message
01:49.373	Info	Data	Current variable values:
			\$User = 'Administrateur', \$UserPsw = ''
			poser = /tarimistratear, poser sw =

01:51.039	Info	Keyboard	Key sequence '{Down}' with focus on 'None'.
01:51.282	Info	Keyboard	Key sequence '{Return}' with focus on 'None'.
01:51.527	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.EdPassword' at Center.
01:52.014	Info	Keyboard	Key sequence from variable '\$UserPsw' with focus on 'CworkMainForm.OuvertureDeSessionCWork.EdPassword'.
01:52.307	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ElementBOk' at 17;20.
01:52.788	Info	Wait	Waiting 3m to exist. Associated repository item: 'CworkMainForm.Atelier1'
02:02.919	Info	Validation	Validating AttributeEqual (Text='Atelier1') on item 'CworkMainForm.Atelier1'.
02:04.178	Success	Validation	Attribute 'Text' of element for item 'CworkTestLibRepository.CworkMainForm.Atelier1' does match the specified value.

### **○** Create3AdditionalCNC

12.53s **→** 

Time	Level	Category	Message
02:04.314	Info	Mouse	Mouse Left Click item 'CWork2024983.BAdd' at 72;26.
02:05.444	Info	Mouse	Mouse Left Click item 'AjoutDeCNCS.CNCCount' at 11;10.
02:06.193	Info	Keyboard	Key sequence '{Back up}3' with focus on 'AjoutDeCNCS.CNCCount'.
02:06.542	Info	Mouse	Mouse Left Click item 'AjoutDeCNCS.BAdd' at 39;13.
02:07.200	Info	Validation	Validating AttributeEqual (RawText='Cnc-2') on item 'CWork2024983.Atelier1.Cnc2'.
02:14.769	Success	Validation	Attribute 'RawText' of element for item 'Sprint_9_8_4Repository.CWork2024983.Atelier1.Cnc2' does match the specified value.
02:14.904	Info	Validation	Validating AttributeEqual (RawText='Cnc-3') on item 'CWork2024983.Atelier1.Cnc3'.
02:15.724	Success	Validation	Attribute 'RawText' of element for item 'Sprint_9_8_4Repository.CWork2024983.Atelier1.Cnc3' does match the specified value.
02:15.878	Info	Validation	Validating AttributeEqual (RawText='Cnc-4') on item 'CWork2024983.Atelier1.Cnc4'.
02:16.699	Success	Validation	Attribute 'RawText' of element for item 'Sprint_9_8_4Repository.CWork2024983.Atelier1.Cnc4' does match the specified value.

# • AddManualPrograms

0ms •

	Time	Level	Category	Message	
--	------	-------	----------	---------	--