

#### Sprint\_9\_8\_1\_For\_11423\_API\_Retour\_Prog Execution time Computer name Language 2024-04-25 9:20:14 AM DELPHI11 en-US Operating system Screen dimension Duration Windows 11 64bit 2.4m 1920x1080 Run configuration name Username TestRun User

Total warnings Total errors

0

0

#### **Table of Contents**

[SETUP]	2
■ InitCworkWlthPrgs3 (CworkTestLib)	2
■ InitNewWorkingInWindows (CworkTestLib)	2
■ NewWorkingDirServerAndAccess (CworkTestLib)	
■ CreateFilesToImport2 (CworkTestLib)	5
<ul><li>CreateFilesToImport2 (CworkTestLib)</li><li>StartCwork (CworkTestLib)</li></ul>	5
■ LogUser (CworkTestLib)	5
CreateNewCnc (CworkTestLib)	6
■ ImportPrgFromFaoFolder (CworkTestLib)	
<ul><li>QuitCworkWithMenu (CworkTestLib)</li></ul>	
StartCwork (CworkTestLib)	7
LogUser (CworkTestLib)	7
StopStartCworkService (CworkTestLib)	7
OuitCworkWithMenu (CworkTestLib)	۶

#### **Global Parameters:**

**Cwork:** C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe

CworkUsr: Administrateur

CworkPsw:

QuitPos: 11

CworkDir: C:\Program Files (x86)\Smcom Software\Cwork\bin

CworkTravail: C:\CworkTestAuto

CworkNbPrg: 1

CworkProcessId:

ComPC: ComPC

CApi: CApi

#### **SETUP**

2.4m

+

## InitCworkWlthPrgs3 (CworkTestLib)

1.9m

+

■ InitNewWorkingInWindows (CworkTestLib)

+ 5.82s

Time Level Category Message 00:00.229 Info UserCode Run RunProgramAndWait C:\Users\User\Documents\cwork\Cwork80\tst\TestCwork\Sprint-9  $\verb|_8_1\bin\Debug\\|.....\TestPrep\CleanCworkWorkingDir.bat|$ 

#### NewWorkingDirServerAndAccess (CworkTestLib)

43.8s

Time	Level	Category	Message
00:06.049	Info	Data	Current variable values:
			\$AppToRun = 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe', \$AppWorkingDir = 'C:\Program Files (x86)\Smcom Software\Cwork\bin', \$CworkWorkingDir = 'C:\CworkTestAuto'
00:06.091	Info	Application	Run application 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe' with arguments '/WIZARD' in normal mode.
00:06.329	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptDataDir' at Center.
00:08.635	Info	Keyboard	Key 'Ctrl+A' Press with focus on 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptDataDir'.
00:08.911	Info	Keyboard	Key sequence from variable '\$CworkWorkingDir' with focus on 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptDataDir'.

Oct   Oct				
00-14.750	00:09.714	Info	Delay	
Key sequence Smcom' with focus on 'CworkAssitantConfig AssistantDeConfigurationDeCWork.Panel3.0 ptSociety'.				Waiting for 5s.
CworkAssitantConfig AssistantDeConfigurationDeCWork.Panel3.0 ptSociety.	00:14.750	Info	Keyboard	. • ,
CworkAssitantConfig AssistantDeConfigurationDeCWork.Panel3.0 ptPartnerID* at 36:14.   Oc. 15.964   Info   Validation   Validating AttributeEqual (Text="Smcom") on item ("CworkAssitantConfig AssistantDeConfigurationDeCWork.Panel3.0 ptSociety1".     Oc. 16.333   Success   Validation   Attribute Text* of element for item ("CworkTestLibRepository.CworkAssitantConfig AssistantDeConfigurationDeCWork.Panel3.0 ptSociety1" does match the specified value.				'Cwork Assistant Config. Assistant De Configuration De CWork. Panel 3.0
C.WorkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.0 ptSociety1*.   October   Octobe	00:15.243	Info	Mouse	'Cwork Assistant Config. Assistant De Configuration De CWork. Panel 3. O
V         C'GworkTestLibRepository,CworkAssitantConfig,AssistantDeConfigurationDeCWork.Panel3.OptSociety1" does match the specified value.           00:16.472         Info         Mouse         Mouse Left Click item CworkAssitantConfig,AssistantDeConfigurationDeCWork.Panel3.B Next* at Center.           00:17.105         Info         Validation         Validating AttributeEqual (Text="Selectionner la fonction de votre ordinateur") on item "CworkAssitantConfig,StartWizardForm.SelectionnerLaFonctionDeV orteOrdina".           00:17.638         Success         Validation         Attribute "Text" of element for item "CworkTestLibRepository.CworkAssitantConfig,StartWizardForm.SelectionnerLaFonctionDeV orteOrdina" does match the specified value.           00:17.785         Info         Mouse         Select Server           Mouse Left Click item "CworkAssitantConfig,AssistantDeConfigurationDeCWork.Panel3.Bt nServeur" at Center.         Server selected           00:18.479         Info         Validation         Server selected           Validating Exists on item "CworkAssitantConfig,AssistantDeConfigurationDeCWork.Panel3.B Next".         Next".           00:18.678         Success         Validation         Element for item "BNext" does exist.           00:19.294         Info         Mouse         Mouse Left Click item "CworkAssitantConfig,AssistantDeConfigurationDeCWork.Panel3.B Next".           00:19.550         Success         Validation         Element for item "BNext" does exist.      <	00:15.964	Info	Validation	'Cwork Assistant Config. Assistant De Configuration De CWork. Panel 3.0
ComorkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.8 Next* at Center.         00:17.105       Info       Validation       Validating AttributeEqual (Text="Selectionner la fonction de votre ordinateur") on item ("CworkAssitantConfig.StartWizardForm.SelectionnerLaFonctionDeV otreOrdina".         00:17.638       Success       Validation       Attribute Text* of element for item ("CworkTestLibRepository.CworkAssitantConfig.StartWizardForm.SelectionnerLaFonctionDeVotreOrdina" does match the specified value.         00:17.785       Info       Mouse       Select Server         Mouse Left Click item ("CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.8t nServeur" at Center.       Validation       Server selected         Validation       Server selected       Validation Element for item 'BNext' does exist.         Vollation       Element for item 'BNext' does exist.         Validation       Info       Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.8 Next' at Center.         00:19.294       Info       Validation       Information server displayed 'Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.8 Next'.         00:19.550       Success       Validation       Element for item 'BNext' does exist.         Vol19.555       Info       Mouse       Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.8 Next'.         00:19.585       Info       Mouse       <		Success	Validation	'CworkTestLibRepository.CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.OptSociety1' does match the specified
ordinateur) on item 'CworkAssitantConfig.StartWizardForm.SelectionnerLaFonctionDeV otreOrdina*.  00:17.638 Success Validation Attribute 'Text' of element for item 'CworkAssitantConfig.StartWizardForm.Sel ectionnerLaFonctionDeVotreOrdina* does match the specified value.  00:17.785 Info Mouse Select Server  Mouse Left Click item 'CworkAssitantDeConfigurationDeCWork.Panel3.Bt nServeur* at Center.  00:18.479 Info Validation Server selected  Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.  00:18.678 Success Validation Element for item 'BNext' does exist.  ○ 00:18.709 Info Mouse Mouse Left Click item 'CworkAssitantDeConfigurationDeCWork.Panel3.B Next' at Center.  00:19.294 Info Validation Information server displayed  Validating Exists on item 'CworkAssitantDeConfigurationDeCWork.Panel3.B Next' at Center.  00:19.550 Success Validation Element for item 'BNext' does exist.  ○ 00:19.550 Info Mouse Mouse Left Click item 'CworkAssitantDeConfigurationDeCWork.Panel3.B Next'.  Doi:19.550 Success Validation Element for item 'BNext' does exist.  ○ 00:19.550 Info Mouse Mouse Left Click item 'CworkAssitantDeConfigurationDeCWork.Panel3.B Next'.  Oo:19.585 Info Mouse Mouse Left Click item 'CworkAssitantDeConfigurationDeCWork.Panel3.B	00:16.472	Info	Mouse	'Cwork Assistant Config. Assistant De Configuration De CWork. Panel 3.B
VeworkTestLibRepository.CworkAssitantConfig.StartWizardForm.Sel ectionnerLaFonctionDeVotreOrdina' does match the specified value.         00:17.785       Info       Mouse       Select Server         Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.Bt nServeur' at Center.       Oc.18.479       Info       Validation         00:18.479       Info       Validation       Server selected         Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.       Next'.         00:18.678       Success       Validation       Element for item 'BNext' does exist.         00:18.709       Info       Mouse       Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.         00:19.294       Info       Validation       Information server displayed Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.         00:19.550       Success       Validation       Element for item 'BNext' does exist.         00:19.585       Info       Mouse       Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B	00:17.105	Info	Validation	ordinateur') on item 'CworkAssitantConfig.StartWizardForm.SelectionnerLaFonctionDeV
Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.Bt nServeur' at Center.  O0:18.479 Info Validation Server selected  Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.  O0:18.678 Success Validation Element for item 'BNext' does exist.  O0:18.709 Info Mouse Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.  O0:19.294 Info Validation Information server displayed  Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.  O0:19.550 Success Validation Element for item 'BNext' does exist.  O0:19.585 Info Mouse Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B		Success	Validation	'CworkTestLibRepository.CworkAssitantConfig.StartWizardForm.Sel ectionnerLaFonctionDeVotreOrdina' does match the specified
'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.Bt nServeur' at Center.         00:18.479       Info       Validation       Server selected         Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.       Next'.         00:18.678       Success       Validation       Element for item 'BNext' does exist.         00:18.709       Info       Mouse       Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.         00:19.294       Info       Validation       Information server displayed         Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.       Next'.         00:19.550       Success       Validation       Element for item 'BNext' does exist.         00:19.585       Info       Mouse       Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B	00:17.785	Info	Mouse	Select Server
Validating Exists on item 'CworkAssistantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.         00:18.678       Success       Validation       Element for item 'BNext' does exist.         00:18.709       Info       Mouse       Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.         00:19.294       Info       Validation       Information server displayed Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.         00:19.550       Success       Validation       Element for item 'BNext' does exist.         00:19.585       Info       Mouse       Mouse Left Click item 'CworkAssitantDeConfigurationDeCWork.Panel3.B				'Cwork Assistant Config. Assistant De Configuration De CWork. Panel 3.Bt
'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.         00:18.678       Success       Validation       Element for item 'BNext' does exist.         00:18.709       Info       Mouse       Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.         00:19.294       Info       Validation       Information server displayed         Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.         00:19.550       Success       Validation       Element for item 'BNext' does exist.         00:19.585       Info       Mouse       Mouse Left Click item 'CworkAssitantDeConfigurationDeCWork.Panel3.B	00:18.479	Info	Validation	Server selected
<ul> <li>✓</li> <li>00:18.709 Info Mouse Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.</li> <li>00:19.294 Info Validation Information server displayed</li></ul>				'Cwork Assistant Config. Assistant De Configuration De CWork. Panel 3.B
'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.         00:19.294       Info       Validation       Information server displayed         Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.         00:19.550       Success       Validation       Element for item 'BNext' does exist.         00:19.585       Info       Mouse       Mouse Left Click item 'CworkAssitantDeConfigurationDeCWork.Panel3.B		Success	Validation	Element for item 'BNext' does exist.
Validating Exists on item         'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B         Next'.         00:19.550       Success         Validation       Element for item 'BNext' does exist.         00:19.585       Info         Mouse       Mouse Left Click item         'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B	00:18.709	Info	Mouse	'Cwork Assistant Config. Assistant De Configuration De CWork. Panel 3.B
'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.       00:19.550     Success     Validation     Element for item 'BNext' does exist.       ○     00:19.585     Info     Mouse     Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B	00:19.294	Info	Validation	Information server displayed
00:19.585 Info Mouse Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B				'Cwork Assistant Config. Assistant De Configuration De CWork. Panel 3.B
'Cwork Assistant Config. Assistant De Configuration De CWork. Panel 3. Bell and the configuration of the configu		Success	Validation	Element for item 'BNext' does exist.
	00:19.585	Info	Mouse	'Cwork Assistant Config. Assistant De Configuration De CWork. Panel 3.B

00:20.228	Info	Validation	Choix base displayed
			Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:20.494	Success	Validation	Element for item 'BNext' does exist.
00:20.523	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.
00:21.168	Info	Mouse	Choix attelier
			Mouse Left Click item 'CworkAssitantConfig.StartWizardForm.BAddSupervision' at Center.
00:22.104	Info	Keyboard	Enter name of workshop
			Key sequence 'Atelier1' with focus on 'None.TEdit'.
00:22.720	Info	Mouse	Mouse Left Click item 'None.ButtonOK' at 32;13.
00:23.331	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:23.545	Success	Validation	Element for item 'BNext' does exist.
00:23.564	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 0;0.
00:24.229	Info	Mouse	Choix profil
			Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.Pr ogStatusBox' at 391;17.
00:25.135	Info	Mouse	Mouse Left Click item 'None.FrenchMecaniqueGenerale' at 88;6.
00:25.606	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:25.940	Success	Validation	Element for item 'BNext' does exist.
00:26.005	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 47;13.
00:26.668	Info	Mouse	Choix mode DNC PROD
			Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.C bProfil' at 389;13.
00:27.605	Info	Mouse	Mouse Left Click item 'None.DNCPlusSuiviDeProduction' at Center.
00:28.105	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:28.367	Success	Validation	Element for item 'BNext' does exist.
00:28.396	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 44;13.

00:29.041	Info	Mouse	Choix type de démargae  Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.D emarrerAvecPageLogin' at 7;8.
00:29.948	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:30.200	Success	Validation	Element for item 'BNext' does exist.
00:30.241	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 49;12.
00:30.856	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Close'.
00:31.115	Success	Validation	Element for item 'BClose' does exist.
00:31.145	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Close' at Center.
00:31.764	Info	Wait	Waiting 30s to not exist. Associated repository item: 'CworkAssitantConfig.AssistantDeConfigurationDeCWork'
00:39.786	Info	Delay	Waiting for 10s.

203ms **∓** 

Time	Level	Category	Message
00:49.854	Info	UserCode	Run RunProgramAndWait C:\Users\User\Documents\cwork\Cwork80\tst\TestCwork\Sprint-9 _8_1\bin\Debug\\\\TestPrep\genfic2.bat

## StartCwork (CworkTestLib)

79ms **∓** 

Time	Level	Category	Message
00:50.053	Info	Data	Current variable values:
			\$AppToRun = 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe'
00:50.089	Info	Application	Run application with file name from variable \$AppToRun with arguments '/TEST' in normal mode.

# **O** ■ LogUser (CworkTestLib)

14.08s **T** 

Time	Level	Category	Message
00:50.134	Info	Data	Current variable values:
			\$User = 'Administrateur', \$UserPsw = ''

00:50.178	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ComboUser' at 281;7.
00:51.767	Info	Keyboard	Key sequence '{Down}' with focus on 'None'.
00:52.014	Info	Keyboard	Key sequence '{Return}' with focus on 'None'.
00:52.267	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.EdPassword' at Center.
00:52.730	Info	Keyboard	Key sequence from variable '\$UserPsw' with focus on 'CworkMainForm.OuvertureDeSessionCWork.EdPassword'.
00:53.013	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ElementBOk' at 17;20.
00:53.511	Info	Wait	Waiting 3m to exist. Associated repository item: 'CworkMainForm.Atelier1'
01:02.941	Info	Validation	Validating AttributeEqual (Text='Atelier1') on item 'CworkMainForm.Atelier1'.
01:04.086	Success	Validation	Attribute 'Text' of element for item 'CworkTestLibRepository.CworkMainForm.Atelier1' does match the specified value.

## **⊙** CreateNewCnc (CworkTestLib)

1.95s **↑** 

Time	Level	Category	Message
01:04.219	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.BAdd' at 75;14.
01:05.481	Info	Mouse	Mouse Left Click item 'AjoutDeCNCS.BAdd' at 19;10.

## **○ ImportPrgFromFaoFolder (CworkTestLib)**

44.97s

Time	Level	Category	Message
01:06.173	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.MenuItemFichier' at 29;11.
01:12.697	Info	Mouse	Mouse Left Click item 'CworkMainForm.Cwork.MenuItem1' at 64;16.
01:13.164	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.OptImportFolder' at 17;11.
01:14.137	Info	Keyboard	Key sequence 'C:\CworkTestAuto\ImportFAO' with focus on 'ImportationDunDocumentOuDunDossier.OptImportFolder'.
01:15.149	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.Button1' at 8;12.
01:15.926	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.Cnc1' at 15;8.
01:16.856	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.ButtonOK' at 44;13.
01:17.608	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.ElementBOk' at 92;14.
01:49.493	Info	Wait	Waiting 4m to not exist. Associated repository item: 'ImportationDunDocumentOuDunDossier'
01:49.534	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.StationsTiles' at 671;296.

## • QuitCworkWithMenu (CworkTestLib)

1.97s **∓** 

Time	Level	Category	Message
01:51.138	Info	Data	Current variable values:
			\$QuitItemNum = '11'
01:51.183	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.MenuItemFichier' at Center.
01:52.636	Info	Mouse	Mouse Left Click item 'CworkMainForm.Cwork.MenuItemQuit' at 58;14.

## StartCwork (CworkTestLib)

84ms

Time	Level	Category	Message
01:53.108	Info	Data	Current variable values:
			\$AppToRun = 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe'
01:53.150	Info	Application	Run application with file name from variable \$AppToRun with arguments '/TEST' in normal mode.

## **Q** LogUser (CworkTestLib)

14.16s

Time	Level	Category	Message
01:53.195	Info	Data	Current variable values:
			\$User = 'Administrateur', \$UserPsw = ''
01:53.240	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ComboUser' at 281;7.
01:54.918	Info	Keyboard	Key sequence '{Down}' with focus on 'None'.
01:55.161	Info	Keyboard	Key sequence '{Return}' with focus on 'None'.
01:55.408	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.EdPassword' at Center.
01:55.916	Info	Keyboard	Key sequence from variable '\$UserPsw' with focus on 'CworkMainForm.OuvertureDeSessionCWork.EdPassword'.
01:56.206	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ElementBOk' at 17;20.
01:56.668	Info	Wait	Waiting 3m to exist. Associated repository item: 'CworkMainForm.Atelier1'
02:06.137	Info	Validation	Validating AttributeEqual (Text='Atelier1') on item 'CworkMainForm.Atelier1'.
02:07.203	Success	Validation	Attribute 'Text' of element for item 'CworkTestLibRepository.CworkMainForm.Atelier1' does match the specified value.

## **⊙** StopStartCworkService (CworkTestLib)

demarage CAPI			
Time	Level	Category	Message
02:07.353	Info	Data	Current variable values:  \$CworkServiceName = 'CApi'
02:07.405	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.MenuItemOutils' at 23;10.
02:09.042	Info	Mouse	Mouse Left Click item 'CworkMainForm.Cwork.MenuItem11' at 61;15.
02:09.515	Info	Mouse	Mouse Left Click item 'GestionDesServeursEtMoteurs.ActionsSurMoteurs' at 56;10.
02:10.699	Info	Mouse	Stop  Mouse Left Click item 'GestionDesServeursEtMoteurs.BCStopCworkService' at 28;15.
02:11.798	Info	Wait	Waiting 30s for the attribute 'Enabled' to equal the specified value 'True'. Associated repository item: 'GestionDesServeursEtMoteurs.BStartCworkService'
02:12.435	Info	Mouse	Mouse Left Click item 'GestionDesServeursEtMoteurs.BStartCworkService' at 26;14.
02:13.450	Info	Validation	Validating AttributeEqual (Valid='True') on item 'GestionDesServeursEtMoteurs.BCStopCworkService'.
02:15.676	Success	Validation	Attribute 'Valid' of element for item 'CworkTestLibRepository.GestionDesServeursEtMoteurs.BCStopCw orkService' does match the specified value.
02:15.817	Info	Delay	Waiting for 5s.
02:20.882	Info	Mouse	Mouse Left Click item 'GestionDesServeursEtMoteurs.Valider' at 53;15.
02:21.790	Info	Delay	Waiting for 3s.

## QuitCworkWithMenu (CworkTestLib)

Category

Data

Mouse

Level

Info

Info

Time

02:24.845

02:24.910

2.01s

'CworkMainForm.CWork202195.MenuItemFichier' at Center.

02:26.387 Info Mouse Mouse Left Click item 'CworkMainForm.Cwork.MenuItemQuit' at 58;14.

Message

Current variable values:

\$QuitItemNum = '11'

Mouse Left Click item