

Sprint_9_8_4_For_12026_CreateMultipleDocs_SETUP_ONLY

Execution time Computer name Language 23/10/2024 09:30:34 DELPHI11 en-US Operating system Screen dimension Duration Windows 11 64bit 1920x1080 3.4m Run configuration name Username

Run configuration name Username TestRun User

Total warnings Total errors

0

1

Table of Contents

■ [SETUP]	2
■ InitCworkWIthPrgs3 (CworkTestLib)	2
■ InitNewWorkingInWindows (CworkTestLib)	2
NewWorkingDirServerAndAccess (CworkTestLib)	2
■ CreateFilesToImport2 (CworkTestLib)	5
CreateFilesToImport2 (CworkTestLib)StartCwork (CworkTestLib)	5
■ LogUser (CworkTestLib)	5
■ CreateNewCnc (CworkTestLib)	6
■ ImportPrgFromFaoFolder (CworkTestLib)	6
QuitCworkWithMenu (CworkTestLib)	7
StartCwork (CworkTestLib)	7
LogUser (CworkTestLib)	7
■ CreateThreeCNC	8
AddDocumentsOnThreeCNC	۶

Global Parameters:

Cwork: C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe

CworkUsr: Administrateur

CworkPsw:

QuitPos: 11

CworkDir: C:\Program Files (x86)\Smcom Software\Cwork\bin

CworkTravail: C:\CworkTestAuto

CworkNbPrg: 1

CworkProcessId:

CApi: CApi

Cnc-2: Cnc-2

PrgName: Prg1_2

AliasName: Prg1_2_ALIAS

SETUP

+ 3.4m

InitCworkWIthPrgs3 (CworkTestLib)

1.7m

+

InitNewWorkingInWindows (CworkTestLib)

819ms +

Time Level Category Message 00:00.247 Info UserCode Run RunProgramAndWait C:\Users\User\Documents\cwork\Cwork80\tst\TestCwork\Sprint-9 $\verb|_8_4\bin\Debug\\......\TestPrep\CleanCworkWorkingDir.bat|$

▶ NewWorkingDirServerAndAccess (CworkTestLib)

41.41s **→**

Time	Level	Category	Message
00:01.062	Info	Data	Current variable values:
			\$AppToRun = 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe', \$AppWorkingDir = 'C:\Program Files (x86)\Smcom Software\Cwork\bin', \$CworkWorkingDir = 'C:\CworkTestAuto'
00:01.124	Info	Application	Run application 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe' with arguments '/WIZARD' in normal mode.
00:01.358	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptDataDir' at Center.
00:03.608	Info	Keyboard	Key 'Ctrl+A' Press with focus on 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptDataDir'.

00:03.909	Info	Keyboard	Key sequence from variable '\$CworkWorkingDir' with focus on 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptDataDir'.
00:04.720	Info	Delay	wait empty compagny name
			Waiting for 5s.
00:09.780	Info	Keyboard	Enter compagny name
			Key sequence 'Smcom' with focus on 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptSociety'.
00:10.165	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptPartnerID' at 36;14.
00:10.952	Info	Validation	Validating AttributeEqual (Text='Smcom') on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptSociety1'.
00:11.373	Success	Validation	Attribute 'Text' of element for item 'CworkTestLibRepository.CworkAssitantConfig.AssistantDeConfigu rationDeCWork.Panel3.OptSociety1' does match the specified value.
00:11.501	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.
00:12.115	Info	Validation	Validating AttributeEqual (Text='Selectionner la fonction de votre ordinateur') on item 'CworkAssitantConfig.StartWizardForm.SelectionnerLaFonctionDeV otreOrdina'.
00:12.652	Success	Validation	Attribute 'Text' of element for item 'CworkTestLibRepository.CworkAssitantConfig.StartWizardForm.Sel ectionnerLaFonctionDeVotreOrdina' does match the specified value.
00:12.783	Info	Mouse	Select Server
			Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.Bt nServeur' at Center.
00:13.432	Info	Validation	Server selected
			Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:13.655	Success	Validation	Element for item 'BNext' does exist.
00:13.679	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.
00:14.325	Info	Validation	Information server displayed
			Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:14.554	Success	Validation	Element for item 'BNext' does exist.
00:14.585	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.

00:15.210	Info	Validation	Choix base displayed
			Validating Exists on item
			'Cwork Assistant Config. Assistant De Configuration De CWork. Panel 3. B Next'.
00:15.411	Success	Validation	Element for item 'BNext' does exist.
00:15.459	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.
00:16.106	Info	Mouse	Choix attelier
			Mouse Left Click item 'CworkAssitantConfig.StartWizardForm.BAddSupervision' at Center.
00:17.075	Info	Keyboard	Enter name of workshop
			Key sequence 'Atelier1' with focus on 'None.TEdit'.
00:17.671	Info	Mouse	Mouse Left Click item 'None.ButtonOK' at 32;13.
00:18.262	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:18.496	Success	Validation	Element for item 'BNext' does exist.
00:18.521	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 0;0.
00:19.168	Info	Mouse	Choix profil
			Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.Pr ogStatusBox' at 391;17.
00:20.010	Info	Mouse	Mouse Left Click item 'None.FrenchMecaniqueGenerale' at 88;6.
00:20.509	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:20.802	Success	Validation	Element for item 'BNext' does exist.
00:20.834	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 47;13.
00:21.451	Info	Mouse	Choix mode DNC PROD
			Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.C bProfil' at 389;13.
00:22.387	Info	Mouse	Mouse Left Click item 'None.DNCPlusSuiviDeProduction' at Center.
00:22.886	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:23.156	Success	Validation	Element for item 'BNext' does exist.
00:23.177	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 44;13.

00:23.826	Info	Mouse	Choix type de démargae Mouse Left Click item
			'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.D emarrerAvecPageLogin' at 7;8.
00:24.763	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:25.035	Success	Validation	Element for item 'BNext' does exist.
00:25.083	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 49;12.
00:25.736	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Close'.
00:25.959	Success	Validation	Element for item 'BClose' does exist.
00:25.989	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Close' at Center.
00:26.608	Info	Wait	Waiting 30s to not exist. Associated repository item: 'CworkAssitantConfig.AssistantDeConfigurationDeCWork'
00:32.422	Info	Delay	Waiting for 10s.

○ CreateFilesToImport2 (CworkTestLib)

202ms

Time	Level	Category	Message
00:42.476	Info	UserCode	Run RunProgramAndWait C:\Users\User\Documents\cwork\Cwork80\tst\TestCwork\Sprint-9 _8_4\bin\Debug\\\\TestPrep\genfic2.bat

StartCwork (CworkTestLib)

83ms **∓**

Time	Level	Category	Message
00:42.677	Info	Data	Current variable values:
			\$AppToRun = 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe'
00:42.715	Info	Application	Run application with file name from variable \$AppToRun with arguments '/TEST' in normal mode.

Q LogUser (CworkTestLib)

15.02s **→**

Time	Level	Category	Message
00:42.761	Info	Data	Current variable values:
			\$User = 'Administrateur', \$UserPsw = ''

00:42.806	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ComboUser' at 281;7.
00:44.460	Info	Keyboard	Key sequence '{Down}' with focus on 'None'.
00:44.696	Info	Keyboard	Key sequence '{Return}' with focus on 'None'.
00:44.938	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.EdPassword' at Center.
00:45.395	Info	Keyboard	Key sequence from variable '\$UserPsw' with focus on 'CworkMainForm.OuvertureDeSessionCWork.EdPassword'.
00:45.662	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ElementBOk' at 17;20.
00:46.138	Info	Wait	Waiting 3m to exist. Associated repository item: 'CworkMainForm.Atelier1'
00:56.268	Info	Validation	Validating AttributeEqual (Text='Atelier1') on item 'CworkMainForm.Atelier1'.
00:57.656	Success	Validation	Attribute 'Text' of element for item 'CworkTestLibRepository.CworkMainForm.Atelier1' does match the specified value.

⊙ CreateNewCnc (CworkTestLib)

2.1s **★**

Time	Level	Category	Message
00:57.786	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.BAdd' at 75;14.
00:59.199	Info	Mouse	Mouse Left Click item 'AjoutDeCNCS.BAdd' at 19;10.

○ ImportPrgFromFaoFolder (CworkTestLib)

41.65s

Time	Level	Category	Message
01:30.920	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.MenultemFichier' at 29;11.
01:32.668	Info	Mouse	Mouse Left Click item 'CworkMainForm.Cwork.MenuItem1' at 64;16.
01:33.138	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.OptStatus' at 157;15.
01:34.105	Info	Mouse	Mouse Left Click item 'List1000.VALIDE' at 19;2.
01:34.575	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.OptImportFolder' at 17;11.
01:35.330	Info	Keyboard	Key sequence 'C:\CworkTestAuto\ImportFAO' with focus on 'ImportationDunDocumentOuDunDossier.OptImportFolder'.
01:36.288	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.Button1' at 8;12.
01:37.106	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.Cnc1' at 15;8.
01:37.855	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.ButtonOK' at 44;13.
01:38.644	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.ElementBOk' at 92;14.

01:39.389	Info	Wait	Waiting 4m to not exist. Associated repository item: 'ImportationDunDocumentOuDunDossier'
01:39.832	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.StationsTiles' at 671;296.

• QuitCworkWithMenu (CworkTestLib)

2.19s **▼**

Time	Level	Category	Message
01:41.543	Info	Data	Current variable values:
			\$QuitItemNum = '11'
01:41.585	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.MenultemFichier' at Center.
01:43.296	Info	Mouse	Mouse Left Click item 'CworkMainForm.Cwork.MenuItemQuit' at 58;14.

StartCwork (CworkTestLib)

137ms

†

Time	Level	Category	Message
01:43.738	Info	Data	Current variable values:
			\$AppToRun = 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe'
01:43.775	Info	Application	Run application with file name from variable \$AppToRun with arguments '/TEST' in normal mode.

Q LogUser (CworkTestLib)

14.57s

+

Time	Level	Category	Message
01:43.877	Info	Data	Current variable values:
			\$User = 'Administrateur', \$UserPsw = ''
01:43.930	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ComboUser' at 281;7.
01:45.514	Info	Keyboard	Key sequence '{Down}' with focus on 'None'.
01:45.751	Info	Keyboard	Key sequence '{Return}' with focus on 'None'.
01:46.010	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.EdPassword' at Center.
01:46.481	Info	Keyboard	Key sequence from variable '\$UserPsw' with focus on 'CworkMainForm.OuvertureDeSessionCWork.EdPassword'.
01:46.781	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ElementBOk' at 17;20.
01:47.273	Info	Wait	Waiting 3m to exist. Associated repository item: 'CworkMainForm.Atelier1'
01:57.040	Info	Validation	Validating AttributeEqual (Text='Atelier1') on item 'CworkMainForm.Atelier1'.

01:58.301	Success	Validation	Attribute 'Text' of element for item 'CworkTestLibRepository.CworkMainForm.Atelier1' does match the specified value.

⊙ CreateThreeCNC

2.76s **★**

Time	Level	Category	Message
01:58.445	Info	Mouse	Mouse Left Click item 'CWork2024983.TAdvSmoothToggleButton1' at 28;32.
01:59.229	Info	Mouse	Mouse Left Click item 'CWork2024983.BAdd' at 69;22.
02:00.171	Info	Keyboard	Key sequence '{Back}3' with focus on 'AjoutDeCNCS.CNCCount'.
02:00.560	Info	Mouse	Mouse Left Click item 'AjoutDeCNCS.BAdd' at 48;15.

○ AddDocumentsOnThreeCNC

1.4m **▼**

Time	Level	Category	Message
02:01.209	Info	Mouse	Mouse Left Click item 'CWork2024983.TAdvSmoothToggleButton' at 27;41.
02:07.735	Info	Mouse	Mouse Left Click item 'CWork2024983.BNew' at 61;41.
02:09.297	Info	Mouse	Mouse Left Click item 'NouveauDocument.AQXDHOYA' at 25;30.
02:09.949	Info	Mouse	Mouse Left Click item 'NouveauDocument.ElementBOk' at 16;25.
02:10.699	Info	Mouse	Mouse Left Click item 'ProprietesDunDocument.TEditBtn' at 23;17.
02:11.823	Info	Keyboard	Key sequence 'prog1' with focus on 'ProprietesDunDocument.TEditBtn'.
02:12.332	Info	Mouse	Mouse Left Click item 'ProprietesDunDocument.Button' at 1;8.
02:13.074	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.Cnc1' at 19;9.
02:13.855	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.ButtonOK' at 37;7.
02:14.604	Info	Mouse	Mouse Left Click item 'ProprietesDunDocument.ElementBOK' at 40;11.
02:15.451	Info	Mouse	Mouse Left Click item 'CWork2024983.Prog1CNCA0EDITECnc1.BClose' at 101;16.
02:17.669	Info	Mouse	Mouse Left Click item 'CWork2024983.BNew' at 65;22.
02:18.484	Info	Mouse	Mouse Left Click item 'NouveauDocument.ProgrammeDusinage' at 9;6.
02:19.135	Info	Mouse	Mouse Left Click item 'NouveauDocument.ElementBOk' at 10;17.
02:19.822	Info	Mouse	Mouse Left Click item 'ProprietesDunDocument.TEditBtn' at 64;19.
02:20.950	Info	Keyboard	Key sequence 'prog2' with focus on 'ProprietesDunDocument.TEditBtn'.
02:21.427	Info	Mouse	Mouse Left Click item 'ProprietesDunDocument.Button' at 3;11.
02:22.110	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.Cnc2' at 12;7.
02:22.854	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.ButtonOK' at 19;4.
02:23.636	Info	Mouse	Mouse Left Click item 'ProprietesDunDocument.ElementBOK' at 36;4.
02:24.419	Info	Mouse	Mouse Left Down item 'CWork2024983.Prog1CNCA0EDITECnc1.BClose' at 66;23.

02:27.077	Info	Mouse	Mouse Left Up item 'CWork2024983.Prog1CNCA0EDITECnc1.BClose' at 72;29.
02:28.208	Info	Mouse	Mouse Left Click item 'CWork2024983.BNew' at 63;32.
02:29.074	Info	Mouse	Mouse Left Click item 'NouveauDocument.ProgrammeDusinage' at 31;4.
02:29.700	Info	Mouse	Mouse Left Click item 'NouveauDocument.ElementBOk' at 11;18.
02:30.417	Info	Mouse	Mouse Left Click item 'ProprietesDunDocument.TEditBtn' at 68;17.
02:31.542	Info	Keyboard	Key sequence 'prog3' with focus on 'ProprietesDunDocument.TEditBtn'.
02:31.998	Info	Mouse	Mouse Left Click item 'ProprietesDunDocument.Button' at 10;7.
02:32.668	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.Cnc3' at 19;4.
02:33.424	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.ButtonOK' at 20;18.
02:34.141	Info	Mouse	Mouse Left Click item 'CWork2024983.PartsView' at 735;487.
02:34.949	Info	Mouse	Mouse Left Click item 'CWork2024983.Prog1CNCA0EDITECnc1.BClose' at 37;40.
03:25.280	Error	Module	The test run has been aborted by the user.