

$Sprint_9_8_4_For_12026_CreateMultipleDocs_SETUP_ONLY$

Execution time

23/10/2024 10:30:12

Operating system

Windows 11 64bit

Run configuration name

Computer name

Language

en-US

Screen dimension

Duration

1920x1080

3m

Username

Run configuration name Username TestRun User

Total warnings Total errors

0

Table of Contents

[SETUP]	2
■ InitCworkWlthPrgs3 (CworkTestLib)	2
■ InitNewWorkingInWindows (CworkTestLib)	2
■ NewWorkingDirServerAndAccess (CworkTestLib)	
 CreateFilesTolmport2 (CworkTestLib) 	- 5
StartCwork (CworkTestLib)	5
■ LogUser (CworkTestLib)	6
CreateNewCnc (CworkTestLib)	6
■ ImportPrgFromFaoFolder (CworkTestLib)	6
QuitCworkWithMenu (CworkTestLib)	7
StartCwork (CworkTestLib)	7
■ LogUser (CworkTestLib)	7
■ Create3AdditionalCNC	8
 AddManualPrograms 	٩

Warnings occurred. For additional information see the report of the individual modules, please.

Global Para	meters:						
Cwork: C:\Progra	am Files (x86)\S	mcom Software\Cwor	k\bin\Cwork.exe				
CworkUsr: Admi	inistrateur						
CworkPsw:							
QuitPos: 11							
CworkDir: C:\Pro	ogram Files (x86)\Smcom Software\Cv	vork\bin				
CworkTravail: C:\CworkTestAuto							
CworkNbPrg: 1							
CworkProcessId	l :						
CApi: CApi							
Cnc-2: Cnc-2							
PrgName: Prg1_	_2						
AliasName: Prg1	1_2_ALIAS						
ModuleGroupA	рр:						
ModuleGroupRo	epTravail:						
ModuleGroupC	workDir:						
ModuleGroupnl	bFile:						
ModuleGroupA	ppld:						
ModuleGroupps	sw:						
ModuleGroupU	ser:						
AppToRun:							
AppWorkingDir	:						
CworkWorkingl	Dir:						
SETUP				3m	-		
■ InitCwor	kWIthPrgs3 (CworkTestLib)		1.9m	*		
)A/. 1.1 1.1	r	. (121-)				
⊙ InitNev	vWorkingInW	/indows (CworkTe	STLID)	5.98s	*		
Time	Level	Category	Message				
00:00.475	Info	UserCode	Run RunProgramAndWait C:\Users\User\Documents\cwo _8_4\bin\Debug\\\\TestPr				

○ NewWorkingDirServerAndAccess (CworkTestLib)

2

44.1s

1

Time	Level	Category	Message
00:06.442	Info	Data	Current variable values:
			\$AppToRun = 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe', \$AppWorkingDir = 'C:\Program Files (x86)\Smcom Software\Cwork\bin', \$CworkWorkingDir = 'C:\CworkTestAuto'
00:06.477	Info	Application	Run application 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe' with arguments '/WIZARD' in normal mode.
00:06.725	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptDataDir' at Center.
00:10.372	Info	Keyboard	Key 'Ctrl+A' Press with focus on 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptDataDir'.
00:10.665	Info	Keyboard	Key sequence from variable '\$CworkWorkingDir' with focus on 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptDataDir'.
00:11.447	Info	Delay	wait empty compagny name
			Waiting for 5s.
00:16.484	Info	Keyboard	Enter compagny name
			Key sequence 'Smcom' with focus on 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptSociety'.
00:16.950	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptPartnerlD' at 36;14.
00:17.711	Info	Validation	Validating AttributeEqual (Text='Smcom') on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.O ptSociety1'.
00:18.153	Success	Validation	Attribute 'Text' of element for item 'CworkTestLibRepository.CworkAssitantConfig.AssistantDeConfigu rationDeCWork.Panel3.OptSociety1' does match the specified value.
00:18.299	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.
00:18.971	Info	Validation	Validating AttributeEqual (Text='Selectionner la fonction de votre ordinateur') on item 'CworkAssitantConfig.StartWizardForm.SelectionnerLaFonctionDeV otreOrdina'.
00:19.532	Success	Validation	Attribute 'Text' of element for item 'CworkTestLibRepository.CworkAssitantConfig.StartWizardForm.Sel ectionnerLaFonctionDeVotreOrdina' does match the specified value.
00:19.679	Info	Mouse	Select Server
			Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.Bt nServeur' at Center.
00:20.368	Info	Validation	Server selected
			Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.

00:20.623	Success	Validation	Element for item 'BNext' does exist.
00:20.666	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.
00:21.336	Info	Validation	Information server displayed
			Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:21.624	Success	Validation	Element for item 'BNext' does exist.
00:21.664	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.
00:22.288	Info	Validation	Choix base displayed
			Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:22.579	Success	Validation	Element for item 'BNext' does exist.
00:22.629	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at Center.
00:23.275	Info	Mouse	Choix attelier
			Mouse Left Click item 'CworkAssitantConfig.StartWizardForm.BAddSupervision' at Center.
00:24.312	Info	Keyboard	Enter name of workshop
			Key sequence 'Atelier1' with focus on 'None.TEdit'.
00:24.915	Info	Mouse	Mouse Left Click item 'None.ButtonOK' at 32;13.
00:25.492	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:25.718	Success	Validation	Element for item 'BNext' does exist.
00:25.755	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 0;0.
00:26.398	Info	Mouse	Choix profil
			Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.Pr ogStatusBox' at 391;17.
00:27.306	Info	Mouse	Mouse Left Click item 'None.FrenchMecaniqueGenerale' at 88;6.
00:27.811	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:28.105	Success	Validation	Element for item 'BNext' does exist.

00:28.130	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 47;13.
00:28.845	Info	Mouse	Choix mode DNC PROD
			Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.C bProfil' at 389;13.
00:29.779	Info	Mouse	Mouse Left Click item 'None.DNCPlusSuiviDeProduction' at Center.
00:30.242	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:30.514	Success	Validation	Element for item 'BNext' does exist.
00:30.533	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 44;13.
00:31.153	Info	Mouse	Choix type de démargae
			Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.D emarrerAvecPageLogin' at 7;8.
00:32.121	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next'.
00:32.349	Success	Validation	Element for item 'BNext' does exist.
00:32.380	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Next' at 49;12.
00:33.026	Info	Validation	Validating Exists on item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Close'.
00:33.285	Success	Validation	Element for item 'BClose' does exist.
00:33.317	Info	Mouse	Mouse Left Click item 'CworkAssitantConfig.AssistantDeConfigurationDeCWork.Panel3.B Close' at Center.
00:33.995	Info	Wait	Waiting 30s to not exist. Associated repository item: 'CworkAssitantConfig.AssistantDeConfigurationDeCWork'
00:40.491	Info	Delay	Waiting for 10s.

○ CreateFilesToImport2 (CworkTestLib)

163ms

+

Time	Level	Category	Message
00:50.544	Info	UserCode	Run RunProgramAndWait C:\Users\User\Documents\cwork\Cwork80\tst\TestCwork\Sprint-9 _8_4\bin\Debug\\\\TestPrep\genfic2.bat

StartCwork (CworkTestLib)

92ms **∓**

Time	Level	Category	Message
00:50.709	Info	Data	Current variable values:
			\$AppToRun = 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe'
00:50.758	Info	Application	Run application with file name from variable \$AppToRun with arguments '/TEST' in normal mode.

O◀ LogUser (CworkTestLib)

15.09s

Time	Level	Category	Message
00:50.803	Info	Data	Current variable values:
			\$User = 'Administrateur', \$UserPsw = ''
00:50.849	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ComboUser' at 281;7.
00:52.525	Info	Keyboard	Key sequence '{Down}' with focus on 'None'.
00:52.767	Info	Keyboard	Key sequence '{Return}' with focus on 'None'.
00:53.034	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.EdPassword' at Center.
00:53.523	Info	Keyboard	Key sequence from variable '\$UserPsw' with focus on 'CworkMainForm.OuvertureDeSessionCWork.EdPassword'.
00:53.814	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ElementBOk' at 17;20.
00:54.277	Info	Wait	Waiting 3m to exist. Associated repository item: 'CworkMainForm.Atelier1'
01:04.413	Info	Validation	Validating AttributeEqual (Text='Atelier1') on item 'CworkMainForm.Atelier1'.
01:05.763	Success	Validation	Attribute 'Text' of element for item 'CworkTestLibRepository.CworkMainForm.Atelier1' does match the specified value.

⊙ CreateNewCnc (CworkTestLib)

Time	Level	Category	Message
01:05.893	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.BAdd' at 75;14.
01:07.371	Info	Mouse	Mouse Left Click item 'AjoutDeCNCS.BAdd' at 19;10.

○ ImportPrgFromFaoFolder (CworkTestLib)

41.93s **→**

Time	Level	Category	Message
01:39.181	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.MenuItemFichier' at 29;11.
01:40.868	Info	Mouse	Mouse Left Click item 'CworkMainForm.Cwork.MenuItem1' at 64;16.

01:41.370	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.OptStatus' at 157;15.
01:42.374	Info	Mouse	Mouse Left Click item 'List1000.VALIDE' at 19;2.
01:42.871	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.OptImportFolder' at 17;11.
01:43.711	Info	Keyboard	Key sequence 'C:\CworkTestAuto\ImportFAO' with focus on 'ImportationDunDocumentOuDunDossier.OptImportFolder'.
01:44.707	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.Button1' at 8;12.
01:45.498	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.Cnc1' at 15;8.
01:46.307	Info	Mouse	Mouse Left Click item 'SelectionnerUneCnc.ButtonOK' at 44;13.
01:47.034	Info	Mouse	Mouse Left Click item 'ImportationDunDocumentOuDunDossier.ElementBOk' at 92;14.
01:47.806	Info	Wait	Waiting 4m to not exist. Associated repository item: 'ImportationDunDocumentOuDunDossier'
01:48.216	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.StationsTiles' at 671;296.

• QuitCworkWithMenu (CworkTestLib)

2.22s

Time	Level	Category	Message
01:50.026	Info	Data	Current variable values:
			\$QuitItemNum = '11'
01:50.068	Info	Mouse	Mouse Left Click item 'CworkMainForm.CWork202195.MenuItemFichier' at Center.
01:51.775	Info	Mouse	Mouse Left Click item 'CworkMainForm.Cwork.MenuItemQuit' at 58;14.

StartCwork (CworkTestLib)

153ms **∓**

Time	Level	Category	Message
01:52.250	Info	Data	Current variable values:
			\$AppToRun = 'C:\Program Files (x86)\Smcom Software\Cwork\bin\Cwork.exe'
01:52.289	Info	Application	Run application with file name from variable \$AppToRun with arguments '/TEST' in normal mode.

Q LogUser (CworkTestLib)

14.99s

+

Time	Level	Category	Message
01:52.399	Info	Data	Current variable values:
			\$User = 'Administrateur', \$UserPsw = ''

01:54.184	Info	Keyboard	Key sequence '{Down}' with focus on 'None'.
01:54.425	Info	Keyboard	Key sequence '{Return}' with focus on 'None'.
01:54.676	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.EdPassword' at Center.
01:55.181	Info	Keyboard	Key sequence from variable '\$UserPsw' with focus on 'CworkMainForm.OuvertureDeSessionCWork.EdPassword'.
01:55.461	Info	Mouse	Mouse Left Click item 'CworkMainForm.OuvertureDeSessionCWork.ElementBOk' at 17;20.
01:55.932	Info	Wait	Waiting 3m to exist. Associated repository item: 'CworkMainForm.Atelier1'
02:05.907	Info	Validation	Validating AttributeEqual (Text='Atelier1') on item 'CworkMainForm.Atelier1'.
02:07.237	Success	Validation	Attribute 'Text' of element for item 'CworkTestLibRepository.CworkMainForm.Atelier1' does match the specified value.

○ Create3AdditionalCNC

11.28s **★**

Time	Level	Category	Message
02:07.400	Info	Mouse	Mouse Left Click item 'CWork2024983.BAdd' at 72;26.
02:08.493	Info	Mouse	Mouse Left Click item 'AjoutDeCNCS.CNCCount' at 11;10.
02:09.242	Info	Keyboard	Key sequence '{Back}3' with focus on 'AjoutDeCNCS.CNCCount'.
02:09.599	Info	Mouse	Mouse Left Click item 'AjoutDeCNCS.BAdd' at 39;13.
02:10.273	Info	Validation	Validating AttributeEqual (RawText='Cnc-2') on item 'CWork2024983.Atelier1.Cnc2'.
02:16.906	Success	Validation	Attribute 'RawText' of element for item 'Sprint_9_8_4Repository.CWork2024983.Atelier1.Cnc2' does match the specified value.
02:17.047	Info	Validation	Validating AttributeEqual (RawText='Cnc-3') on item 'CWork2024983.Atelier1.Cnc3'.
02:17.744	Success	Validation	Attribute 'RawText' of element for item 'Sprint_9_8_4Repository.CWork2024983.Atelier1.Cnc3' does match the specified value.
02:17.891	Info	Validation	Validating AttributeEqual (RawText='Cnc-4') on item 'CWork2024983.Atelier1.Cnc4'.
02:18.514	Success	Validation	Attribute 'RawText' of element for item 'Sprint_9_8_4Repository.CWork2024983.Atelier1.Cnc4' does match the specified value.

• AddManualPrograms

39.32s **↑**

Time	Level	Category	Message
02:18.680	Info	Mouse	Mouse Left Click item 'CWork2024983.Atelier1.Cnc1Cnc2Cnc3Cnc4DO0Pe' at 94;60.
02:19.806	Info	Mouse	Mouse Right Click item 'CWork2024983.Atelier1.Cnc1Cnc2Cnc3Cnc4DO0Pe' at 94;60.
02:20.869	Info	Mouse	Mouse Left Click item 'Cwork.Voir' at 27;14.
02:21.340	Info	Mouse	Mouse Left Click item 'CWork2024983.BNew' at 26;24.

02:22.814	Info	Mouse	Mouse Left Click item 'NouveauDocument.ProgrammeDusinage' at 18;11.
02:23.463	Info	Mouse	Mouse Left Click item 'NouveauDocument.ElementBOk' at 21;5.
02:24.182	Info	Mouse	Mouse Left Click item 'ProprietesDunDocument.TEditBtn' at 29;3.
02:25.342	Info	Keyboard	Key sequence 'prg3' with focus on 'ProprietesDunDocument.TEditBtn'.
02:25.810	Info	Mouse	Mouse Left Click item 'ProprietesDunDocument.ElementBOK' at 54;6.
02:26.651	Info	Mouse	Mouse Left Click item 'CWork2024983.Prog1CNCA0EDITECnc1.ColorMemo' at 9;22.
02:29.026	Info	Keyboard	Key sequence 'test programme cnc1' with focus on 'CWork2024983.Prog1CNCA0EDITECnc1.ColorMemo'.
02:29.992	Info	Mouse	Mouse Left Click item 'CWork2024983.Prog1CNCA0EDITECnc1.BSave' at 28;14.
02:30.899	Info	Mouse	Mouse Left Click item 'CWork2024983.Prog1CNCA0EDITECnc1.BClose' at 63;32.
02:31.775	Info	Mouse	Mouse Left Click item 'CWork2024983.TAdvSmoothToggleButton1' at 48;31.
02:32.462	Info	Mouse	Mouse Left Click item 'CWork2024983.TAdvSmoothToggleButton1' at 657;161.
02:32.870	Warn	Click	The mouse action was performed outside the boundaries of the assigned UI element.
02:33.273	Info	Mouse	Mouse Right Click item 'CWork2024983.Atelier1.RawTextDO0Percent1' at 29;36.
02:34.336	Info	Mouse	Mouse Left Click item 'Cwork.Voir' at 29;12.
02:34.851	Info	Mouse	Mouse Left Click item 'CWork2024983.BNew' at 12;39.
02:35.841	Info	Mouse	Mouse Left Click item 'NouveauDocument.AQXDHOYA' at 10;30.
02:36.494	Info	Mouse	Mouse Left Click item 'NouveauDocument.ElementBOk' at 17;18.
02:37.212	Info	Mouse	Mouse Left Click item 'ProprietesDunDocument.TEditBtn' at 64;7.
02:38.309	Info	Keyboard	Key sequence 'prg4' with focus on 'ProprietesDunDocument.TEditBtn'.
02:38.782	Info	Mouse	Mouse Left Click item 'ProprietesDunDocument.ElementBOK' at 61;7.
02:39.650	Info	Mouse	Mouse Left Click item 'CWork2024983.Prog1CNCA0EDITECnc1.ColorMemo' at 50;7.
02:41.680	Info	Keyboard	Key sequence 'test programme cnc2' with focus on 'CWork2024983.Prog1CNCA0EDITECnc1.ColorMemo'.
02:42.618	Info	Mouse	Mouse Left Click item 'CWork2024983.Prog1CNCA0EDITECnc1.BSave' at 50;26.
02:43.493	Info	Mouse	Mouse Left Click item 'CWork2024983.Prog1CNCA0EDITECnc1.BClose' at 53;37.
02:44.369	Info	Mouse	Mouse Left Click item 'CWork2024983.TAdvSmoothToggleButton1' at 40;27.
02:45.030	Info	Mouse	Mouse Left Click item 'CWork2024983.Atelier1.Cnc1Cnc2Cnc3Cnc4DO0Pe' at 803;49.
02:46.092	Info	Mouse	Mouse Right Click item 'CWork2024983.Atelier1.Cnc1Cnc2Cnc3Cnc4DO0Pe' at 803;49.
02:47.150	Info	Mouse	Mouse Left Click item 'Cwork.Voir' at 14;10.
02:47.652	Info	Mouse	Mouse Left Click item 'CWork2024983.BNew' at 71;54.
02:48.621	Info	Mouse	Mouse Left Click item 'NouveauDocument.ProgrammeDusinage' at 23;18.

02:49.249	Info	Mouse	Mouse Left Click item 'NouveauDocument.ElementBOk' at 14;19.
02:49.962	Info	Mouse	Mouse Left Click item 'ProprietesDunDocument.TEditBtn' at 54;19.
02:51.056	Info	Keyboard	Key sequence 'prg5' with focus on 'ProprietesDunDocument.TEditBtn'.
02:51.556	Info	Mouse	Mouse Left Click item 'ProprietesDunDocument.ElementBOK' at 44;22.
02:52.368	Info	Mouse	Mouse Left Click item 'CWork2024983.Prog1CNCA0EDITECnc1.ColorMemo' at 40;14.
02:54.621	Info	Keyboard	Key sequence 'test programme cnc3' with focus on 'CWork2024983.Prog1CNCA0EDITECnc1.ColorMemo'.
02:55.559	Info	Mouse	Mouse Left Click item 'CWork2024983.Prog1CNCA0EDITECnc1.BSave' at 44;33.
02:56.399	Info	Mouse	Mouse Left Click item 'CWork2024983.Prog1CNCA0EDITECnc1.BClose' at 38;14.
02:57.309	Info	Mouse	Mouse Left Click item 'CWork2024983.TAdvSmoothToggleButton1' at 17;32.