Repair Estimate

Vehicle: TN-07-AX-3921

Garage: Rajan Motors Service Centre
Address: 45, Industrial Road, Guindy, Chennai - 600032
Estimate Date: 17-Oct-2026
Customer: Arun Vijayan
Vehicle Reg: TN-07-AX-3921

S.No	Description	Type	Amount (Rs)
1	Front bumper -- replacement	Part + Labour	18,500
2	Front headlight assembly (RHS) -- replacement	Part + Labour	12,800
3	Bonnet panel -- dent repair and repaint	Labour + Paint	9,200
4	Radiator grille -- replacement	Part	4,500
5	Front fender (RHS) -- minor dent repair	Labour	3,500
6	Wheel alignment and balancing	Service	1,800
7	Painting -- front section (primer + topcoat)	Paint	6,500
		Sub-Total	**56,800**
		GST (18%)	**10,224**
		TOTAL	**67,024**

Authorised by: K. Rajan, Service Manager, Rajan Motors Service Centre