

Work Instruction for OHP

Do's

DOC NO. OMC/PRODN/OC/WI/03 ISSUE NO. 01 REV. NO. 00 DATE. 10/01/2018

- Operation and Rectification of breakdown in the OHP should be done under the supervision of authorized competent person.
- 2. Persons working in OHP should be properly trained.
- All machines are to be checked/ examined by competent person at the starting of the shift.
- 4. Once in every seven days all machine of OHP shall be examined by competent person and the result of such examination shall be recorded in bound paged book.
- 5. Once in every twenty four hours, the electrical parts of every machine of OHP should be examined by a responsible electrician.
- 6. Before starting of OHP the operator shall blow siren for three times and all persons working near the moving machine should take shelter at a safe places.
- 7. Following precaution shall be taken in all bunkers:-
 - (a) Work inside the bunker can be stated only after ensuring that the conveyor belt is kept stopped.
 - (b) Only experienced person should be allowed to work inside the bunker.
 - (c) All persons should use safety belt and fastened from top of the bunker while working inside bunker.
 - (d) Permanent ladder should be provided where feasible.
- 8. The standard of lighting in the OHP area should be proper.
- 9. The safety measures should be followed while working in the OHP.
- Prevention should be made for non formation and non deposition of dust at loading, discharges and transfer point.
- 11. Check visually for presence of persons in proximity of the belt before starting of it.
- 12. One Engineer/foreman shall be in-charge of all activities in OHP in each shift that shall be responsible for maintaining safety and that should be recorded accordingly.



Work Instruction for OHP

Don'ts

DOC NO.
OMC/PRODN/OC/WI/03
ISSUE NO. 01
REV. NO. 00
DATE. 10/01/2018

- 1. No person shall ride on conveyor belt. (Bridge or over bridge).
- 2. No cleaning under running belt shall be done.
- 3. No person shall be working without proper PPE.
- 4. No maintenance work shall be done without permit.
- 5. No person should wear loose dresses during working near moving machine
- 6. No machine shall be allowed to start until conformed that machine is OK
- Nobody is allowed to do any job like greasing, repair or cleaning near the moving machine.
- 8. No person is allowed to work in a bunker if the belt is in running condition
- 9. Nobody is allowed to do repair and shifting job in the belt in running condition.
- Before starting of crusher, the operator must ensure by personal inspection that nobody is working in the crusher.
- 11. During loading in to truck under the bunker, no person should be allowed to remain on the truck outside cabin.