

Experiment 1

Mansi Waliyal
19EE10039.

Verification of Overcurrent Relay characteristics -

3. Y.
Assessment
and

Observations:

IEEE MI (Moderately Inverse) and

VI (very inverse). curves

$\rightarrow TMS = 1.25 \rightarrow$ less deviation

between observed and calculated
data comparison:

$\rightarrow TMS = 0.7$, at high PSM, \rightarrow larger
deviation.

\rightarrow If there is increment in PSM
then time of operation even
increases.

• For both cases, operating time at
particular PSM is higher when
 $TSM = 0.25$ than 0.7.

{ Increase in TMS, increases
operation time }

• $TMS = 1.25$ at lower PSM, operation
time for MI is smaller than VI.
But as PSM increases, difference
becomes smaller.

- ! • Similar observation in $TMS = 0.7$
but smaller dimension.
- All are inverse initially and
approach definite minimum
operation time with PSM increasing.

4. To improve
Relay's
performances

- Numerical relay protection shares common function, may lead to common failure.
Thus, use backup relays
- Use externally-sourced transient interferences such that they don't affect conventional technology of numerical relay.
- Provide cyber security to relays to avoid hacking risk.

1. IEEE VI curve.

(b)

$$K = 19.61, \alpha = 2, L = 0.491$$

$$I_{pickup} = 1A \text{ (primary side)}$$

$$TMS = 1.25$$

$$\text{operating time} \Rightarrow t = TMS \left(\frac{K}{(I_A)^2 - 1} + L \right)$$

$$t = 1.25 \left(\frac{19.61}{1^2 - 1} + 0.491 \right)$$

Verify:

$$I_a = 4.5205 A$$

$$t_{on} = 1.707 s \text{ (tripping time)}$$


$$t_{cal} = 1.875 s$$

$t_{on} \neq t_{cal}$ thus, verified.

Manvi Uniyal
19EEE10039.

IEEE VI ($TMS = 1.25$)

* Experimental
Calculated



Mansi Uwiyal
195E10039

1.7 IEEE V/I curve.

(ii) $K = 19.61, \alpha = 2, L = 0.491$

$I_{\text{pickup}} = 1A, T_{MS} = 0.7$

$$t = 0.7 \left(\frac{19.61}{I^2 - 1} + 0.491 \right).$$

Verify: $I_a = 302063A$


$t_{\text{obs}} = 1.8229 \text{ s}$

$t_{\text{cal}} = 1.8228 \text{ s. } \{ \text{almost same.}$

Mansi Uniyal
IIEEE 10039

IEEE VI (TM5-0-7)

* Experimental
— Calculated



Mansi Uniyal
19EE10039.

10)

(iii)

IEEE M1 curve.

$$k = 0.0515, \alpha = 0.02, L = 0.114$$

$$I_{\text{pickup}} = I_A \text{ (primary side)}$$

$$TMS = 1.25$$

$$t = 1.25 \left(\frac{0.0515}{2} + 0.114 \right)$$

Verify:

$$I_a = 2.0538 \text{ A}$$

$$t_{\text{obs}} = 4.7783 \text{ s}$$


$$t_{\text{calc}} = 4.5828 \text{ s. } \} \text{ almost same.}$$

Mansi Singh

19EEE10039.

IEEE MI curve Tms 1.05

* Experimental
- Calculated.



Mansi Uniyal
19EEE 10039.

10>

(iv) IEEE MI-curve.

$$K = 0.0515, \alpha = 0.02, L = 0.114.$$
$$I_{\text{pickup}} = 1 \text{ A}, T_{MS} = 0.7.$$

$$t = 0.7 \left(\frac{0.0515 + 0.114}{I^{0.02}} \right).$$

Verify: $I_a = 4.6637 \text{ A}$

$$t_{\text{obs}} = 1.3339 \text{ s}$$


$$t_{\text{calc}} = 1.2325 \text{ s}$$

} almost same.

Operation time →

10EE10039



ICEE MI (TM=0.3)
* Experimented
— Calculated



5. >

Mansi Uniyal
19EF10039

R_B and R_C have CTs of 100:5. Max fault current at bus B = 800A. $I_{\text{pickup}} = 8\text{A}$ for both relays. R_B is set with $TMS = 0.1$ and R_C has $TMS = 0.3$. if time of coordination = 0.3s.



Mansi Uniyal
19EE10039.

for R_B ,

$$\text{max. fault current} = \frac{800}{(100/5)} = 40\text{A}.$$

$$TMS = 0.1$$

$$PBM = \frac{1}{I_{\text{pickup}}} = \frac{40}{8} = 5.$$

$$t = \left(\frac{|19.6| + 0.491}{5^2 - 1} \right) * 0.1 = 0.13085\text{s.}$$

trip time.

$$t_{\text{coordination}} = 0.3$$

for R_C :

$$t = 0.13085 + 0.3 = 0.43085\text{s.}$$

trip time

If R_B fails to break,
then $I_{\text{fault at C}} = 40\text{A}$.

$$PSM = 40/8 = 5.$$

$$0.43085 = TMS \left(\frac{|19.6| + 0.491}{5^2 - 1} \right)$$

$$TMS = 0.3294\text{s}$$


∴ TMS for $R_C > 0.3$, thus Setting is Wrong!
 $= 0.3294$

Experiment 1

Mansi Uniyal
19EE10039.

6.) 12.47kV distribution system, with Relay RB and Rc as IEEE Very Inverse(VI) curve and coordinated with time interval 0.3s. CTs for RB and Rc are of 100:5 and 200:5 respectively. Phase A to ground faults at F₁, F₂, F₃, with fault resistance of 9.2Ω.

Relays	I _{Pickup} (A)	TMS
RB	79	0.1
Rc	162	0.4



$$t = \frac{19.61}{(I/I_{\text{pickup}})^2 - 1} + 0.491 \quad \text{TMS}$$

Roll number: 19EE10039.

R_f: 9.2

Relay Fault at

Relays	F ₁	F ₂	F ₃
I (A)	151.9	179.1	170.8
t _{simulation} (s)	0.7766	35.4	0.583
t _{ref} (s)	0.7762	35.489	0.5828
Std curve		16.529	-
			8.7025