19	EE10039.	Past 2.	
	Ambient temp= Set point=25 NCWDE "M32DE DRG OU DI RIG, HIGH	F.INC"	
	DI RIG LOW DI RIG LOW DI RIG DI RIG DI RIG DX DD DVT DDRA, RIG	(RAMEND)	put
	DI RIG, OXFF DUT DDRD, RIG LDI RIG, OX87 DUT ADCSRA	4.0	O.
	LDI RIB, OX6 DUT ADMUX, R	10	
	READ: NOP SBI ADCSK	CA, ADSC.	

POLL_ADC:
NOP
SBIS ADCSRA, ADIP
RJMP POOL_ADC
8431 ADCSRA, ADIP

Mansi Uniyat 19 EE100 39. Add hysterisis to stop relay chattering move set proint up or down based on output state. else slow loop rate so output is only updated every few seconds.