


Dotted lines rotate around the z-axis




Pendulum

Motor Rotates the sensor and pendulum about the z-axis

PSU

Controller/Drivers



Low Power Source