FICTIONAL ASSESSMENT FIXTURE

Preliminary basement inspection

Reference and date

Incident IMG_003 / inspection INS-003 / 22 September 2026. This report concerns the flooded basement shown in the corresponding image.

Observed damage

Standing water affects the basement, including stored belongings and low wall surfaces. Severe water damage is visible. The basement is one affected area for the exercise.

Unresolved cause

The source of the water has not been established. A supply-pipe failure and external floodwater remain possible explanations. No policy rider or additional coverage document has been supplied. Do not infer the cause from a superficially similar historical claim.

Next action

Request evidence of the water source or refer the coverage question to an adjuster. A provisional repair assessment with clearly stated uncertainty is useful. Do not promise coverage or a settlement.

Synthetic training material. Not a real inspection, invoice, insurance decision or payment commitment.