



- Pressure transducers
- Linear flow front sensors

Defects



Mean

Std.dev.

$P_{defect}(x)$:

