

Objektnam e	Gerätemodell	Firmwareversi on	Adresse + Port	Geräteinstanz nr.	SW Version Applikation	Beschreibung	Subnetz maske	Router
00DB302	PXC3.E16A-2	v01.21	172.16.13.14	3148814	AAS-20:SU=SiUn;CPD=2025-07-24 11:14:16;	Automationsstation		
BNR03	PXG3.M-1	v01.21	172.16.13.1	2100225		PXG Router 03 Geb. C		
01DB302	PXC3.E16A-2	v01.21	172.16.13.24	3148824	AAS-20:SU=SiUn;CPD=2025-07-16 13:55:53;	Automationsstation		
01DB301	PXC3.E16A-2	v01.21	172.16.13.22	3148822	AAS-20:SU=SiUn;CPD=2025-07-16 14:34:28;	Automationsstation		
02DA301	PXC3.E75A-2	v01.21	172.16.13.31	3148831	AAS-20:SU=SiUn;CPD=2025-07-30 11:10:43;	Automationsstation		
02DB301	PXC3.E16A-2	v01.21	172.16.13.32	3148832	AAS-20:SU=SiUn;CPD=2025-05-20 23:11:44;	Automationsstation		
01DA303	PXC3.E75A-2	v01.21	172.16.13.25	3148825	AAS-20:SU=SiUn;CPD=2025-07-16 13:55:47;	Automationsstation		
02DB302	PXC3.E16A-2	v01.21	172.16.13.34	3148834	AAS-20:SU=SiUn;CPD=2025-05-20 23:12:13;	Automationsstation		
01DA302	PXC3.E75A-2	v01.21	172.16.13.23	3148823	AAS-20:SU=SiUn;CPD=2025-08-14 11:11:49;	Automationsstation		
02DA302	PXC3.E75A-2	v01.21	172.16.13.33	3148833	AAS-20:SU=SiUn;CPD=2025-07-28 13:58:40;	Automationsstation		
AS_C100 02PD310	PXC4.E16-2	02.21.194.29	172.16.13.54	681014	AAS-30:SU=SiUn;CPD=2025-07-29 12:23:42;	M-Bus Zähler 2.OG/3.OG		
00DA310	PXC3.E75A-2	v01.21	172.16.13.51	3148851	AAS-20:SU=SiUn;CPD=2025-07-30 10:41:35;	Automationsstation		
CP_B001	PXM40.E	02.21.194.25	172.16.15.15	681007	AAS-30:SU=SiUn;CPD=2024-11-11 09:51:14;	Control Point CP_B001.B		
BNR04	PXG3.M-1	v01.21	172.16.14.1	2101249		PXG Router 04 Geb D		
CP_B200	PXM40.E	02.21.194.25	172.16.15.24	681005	AAS-30:SU=SiUn;CPD=2024-11-08 07:35:30;	Control Point B200		
02DA303	PXC3.E75A-2	v01.21	172.16.13.35	3148835	AAS-20:SU=SiUn;CPD=2025-07-16 12:11:18;	Automationsstation		
BNR01	PXG3.M-1	v01.21	172.16.11.1	2098177		PXG Router 01 Geb. A		
BNR02	PXG3.M-1	v01.21	172.16.12.1	2099201		PXG Router 02 Geb. B		
AS_C100 02CENF310	PXC5.E003	02.21.194.29	172.16.13.55	681017	AAS-30:SU=SiUn;CPD=2025-09-24 12:43:22;	Automation station 05		

Objektnam e	Gerätemodell	Firmwareversi on	Adresse + Port	Geräteinstanz nr.	SW Version Applikation	Beschreibung	Subnetz maske	Router
BNR05	PXG3.M-1	v01.21	172.16.15.1	2098178		PXG Router 05 Primäranlagen		
03DA103	PXC3.E75A-2	v01.21	172.16.11.44	3146796	AAS-20:SU=SiUn;CPD=2025-07-16 08:25:51;	Automationsstation		
03DA202	PXC3.E75A-2	v01.21	172.16.12.43	3147819	AAS-20:SU=SiUn;CPD=2025-07-16 08:39:48;	Automationsstation		
BACnet-Edg e-Router-50 00	Connect X300/ X200,Connect Software	BER-1.5	172.16.15.252	5000	1.5.3	BACnet Edge Router 1.5.3		
00DB202	PXC3.E16A-2	v01.21	172.16.12.15	3147791	AAS-20:SU=SiUn;CPD=2025-05-20 22:27:50;	Automationsstation		
03DB101	PXC3.E16A-2	v01.21	172.16.11.42	3146794	AAS-20:SU=SiUn;CPD=2025-07-16 08:25:59;	Automationsstation		
02DA110	PXC3.E75A-2	v01.21	172.16.11.52	3146804	AAS-20:SU=SiUn;CPD=2025-07-30 09:45:18;	Automationsstation		
01DB401	PXC3.E16A-2	v01.21	172.16.14.22	3149846	AAS-20:SU=SiUn;CPD=2025-07-16 14:21:59;	Automationsstation		
01DA102	PXC3.E75A-2	v01.21	172.16.11.23	3146775	AAS-20:SU=SiUn;CPD=2025-07-16 13:17:17;	Automationsstation		
00DA101	PXC3.E75A-2	v01.21	172.16.11.11	3146763	AAS-20:SU=SiUn;CPD=2025-10-01 08:22:15;	Automationsstation		
00DB401	PXC3.E16A-2	v01.21	172.16.14.12	3149836	AAS-20:SU=SiUn;CPD=2025-05-21 09:26:01;	Automationsstation		
02DA103	PXC3.E75A-2	v01.21	172.16.11.34	3146786	AAS-20:SU=SiUn;CPD=2025-07-16 09:34:08;	Automationsstation		
00DB301	PXC3.E16A-2	v01.21	172.16.13.12	3148812	AAS-20:SU=SiUn;CPD=2025-05-20 22:28:17;	Automationsstation		
00DA110	PXC3.E75A-2	v01.21	172.16.11.51	3146803	AAS-20:SU=SiUn;CPD=2025-07-24 10:32:08;	Automationsstation		
00DB101	PXC3.E75A-2	v01.21	172.16.11.12	3146764	AAS-20:SU=SiUn;CPD=2025-07-24 10:32:11;	Automationsstation		
00DA410	PXC3.E75A-2	v01.21	172.16.14.51	3149875	AAS-20:SU=SiUn;CPD=2025-07-30 10:39:53;	Automationsstation		
00DB103	PXC3.E16A-2	v01.21	172.16.11.15	3146767	AAS-20:SU=SiUn;CPD=2025-07-24 10:32:11;	Automationsstation		

Objektnam e	Gerätemodell	Firmwareversi on	Adresse + Port	Geräteinstanz nr.	SW Version Applikation	Beschreibung	Subnetz maske	Router
02DA210	PXC3.E75A-2	v01.21	172.16.12.52	3147828	AAS-20:SU=SiUn;CPD=2025-07-30 09:44:26;	Automationsstation		
00DA404	PXC3.E75A-2	v01.21	172.16.14.14	3149838	AAS-20:SU=SiUn;CPD=2025-07-24 11:35:31;	Automationsstation		
00DB201	PXC3.E16A-2	v01.21	172.16.12.12	3147788	AAS-20:SU=SiUn;CPD=2025-05-20 22:27:21;	Automationsstation		
01DB101	PXC3.E16A-2	v01.21	172.16.11.22	3146774	AAS-20:SU=SiUn;CPD=2025-07-16 13:17:31;	Automationsstation		
02DB401	PXC3.E16A-2	v01.21	172.16.14.32	3149856	AAS-20:SU=SiUn;CPD=2025-05-20 23:12:42;	Automationsstation		
02DB101	PXC3.E16A-2	v01.21	172.16.11.32	3146784	AAS-20:SU=SiUn;CPD=2025-07-16 09:34:20;	Automationsstation		
02DB201	PXC3.E16A-2	v01.21	172.16.12.32	3147808	AAS-20:SU=SiUn;CPD=2025-05-20 23:11:12;	Automationsstation		
01DA403	PXC3.E75A-2	v01.21	172.16.14.25	3149849	AAS-20:SU=SiUn;CPD=2025-07-16 14:20:38;	Automationsstation		
01DA201	PXC3.E75A-2	v01.21	172.16.12.21	3147797	AAS-20:SU=SiUn;CPD=2025-07-16 13:34:22;	Automationsstation		
03DA201	PXC3.E75A-2	v01.21	172.16.12.41	3147817	AAS-20:SU=SiUn;CPD=2025-07-16 08:39:39;	Automationsstation		
01DB402	PXC3.E16A-2	v01.21	172.16.14.24	3149848	AAS-20:SU=SiUn;CPD=2025-07-16 14:21:50;	Automationsstation		
AS_B100 02PC210	PXC4.E16-2	02.21.194.29	172.16.12.53	681011	AAS-30:SU=SiUn;CPD=2025-04-16 13:02:58;	M-Bus Zähler EG/1.OG		
00DA401	PXC3.E75A-2	v01.21	172.16.14.11	3149835	AAS-20:SU=SiUn;CPD=2025-08-14 07:42:58;	Automationsstation		
AS_B100 02PD210	PXC4.E16-2	02.21.194.29	172.16.12.54	681012	AAS-30:SU=SiUn;CPD=2025-07-29 12:27:32;	M-Bus Zähler 2.OG/3.OG		
02DB103	PXC3.E16A-2	v01.21	172.16.11.35	3146787	AAS-20:SU=SiUn;CPD=2025-07-16 09:34:20;	Automationsstation		
01DB103	PXC3.E16A-2	v01.21	172.16.11.25	3146777	AAS-20:SU=SiUn;CPD=2025-07-16 13:17:31;	Automationsstation		
00DA203	PXC3.E75A-2	v01.21	172.16.12.16	3147792	AAS-20:SU=SiUn;CPD=2025-09-24 13:25:27;	Automationsstation		

Objektnam e	Gerätemodell	Firmwareversi on	Adresse + Port	Geräteinstanz nr.	SW Version Applikation	Beschreibung	Subnetz maske	Router
AS_D100 02PD410	PXC4.E16-2	02.22.233.24	172.16.14.54	681016	AAS-30:SU=SiUn;CPD=2025-07-29 12:18:15;	M-Bus Zähler 2.OG		
01DA202	PXC3.E75A-2	v01.21	172.16.12.23	3147799	AAS-20:SU=SiUn;CPD=2025-08-14 10:59:37;	Automationsstation		
00DA402	PXC3.E75A-2	v01.21	172.16.14.13	3149837	AAS-20:SU=SiUn;CPD=2025-07-24 11:34:45;	Automationsstation		
AS_B200	PXC7.E400M	02.22.233.20	172.16.15.21	681004	AAS-30:SU=SiUn;CPD=2025-09-26 07:22:43;	Automation station B200		
AS_B001.A	PXC7.E400M	02.22.233.20	172.16.15.13	681006	AAS-30:SU=SiUn;CPD=2025-09-25 10:41:47;	Automation station B001.A		
02DB402	PXC3.E16A-2	v01.21	172.16.14.34	3149858	AAS-20:SU=SiUn;CPD=2025-05-20 23:13:11;	Automationsstation		
AS_A200.2	PXC7.E400M	02.22.233.20	172.16.15.16	681003	AAS-30:SU=SiUn;CPD=2025-08-01 10:34:41;	Automation station A200.2		
AS_A200.1 B	PXC7.E400M	02.22.233.20	172.16.15.12	681002	AAS-30:SU=SiUn;CPD=2025-09-26 11:45:18;	Automation station A200.1B		
00DA303	PXC3.E75A-2	v01.21	172.16.13.15	3148815	AAS-20:SU=SiUn;CPD=2025-09-29 10:52:15;	Automationsstation		
AS_C100 02PC310	PXC4.E16-2	02.21.194.29	172.16.13.53	681013	AAS-30:SU=SiUn;CPD=2025-04-16 12:57:09;	M-Bus Zähler EG/1.OG		
01DA402	PXC3.E75A-2	v01.21	172.16.14.23	3149847	AAS-20:SU=SiUn;CPD=2025-07-30 11:43:31;	Automationsstation		
AS_B001.B	PXC4.E16	02.21.194.25	172.16.15.27	681008	AAS-30:SU=SiUn;CPD=2025-06-13 09:24:19;	Automation station AS_B001.B		
MS01	INSIGHT	FW=V5.10.204 / BACStack=V 1.17	172.16.14.141	1048577	INSIGHT Rel 5.1.204 (*Hotfix-0039-BL0204)	MS01		
02DA310	PXC3.E75A-2	v01.21	172.16.13.52	3148852	AAS-20:SU=SiUn;CPD=2025-07-30 09:44:03;	Automationsstation		
00DA202	PXC3.E75A-2	v01.21	172.16.12.14	3147790	AAS-20:SU=SiUn;CPD=2025-09-24 13:14:35;	Automationsstation		
02DA101	PXC3.E75A-2	v01.21	172.16.11.31	3146783	AAS-20:SU=SiUn;CPD=2025-07-16 09:33:52;	Automationsstation		
00DA403	PXC3.E75A-2	v01.21	172.16.14.15	3149839	AAS-20:SU=SiUn;CPD=2025-05-20 22:13:31;	Automationsstation		

Objektnam e	Gerätemodell	Firmwareversi on	Adresse + Port	Geräteinstanz nr.	SW Version Applikation	Beschreibung	Subnetz maske	Router
AS_D100 02PC410	PXC4.E16-2	02.20.194.9	172.16.14.53	681015	AAS-30:SU=SiUn;CPD=2025-04-16 13:22:04;	M-Bus Zähler EG/1.OG		
02DA402	PXC3.E75A-2	v01.21	172.16.14.33	3149857	AAS-20:SU=SiUn;CPD=2025-09-29 10:02:45;	Automation station		
AS_A100 02PC110	PXC4.E16	02.21.194.29	172.16.11.53	681009	AAS-30:SU=SiUn;CPD=2025-04-16 13:05:03;	M-Bus Zähler EG/1.OG		
00DA103	PXC3.E75A-2	v01.21	172.16.11.14	3146766	AAS-20:SU=SiUn;CPD=2025-07-24 10:32:02;	Automationsstation		
00DA201	PXC3.E75A-2	v01.21	172.16.12.11	3147787	AAS-20:SU=SiUn;CPD=2025-07-24 11:06:29;	Automationsstation		
03DB103	PXC3.E16A-2	v01.21	172.16.11.45	3146797	AAS-20:SU=SiUn;CPD=2025-07-16 08:25:59;	Automationsstation		
03DB201	PXC3.E16A-2	v01.21	172.16.12.42	3147818	AAS-20:SU=SiUn;CPD=2025-07-16 08:39:39;	Automationsstation		
01DA103	PXC3.E75A-2	v01.21	172.16.11.24	3146776	AAS-20:SU=SiUn;CPD=2025-07-16 13:17:22;	Automationsstation		
01DA101	PXC3.E75A-2	v01.21	172.16.11.21	3146673	AAS-20:SU=SiUn;CPD=2025-07-16 13:17:07;	Automationsstation		
02DA401	PXC3.E75A-2	v01.21	172.16.14.31	3149855	AAS-20:SU=SiUn;CPD=2025-05-20 22:56:48;	Automationsstation		
AS_A200.1 A	PXC7.E400M	02.22.233.24	172.16.15.11	681001	AAS-30:SU=SiUn;CPD=2025-09-26 07:34:02;	Automation station A200.1A		
01DB201	PXC3.E16A-2	v01.21	172.16.12.22	3147798	AAS-20:SU=SiUn;CPD=2025-07-16 13:34:21;	Automationsstation		
00DA210	PXC3.E75A-2	v01.21	172.16.12.51	3147827	AAS-20:SU=SiUn;CPD=2025-07-30 10:42:51;	Automationsstation		
00DA301	PXC3.E75A-2	v01.21	172.16.13.11	3148811	AAS-20:SU=SiUn;CPD=2025-09-29 10:40:18;	Automationsstation		
00DA302	PXC3.E75A-2	v01.21	172.16.13.13	3148813	AAS-20:SU=SiUn;CPD=2025-09-29 12:13:58;	Automationsstation		
01DA301	PXC3.E75A-2	v01.21	172.16.13.21	3148821	AAS-20:SU=SiUn;CPD=2025-07-16 14:34:29;	Automationsstation		
AS_A100 02PD110	PXC4.E16	02.21.194.29	172.16.11.54	681010	AAS-30:SU=SiUn;CPD=2025-07-29 12:28:45;	M-Bus Zähler 2.OG		

Objektnam e	Gerätemodell	Firmwareversi on	Adresse + Port	Geräteinstanz nr.	SW Version Applikation	Beschreibung	Subnetz maske	Router
03DA101	PXC3.E75A-2	v01.21	172.16.11.41	3146793	AAS-20:SU=SiUn;CPD=2025-07-16 08:25:38;	Automationsstation		
02DA202	PXC3.E75A-2	v01.21	172.16.12.33	3147809	AAS-20:SU=SiUn;CPD=2025-05-20 22:00:32;	Automationsstation		
03DA102	PXC3.E75A-2	v01.21	172.16.11.43	3146795	AAS-20:SU=SiUn;CPD=2025-07-16 08:25:46;	Automationsstation		
02DA410	PXC3.E75A-2	v01.21	172.16.14.52	3149876	AAS-20:SU=SiUn;CPD=2025-08-12 09:45:03;	Automationsstation		
00DA304	PXC3.E75A-2	v01.21	172.16.13.16	3148816	AAS-20:SU=SiUn;CPD=2025-06-04 14:33:56;	Automationsstation		
02DA201	PXC3.E75A-2	v01.21	172.16.12.31	3147807	AAS-20:SU=SiUn;CPD=2025-05-20 21:53:10;	Automationsstation		
00DA102	PXC3.E75A-2	v01.21	172.16.11.13	3146765	AAS-20:SU=SiUn;CPD=2025-09-25 06:26:19;	Automationsstation		
01DA401	PXC3.E75A-2	v01.21	172.16.14.21	3149845	AAS-20:SU=SiUn;CPD=2025-07-16 14:18:16;	Automationsstation		
02DA102	PXC3.E75A-2	v01.21	172.16.11.33	3146785	AAS-20:SU=SiUn;CPD=2025-07-16 09:34:00;	Automationsstation		