SYSCLK: SetAndMeasure



Description:

- In this example, program sets all internal clock.
- Using clock measurement counters, it measures some of internal clocks. The source clock of measuring counter is ECO. (It outputs ECO clock from EXT_CLK port via HF1. Therefore, if the source clock of HF1 is ECO, user can check the ECO frequency to verify the result. EXT_CLK port is used also as TDI, this means it is assumed the debugger is using SWD)
- It reads register value and recalculates the frequency.
- Measured and calculated frequencies are checked as they are close to expected value.

Target Device:

Traveo-II CYT2Bx devices

CPU Board:

CYTVII-B-E-1M-176-CPU Rev. C Board

SYSCLK: SetAndMeasure



Dependency:


None

> Expectation:

- Program counter should reach to infinite loop at the bottom of the main function.
- Output frequency from "SWEOE_TDI" is 16MHz (same as ECO)

SYSCLK: SetAndMeasure





Legend:

- Red block for power, debug (Mandatory)
- Yellow block for the example specific connections