SYSWDT: Warning Interrupt



Description:

 This example demonstrates the WDT warning interrupt functionality. As soon as the timer value overshoots the warn limit, interrupt is generated.

Target Device:

Traveo-II CYT2Bx devices

> CPU Board:

CYTVII-B-E-176-CPU BOARD REV.C (REV_C)

SYSWDT: Warning Interrupt



Dependency:


Any example could be copied to the main "src" based on the interested core

Expectation:

- Put a break point in the ISR "Wdt_Warn_IntrISR".
- Run the code and observe for the warning interrupt occurrence.
- LED gets inverted after the occurrence of the interrupt.

SYSWDT: Warning Interrupt





Legend:

- Red block for power, debug and USB (Mandatory)
- Yellow block for the example specific connections