


Real BESS cooling-fan fault — detected on data the model never saw



threshold

