

LHC-300 MECHANICAL LIGHT ASSEMBLY INSTRUCTIONS


OpenAg, MIT Media Lab




- Attach the LEDs in place on the aluminum plate using the acrylic LED alignment fixture
- Attach wires to LEDs, tape them down to aluminum plate so that the wires come out the "WIRES OUT" end of the plate




- Apply thermal grease to mating surface of heat sink
- Attach heat sink to aluminum plate with indicated hardware




 Position clear optics over each LED and position foam gasket over the optics, using the notched indicators for alignment




• This is what the assembly should look like at this point




- Attach 1/16th foam strip as shown, centered on plastic cover plate
- Attach plastic cover plate to assembly with indicated hardware






• This is what the assembly should look like at this point



- Attach the Mounting Arm Adapter Plate to the sheet metal enclosure with the indicated hardware.
- Attach the light assembly "sandwich" to the sheet metal enclosure with the indicated hardware



- Slip the top and bottom end-caps onto the assembly.
- Attach the fluidic connectors to the brass tubing, and fluidic valves to the pre-cut tubing, as shown.