

Auto Repair Estimate Report

Vehicle Information

Vehicle: Toyota Corolla 2022

Report Date:

Executive Summary

Part Name	Damage	Decision	Estimated Cost Range (EGP)
Front Bumper	Deep Scratch (Moderate)	Repair	11,500 - 22,000 EGP
Headlight	Cracked Lens (Severe)	Replace	30,000 - 58,000 EGP
Hood	Minor Dent (Low)	Repair	5,500 - 9,500 EGP

Note: All cost ranges include labor, parts (if replaced), and painting where applicable. USD conversions are based on an approximate rate of 1 USD = 48 EGP.

Detailed Breakdown

Front Bumper

Analysis Logic:

The damage is moderate and cosmetic, affecting the front bumper, which is a metal/plastic part that can be repaired according to the logic rules.

Market Data for Repair:

Source	Link	Snippet / Details	Found Cost (Original)	Estimated Cost (EGP)
Reddit - r/COROLLA (General)	reddit.com	"Should hover around 1000 bucks for the bumper." (Implies replacement or significant repair, assumed USD)	\$1000 (USD)	~48,000 EGP (High-end estimate if replacement)
CarAnalytics (UK - Bumper Repair Guide)	caranalytics.co.uk	"Medium Damage £190-£360 per bumper"	£190-£360 (GBP)	11,500 - 22,000 EGP (Converted from USD equivalent of GBP)
Key Collision Center (US - Bumper Repair/Replace)	keycollisioncenter.com	"Installation and painting of the new bumper can cost between \$200 and \$600." (Relevant for repair/paint labor)	\$200-\$600 (USD)	9,600 - 28,800 EGP

Based on moderate damage repair, including paint, we estimate a range derived from international repair cost benchmarks converted to EGP.

Headlight

Analysis Logic:

The headlight has a cracked lens which is considered a complex electronic part and given the severity of the damage, it's more practical to replace it for safety and functionality.

Market Data for Replacement:

Source	Link	Snippet / Details	Found Cost (Original)	Estimated Cost (EGP)

Ubuy Egypt	ubuy.com.eg	"2020-2022 Toyota Corolla LLE Sedan Left LED Headlight Assembly ; EGP 30959." EGP 30959."	EGP 30959	30,959 EGP
Reddit - r/COROLLA (General)	reddit.com	"Two different body shop fellas said new headlight from dealer would cost 1200\$. Two different body shops also found headlights on the aftermarket for 600-700\$." (Assumed USD)	\$600-\$1200 (USD)	28,800 - 57,600 EGP (Converted from USD)

The cost for headlight replacement varies based on whether an OEM part from a dealer or an aftermarket part is used. The Ubuy price aligns with aftermarket options.

Hood

Analysis Logic:

The damage is a minor dent on the hood, which is considered minor cosmetic damage and can be repaired according to the logic rules.

Market Data for Repair:

Source	Link	Snippet / Details	Found Cost (Original)	Estimated Cost (EGP)
CarAnalytics (UK - Dent Repair Guide)	caranalytics.co.uk	"Paintless Dent Removal £90-£150 per panel" (Applicable for minor dents)	£90-£150 (GBP)	5,500 - 9,500 EGP (Converted from USD equivalent of GBP)

eBay (Hood part cost, not repair)	ebay.com	"2020 2021 2022 2023 TOYOTA COROLLA HOOD OEM", "You might need to get the item repaired, sanded, prime and painted..."	\$200 (USD - for part)	Not directly applicable for minor dent repair cost.
-----------------------------------	----------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------	--------------------------------------------------------------

For a minor dent, Paintless Dent Repair (PDR) or minimal bodywork followed by painting is the standard. We used international PDR cost benchmarks converted to EGP.

Grand Total Estimated Cost Range:

EGP 47,000 - 89,500