

Auto Repair Estimate Report

Vehicle Information

- **Make:** Toyota
- **Model:** Corolla
- **Year:** 2022
- **Part Affected:** Front Bumper

Assessment

Based on the provided case details and damage assessment:

Decision: Repair

The recommendation is to **Repair** the front bumper. The damage is characterized as moderate cosmetic damage, impacting a metal/plastic part that is highly amenable to repair. This approach is typically more cost-effective and environmentally friendly than a full replacement when structural integrity is not compromised.

Cost Analysis

Our market data search provided various cost estimates for bumper repairs and replacements. Since most relevant repair costs were quoted in USD and the vehicle is in Egypt, we have converted these figures using an approximate exchange rate of **1 USD = 47.5 EGP**.

Key Repair Cost Findings:

- General estimates for "small cosmetic repairs" on front bumpers range from **\$150 to \$600 USD**. (Source: AutoZone.com)
- A specific reference suggested achieving "90 percent" repair for approximately **\$500 USD**. (Source: Facebook Group)

Given the "moderate cosmetic damage," we will focus on the repair cost range for such damage.

Category	Cost (USD)	Cost (EGP)
Minimum Repair Estimate	\$150	7,125 EGP
Maximum Repair Estimate	\$600	28,500 EGP
Average Repair Estimate	\$375	17,812.5 EGP

Note: These estimates cover labor and materials for repairing moderate cosmetic damage, including tasks like dent removal, plastic welding (if applicable), sanding, priming, and repainting. Actual costs may vary depending on the specific repair shop, the exact extent of the damage, and current market prices in Egypt. The USD to EGP exchange rate is an approximation and subject to fluctuations.

Recommendation

Based on the assessment of moderate cosmetic damage and the detailed cost analysis, we strongly recommend proceeding with a **repair of the existing front bumper** for your 2022 Toyota Corolla.

You can expect the repair cost to fall within the range of **7,125 EGP to 28,500 EGP**, with an average estimated cost around **17,812.5 EGP**.

For the best outcome, it is advisable to:

- Seek quotes from several reputable body shops specializing in plastic and bumper repairs.
- Discuss the extent of the damage and the proposed repair method with each shop.
- Ensure the estimate includes all necessary steps: repair, priming, paint matching, and clear coat application.