0.1

Summary of HMS survey. Pointing in the spectrometer coordinate system with $+{\rm X}$ downwards and $+{\rm Y}$ towards smaller angles.

Survey	Angle	Horizontal point (Y_{spec})	Vertical point (X_{spec})
C1792R	40.534	+3.45	+0.91
C1807R	40.013	+3.29	+0.94
C1809R	50.00	+2.92	+1.07

Summary of SHMS survey. Pointing in the spectrometer coordinate

Survey	Angle	Horizontal point (Y _{spec})	Vertical point (X_{spec})
C1796R	20.32	-0.57	-0.27
C1806R	15.02	-0.38	-1.16
C1808R	24.99	-0.43	-1.28
C1810R	39.94	-0.43	-1.25
C1812	15.01	-0.74	-1.34