



ICare Home 2 tonometer Stand + Cap/Guard



VIEW IN BROWSER

updated 8. 3. 2023 | published 8. 3. 2023

Summary

ICare Home 2 tonometer Stand + Cap/Guard

Healthcare > Home Medical Tools

A stand for safer storage, so the tonometer doesn't fall over easily. A cap to guard the measuring part of the tonometer from dust. Fits tightly.

The stand is a loose-ish fit, just right IMHO. Scaling by a few percents can make it looser/tighter - depends on the printer I guess.

I glued the stand in place with double sided tape. But you can also add some rubber feet

The cap is not sensitive dimension-vise. It fits with a probe inserted into the ICare, but the part is not intended to keep the probe in a sterile environment. As per the instructions - probes are single-use and should be disposed of after measuring.

You should probably disinfect the cap periodically.

Model files

stand.stl

cap.stl



stand.step



cap.step



base-v12.f3d

License **G**



This work is licensed under a Creative Commons (4.0 International License)

Attribution

- **≭** | Sharing without ATTRIBUTION
- ✓ | Remix Culture allowed
- ✓ | Commercial Use
- ✓ | Free Cultural Works
- ✓ | Meets Open Definition