SINKING CLOCK PCB LCD Correction 6/5/2024

My original drawings were correct. Six LEDs were mounted about 2 mm off center.

All LEDs shown in blue are in their correct position. Grey is where the misplaced ones are. Black is where their should be.

