SINKING CLOCK LED PCB Revision 3/10/2025

- 1) One screw hole is added.
- 2) The shape of this board has changed slightly. The angled bottom edge is different. The three affected LEDs should keep the same distance as before along this edge.
- 3) If it is not too complicated, please remove the VCC LED on the component side.
- 4) Move the traces further away from the PCB edges wherever possible.

