Managing Quality




© Copyright MAVO Institute

Be a yardstick of quality. Some people aren't used to an environment where excellence is expected.


Steve Jobs




Cause-and-Effect Diagram




Sample Control Chart – Process in Control



Control Chart - Out of Control




Control Chart - Trends






Control Chart - Process Run




Control Chart – Hugging the Center






Flow Charts

Process Flow Chart




System (Data) Flow Chart











MAV@Institute

Scatter Diagram Negative Correlation No Correlation No Correlation

© Copyright MAVO Institute