

RSLogix Micro Project Report



Processor Information

Processor Type: Bul.1763 MicroLogix 1100 Series B

Processor Name: UNTITLED

Total Memory Used: 225 Instruction Words Used - 58 Data Table Words Used

Total Memory Left: 6431 Instruction Words Left


Program Files: 5


Data Files: 9


Program ID: 5eb

Data File List

Name	Number	Type	Scope	Debug	Words	Elements	Last
OUTPUT	0	O	Global	No	15	5	O:4
INPUT	1	I	Global	No	21	7	I:6
STATUS	2	S	Global	No	0	66	S:65
BINARY	3	B	Global	No	2	2	B3:1
TIMER	4	T	Global	No	6	2	T4:1
COUNTER	5	C	Global	No	3	1	C5:0
CONTROL	6	R	Global	No	3	1	R6:0
INTEGER	7	N	Global	No	6	6	N7:5
FLOAT	8	F	Global	No	2	1	F8:0








0005

PROXY SENSOR STATE:
0 - Prox Off
(Conveyor Running)
1 - Prox On
(Conveyor Stopped)




CONVEYOR STOP BIT

B3:0
13

CONVEYOR STOP BIT

B3:0
13

PROXY SENSOR STATE:
0 - Prox Off
(Conveyor Running)
1 - Prox On
(Conveyor Stopped)



0006

PHOTOEYES LOGIC

RED PE BIT
B3:0
2

ONS
B3:0
14

PECAN HOPPER:
0 - RED PE OFF
1 - RED PE ON

MOV
Move
Source 1
1<
Dest N7:0
0<

RED PE BIT
B3:0
2

ONS
B3:1
3

PECAN HOPPER:
0 - RED PE OFF
1 - RED PE ON

MOV
Move
Source 0
0<
Dest N7:0
0<

BLUE PE BIT
B3:0
3

ONS
B3:0
15

WALNUT HOPPER:
0 - BLUE PE OFF
1 - BLUE PE ON

MOV
Move
Source 1
1<
Dest N7:3
0<


BLUE PE BIT
B3:0
3

ONS
B3:1
4

WALNUT HOPPER:
0 - BLUE PE OFF
1 - BLUE PE ON

MOV
Move
Source 0
0<
Dest N7:3
0<

0007






0008

NUT FILLING LOGIC

LEVEL SENSOR STATE:
0 - BOX NOT FULL
1 - BOX FULL

PECAN HOPPER:
0 - RED PE OFF
1 - RED PE ON


PROXY SENSOR STATE:
0 - Prox Off
(Conveyor Running)
1 - Prox On
(Conveyor Stopped)




PROXY SENSOR STATE:
0 - Prox Off
(Conveyor Running)
1 - Prox On
(Conveyor Stopped)

PECAN HOPPER BIT


B3:0
6



LEVEL SENSOR STATE:
0 - BOX NOT FULL
1 - BOX FULL



PECAN HOPPER:
0 - RED PE OFF
1 - RED PE ON



PECAN HOPPER BIT




B3:0
6

0009

LEVEL SENSOR STATE:
0 - BOX NOT FULL
1 - BOX FULL

WALNUT HOPPER:
0 - BLUE PE OFF
1 - BLUE PE ON


PROXY SENSOR STATE:
0 - Prox Off
(Conveyor Running)
1 - Prox On
(Conveyor Stopped)




PROXY SENSOR STATE:
0 - Prox Off
(Conveyor Running)
1 - Prox On
(Conveyor Stopped)

WALNUT HOPPER BIT


B3:0
5



LEVEL SENSOR STATE:
0 - BOX NOT FULL
1 - BOX FULL



WALNUT HOPPER:
0 - BLUE PE OFF
1 - BLUE PE ON



WALNUT HOPPER BIT

B3:0
5

0010

END