



### **Test Report**

Test Started: 2022-02-15 09:01:59

**Test Run Time:** 9.79s **Test Status:** Fail

Test Profile: C-C / SS Gen 1 / 3A handpiece

Dental Wings handpiece USB C-C cable test

### **Error Summary**

Cont Orientation Sanity Sig Int Missing SI Result

#### E-Marker

"D" Port "U" Port

SOP' Data	
SOP' Controller Not Found	

SOP' Data
SOP' Controller Not Found

### Continuity

Connector Orientation		
Port Connector Type		Orientation
"U" Port	USB 3.1 Type-C	Normal
"D" Port	USB 3.1 Type-C	Normal

V <sub>BUS</sub> Voltage Reference		
	Voltage	Valid Range
•	4.75 V	4.75 - 5.10 V

Power Shorts		
Wires		Shorts
•	V <sub>BUS</sub> to GND	None
•	CC to GND	None
•	CC to V <sub>BUS</sub>	None

Physical Wiring		
"D" Port Pin	"U" Port Pin	
DM1	No Connection	
DP1	No Connection	
DM2	No Connection	
DP2	No Connection	
SBU1	No Connection	

Functional Signals		
Wire Present		
CC	Present	
V <sub>CONN</sub>	Absent	
V <sub>CONN</sub> Thru	Absent	
SBU	Absent	
DP/DM1	Absent	

10.2.15.33/result/38

	"D" Port Pin	"U" Port Pin
	SBU2	No Connection
•	TX1	RX1
•	RX1	TX1

Wire	Present
DP/DM2	Absent
SOP'	Absent
SOP"	Absent
✓ TX1	Present
✓ RX1	Present
TX2	Absent
RX2	Absent

### **DC** Resistance


Powe	Power Wires		
	Wire	Measured Value	Maximum
•	GND	59.03 mΩ	83.00 mΩ
•	$V_{BUS}$	98.92 mΩ	167.00 mΩ


GND	GND Pins		
	Pin	Measured Value	Maximum
•	U-A1	8.36 mΩ	40.00 mΩ
•	U-A12	7.15 mΩ	40.00 mΩ
•	U-B1	6.05 mΩ	40.00 mΩ
•	U-B12	4.40 mΩ	40.00 mΩ
•	D-A1	5.98 mΩ	40.00 mΩ
•	D-A12	6.56 mΩ	40.00 mΩ
•	D-B1	5.53 mΩ	40.00 mΩ
•	D-B12	4.55 mΩ	40.00 mΩ

V <sub>BUS</sub>	V <sub>BUS</sub> Pins		
	Pin	Measured Value	Maximum
•	U-A9	10.38 mΩ	40.00 mΩ
•	U-B4	5.90 mΩ	40.00 mΩ
•	U-B9	5.22 mΩ	40.00 mΩ
•	U-A4	6.77 mΩ	40.00 mΩ
•	D-A9	6.66 mΩ	40.00 mΩ
•	D-B4	9.17 mΩ	40.00 mΩ
•	D-B9	6.88 mΩ	40.00 mΩ
•	D-A4	4.80 mΩ	40.00 mΩ

# Signal Integrity

10.2.15.33/result/38 2/3





## **Equipment**

Device Information	
Name	Value
Promira Serial Platform Serial Number	2416-629406
Advanced Cable Tester Serial Number	2468-197299
Hardware Version	0.93
Firmware Version	1.13
Web Version	1.13

Connector Test & Insertion Counts		
Port	Connector	Counts
Upstream	USB 3.1 Type-C	248
Downstream	USB 3.1 Type-C	217
Upstream Adapter	None	
Downstream Adapter	None	

Copyright © 2017 Total Phase, Inc. (https://www.totalphase.com/) All rights reserved.

10.2.15.33/result/38