SYNCHDMLC

FULL

HALF TARGET

HALF ISOCENTER

QUARTER TARGET

QUARTER ISOCENTER

ztip zl wtip zt MED2 wg zg wt zth zbh wl zts wts zbs wbs driving screw hole

zts zbs wts wbs zth zbh zt zg wt wg wl zl ztip wtip

ztip zl wtip wl zt zg wg wt zth zbh MED3 zts wts zbs wbs

zts zbs wts wbs zth zbh zt zg wt wg wl zl ztip wtip

ZMIN ZTHICK ztip zl wtip wl zt zg wg wt zth zbh zts wts zbs wbs

ZFOCUS(1) X

X cross–sections

LEAFGAP START ZMIN MED1 ZTHICK leaf 1 2 3 4 5 6 7 8 9 10 11 12 Z RMAX_CM

Top View

LEAFGAP X START RMAX_CM Y

Y cross–section

ENDTYPE=0

LEAFRADIUS Y zth zbh NEG POS ZTHICK/2 HOLEPOS RMAX_CM Z

ENDTYPE=1

ZFOCUS(2) Y ZMIN NEG POS HOLEPOS Z