Aurora: Module Relay x8

Specifications

Prepared for

Technical Staff

October 2026

Disclosure is prohibited

Revision History

Version	Date	Author	Description
0.1.0	2026-07-02	Martin Pellizzer	Starting version

Table of Contents

Revision History 2

Table of Contents 3

Executive Summary 4

Specifications 5

- Specification 1 . . . 5
  - Requirement . . . 5
  - Specifications . . . 5
- Specification 2 . . . 5
  - Requirement . . . 5
  - Specifications . . . 5

Executive Summary

Specifications

Specification 1

Requirement

The Relay Module shall execute relay-output commands received from Core

Specifications

The Relay Module must communicate with CORE via Modbus RTU protocol and RS485 standard. The Relay Module must execute only 0x04 commands on address zero-based 0x0000 (30001).

Specification 2

Requirement

The Relay Module shall provide Core output status

Specifications